


PLAN (END BENT 1)



ELEVATION (END BENT 1)

AS-BUILT REPAIR QUANTITY TABLE				
END BENT 1	QUANTITIES			
LIND DEINT I	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.
CAP	0.0	0.0		
CURTAIN WALL	3.6	1.8		
WING WALL	2 . 5	1.3		
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.
CAP	0.0	0.0		
CURTAIN WALL	0.0	0.0		
WING WALL	0.0	0.0		
EPOXY RESIN INJECTIO	LIN.FT.	LIN.FT.		
CAP	1 . 5			
CURTAIN WALL	4 . 5			
WING WALL	4.0			
EPOXY COATING		SQ.FT.	SQ.FT.	
CAP		618.5		

NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR "TYPICAL CAP AND COLUMN REPAIR DETAILS," SEE SHEET SD-01.






CONCRETE REPAIR AREA



ERI - EPOXY RESIN INJECTION

PROJECT NO. I-5831A MADISON COUNTY BRIDGE NO. 560547



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

END BENT 1

REVISIONS SHEET NO. S3-15 NO. BY: DATE: DATE: DOCUMENT NOT CONSIDERED 11

FINAL UNLESS ALL 22

SIGNATURES COMPLETED 22 TOTAL SHEETS 24

__ DATE : <u>04/2019</u> __ DATE : <u>02/2022</u> CL BRIGHT DRAWN BY : _ H.A. LOCKLEAR CHECKED BY : .