

#### AS-BUILT REPAIR QUANTITY TABLE DECK UNDERSIDE REPAIRS - SPANS 1 THRU 10 ESTIMATE ACTUAL VOLUME CU.FT. VOLUME SHOTCRETE REPAIRS SQ.FT. SQ.FT. CU.FT. UNDERSIDE OF DECK 29.6 14.8 OVERHANG 0.0 0.0 VOLUME CU.FT. VOLUME CONCRETE REPAIRS SQ.FT. CU.FT. SQ.FT. UNDERSIDE OF DECK 0.0 0.0 OVERHANG 0.0 0.0 ACTUAL ESTIMATE EPOXY RESIN INJECTION LIN.FT. LIN.FT. UNDERSIDE OF DECK 2.0 OVERHANG 0.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

#### NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

SHOTCRETE REPAIR

EPOXY RESIN INJECTION

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

ERI

#### UNDERSIDE PLAN (PILES NOT SHOWN FOR CLARITY)

1052'-5"(FILL FACE TO FILL FACE) 21'-0" 21'-0" 21'-0" 21'-0" 21'-0" SPAN 6 SPAN 8 SPAN 10 SPAN 7 SPAN 9 OVERHANG (TYP.) — OVERHANG (TYP.) 1.0 SF → 3.3 SF — \_\_1.0 SF — (£ @ BENT 5 — Q @ BENT 7 L @ BENT 6 P @ BENT 10 L @ BENT 8 - OVERHANG (TYP.) € @ BENT 9 — — 2.0 FT. ERI

> UNDERSIDE PLAN (PILES NOT SHOWN FOR CLARITY)

PROJECT NO. 15BPR.56 BEAUFORT \_\_\_ COUNTY

BRIDGE NO. 060028

SHEET 1 OF 5

SEAL 26445

TOREY NEW

DocuSigned by:

P. Korey Newton


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

SUPERSTRUCTURE

DECK UNDERSIDE REPAIR SPANS 1 THRU 10

4FFE39D1431B407... 01/27/2022 REVISIONS SHEET NO. NO. BY: DATE: S3-13 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS 78

DATE : 03/2021
DATE : 06/2021 S .T. SANDOR DRAWN BY : . W.C.SMITH CHECKED BY :



(PILES NOT SHOWN FOR CLARITY)

#### AS-BUILT REPAIR QUANTITY TABLE DECK UNDERSIDE REPAIRS - SPANS 11 THRU 20 ESTIMATE ACTUAL VOLUME CU.FT. VOLUME SHOTCRETE REPAIRS SQ.FT. SQ.FT. CU.FT. UNDERSIDE OF DECK 19.3 9.7 OVERHANG 6.0 3.0 AREA SQ.FT. VOLUME CU.FT. VOLUME CONCRETE REPAIRS SQ.FT. CU.FT. UNDERSIDE OF DECK 0.0 0.0 OVERHANG 0.0 0.0 ACTUAL ESTIMATE EPOXY RESIN INJECTION LIN.FT. LIN.FT. UNDERSIDE OF DECK 0.0 OVERHANG 0.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

#### NOTES

► (£ @ BENT 20

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

SHOTCRETE REPAIR

EPOXY RESIN INJECTION

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

ERI

1050'-6"(FILL FACE TO FILL FACE) 21'-0" 21'-0" 21'-0" SPAN 19 SPAN 18 SPAN 20

**1** € @ BENT 18

PROJECT NO. 15BPR.56 BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060028

SHEET 2 OF 5

SEAL 26445

NGINEER

--- DocuSigned by:

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

SUPERSTRUCTURE

DECK UNDERSIDE REPAIR SPANS 11 THRU 20

01/27/2022 SHEET NO. **REVISIONS** NO. BY: DATE: S3-14 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS 78

— € @ BENT 17 - OVERHANG (TYP.) 0.3 SF — 0.7 SF — P. Korey Newton UNDERSIDE PLAN (PILES NOT SHOWN FOR CLARITY)

► © @ BENT 16

-0.3 SF

21'-0"

SPAN 17

1.0 SF —

21'-0"

SPAN 16

\_\_\_ (£ @ BENT 15

— OVERHANG (TYP.)

S .T. SANDOR

W.C.SMITH


DRAWN BY : .

CHECKED BY :

\_\_ DATE : <u>03/2021</u>


DATE : 06/2021

- OVERHANG (TYP.)



# UNDERSIDE PLAN

(PILES NOT SHOWN FOR CLARITY)



#### UNDERSIDE PLAN

(PILES NOT SHOWN FOR CLARITY)

DECK UNDERSIDE REPAIRS - SPANS 21 THRU 24 AND SPANS 26-29 ESTIMATE ACTUAL VOLUME CU.FT. VOLUME SHOTCRETE REPAIRS SQ. FT. SQ.FT. 28.4 14.2 1.4 0.7

AS-BUILT REPAIR QUANTITY TABLE

CU.FT. UNDERSIDE OF DECK OVERHANG AREA SQ.FT. VOLUME CU.FT. VOLUME CONCRETE REPAIRS SQ.FT. CU.FT. UNDERSIDE OF DECK 0.0 0.0 OVERHANG 0.0 0.0 ESTIMATE ACTUAL EPOXY RESIN INJECTION LIN.FT. LIN.FT. UNDERSIDE OF DECK 0.0 OVERHANG 0.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

#### NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIR

ERI

EPOXY RESIN INJECTION

PROJECT NO. 15BPR.56 BEAUFORT BRIDGE NO. 060028

SHEET 3 OF 5

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

SUPERSTRUCTURE

DECK UNDERSIDE REPAIR SPANS 21 THRU 24 AND 26-29

01/27/2022 DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

SEAL 26445

NOINEER

P. Korey Newton

SHEET NO. **REVISIONS** NO. BY: DATE: S3-15 DATE: TOTAL SHEETS 78

1/24/2022 R:\Structures\Plans\Bridge\_060028\403\_029\_15BPR56\_SMU\_ DUR3\_015\_060028.dgn

\_\_ DATE : <u>03/2021</u>


DATE : 06/2021

S .T. SANDOR

W.C.SMITH

DRAWN BY : .

CHECKED BY :



# VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET. NOTES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST

AS-BUILT REPAIR QUANTITY TABLE

DECK UNDERSIDE REPAIRS - SPANS 30 THRU 39

SQ.FT.

40.7

1.9

SQ.FT.

0.0

0.0

ESTIMATE

ESTIMATE

LIN.FT.

8.0

0.0

VOLUME

CU.FT.

20.4

1.0

VOLUME CU.FT.

0.0

0.0

ACTUAL

ACTUAL

LIN.FT.

SQ.FT.

SQ.FT.

VOLUME

CU.FT.

VOLUME

CU.FT.

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIRS

CONCRETE REPAIRS

EPOXY RESIN INJECTION

UNDERSIDE OF DECK

UNDERSIDE OF DECK

UNDERSIDE OF DECK

OVERHANG

OVERHANG

OVERHANG

UNDERSIDE PLAN
(PILES NOT SHOWN FOR CLARITY)

1050'-6"(FILL FACE TO FILL FACE) 21'-0" 21'-0" 21'-0" 21'-0" 21'-0" SPAN 35 SPAN 36 SPAN 38 SPAN 37 SPAN 39 OVERHANG (TYP.) 1.5 SF — 3.0 SF — 1.5 SF ── 3.0 SF ─ 6.0 SF — \_\_ (£ @ BENT 34 — € @ BENT 36 — € @ BENT 37 — € @ BENT 38 L @ BENT 35 — OVERHANG (TYP.) \_\_\_ 1.1 SF **─**0.5 SF — 0.3 SF UNDERSIDE PLAN (PILES NOT SHOWN FOR CLARITY)

ERI EPOXY RESIN INJECTION

SHOTCRETE REPAIR

PROJECT NO. 15BPR.56

BEAUFORT COUNTY

BRIDGE NO. 060028

SHEET 4 OF 5

SEAL 26445

TOREY NEW

DocuSigned by:

P. Korey Newton

DEPARTMENT OF TRANSPORTATION
RALEIGH

SUPERSTRUCTURE

DECK UNDERSIDE REPAIR SPANS 30 THRU 39

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 AFFERSON SHEET NO.

REVISIONS SHEET NO.

BY: DATE: NO. BY: DATE: S3-16

3 SHEET NO.

SHEET NO.

TOTAL SHEETS

78

S .T. SANDOR


W.C.SMITH

DRAWN BY : .

CHECKED BY :

\_\_ DATE : <u>03/2021</u>

DATE : 06/2021



#### AS-BUILT REPAIR QUANTITY TABLE DECK UNDERSIDE REPAIRS - SPANS 40 THRU 49 ESTIMATE ACTUAL VOLUME VOLUME SHOTCRETE REPAIRS CU.FT. SQ.FT. SQ.FT. CU.FT. UNDERSIDE OF DECK 14.3 7.2 OVERHANG 1.6 0.8 VOLUME CU.FT. VOLUME CONCRETE REPAIRS SQ. FT. CU.FT. SQ.FT. UNDERSIDE OF DECK 0.0 0.0 OVERHANG 0.0 0.0 ACTUAL ESTIMATE EPOXY RESIN INJECTION LIN.FT. LIN.FT. UNDERSIDE OF DECK 0.0 OVERHANG 0.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2" CLEARANCE TO SAWCUT. SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

#### NOTES


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

## UNDERSIDE PLAN

(PILES NOT SHOWN FOR CLARITY)



SHOTCRETE REPAIR

ERI EPOXY RESIN INJECTION

PROJECT NO. 15BPR.56

BEAUFORT COUNTY

BRIDGE NO. 060028

SHEET 5 OF 5

SEAL 26445

NGINEE

P. Korey Newton

DEPARTMENT OF TRANSPORTATION
RALEIGH


SUPERSTRUCTURE

DECK UNDERSIDE REPAIR SPANS 40 THRU 49

| DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED | 2 | REVISIONS | SHEET NO. BY: DATE: STATE | SHEET NO. BY: DATE: SHEETS | TOTAL SHEETS | 78

W.C.SMITH

CHECKED BY :



AS-BUILT REPAIR QUANTITY TABLE QUANTITIES END BENTS 1 & 2 ESTIMATE ACTUAL AREA SQ.FT. VOLUME CU.FT. VOLUME SHOTCRETE REPAIRS SQ.FT. CU.FT. 0.0 0.0 CURTAIN WALL 0.0 0.0 WING WALL 0.0 0.0 VOLUME CU.FT. CONCRETE REPAIRS SQ. FT. SQ.FT. CU.FT. 0.0 0.0 CURTAIN WALL 0.0 0.0 WING WALL 0.0 0.0 EPOXY RESIN INJECTION LIN.FT. LIN.FT. 0.0 CURTAIN WALL 0.0 WING WALL 0.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

CONCRETE REPAIR

SHOTCRETE REPAIR

ERI EPOXY RESIN INJECTION

PROJECT NO. 15BPR.56 BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060028



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

SUBSTRUCTURE END BENT REPAIRS

P. Korey Newton

4FFE39D1431B407...

01/27/2022

SHEET NO. **REVISIONS** S3-18 DATE: DATE: BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS 78

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


EXISTING CONCRETE REPAIR J - JACKET

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE				
DENT 1		QUANT	ITIES	
BENT 1	EST	IMATE	АСТ	UAL
SHOTCRETE REPAIR	AREA VOLUME SF CF		AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.5	0.3		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
CONCRETE REPAIR				
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECTION		LF		LF
CAP		0.0		
COLUMN		1.5		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6" SPAN 1 SPAN 2 P2 P5 P3 P1 P4

BOTTOM OF CAP

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u> S. T. SANDOR DRAWN BY : . W.C.SMITH CHECKED BY :

BEAUFORT \_\_ COUNTY BRIDGE NO. 060028

SHEET 1 OF 48

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 1 REPAIR

> > S3-19

TOTAL SHEETS 78

P. Korey Newton

4FFE39D1431B407...
01/27/2022 REVISIONS SHEET NO. NO. BY: DATE: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.


CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE					
DENT O		QUANT	ITIES		
BENT 2	EST	IMATE	ACT	UAL	
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF	
CAP (VERTICAL FACE)	0.0	0.0			
CAP (HORIZONTAL FACE)	2.3	1.2			
COLUMN	0.0	0.0			
CONCRETE REPAIR					
CAP (VERTICAL FACE)	0.0	0.0			
CAP (HORIZONTAL FACE)	0.0	0.0			
COLUMN	0.0	0.0			
EPOXY RESIN INJECTION LF		LF		LF	
CAP		1.0			
COLUMN		0.0			

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.





BOTTOM OF CAP

 DRAWN BY :
 S. T. SANDOR
 DATE :
 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE :
 06/2021

BEAUFORT COUNTY
BRIDGE NO. 060028

SHEET 2 OF 48

STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION
RALEIGH

SUBSTRUCTURE
BENT 2 REPAIR

Docusigned by:

P. Korey Newton

4FFE39D1431B407...

01/27/2022

NO. CONSTDERED NO.

BENT 2 REPAIR

PROJECT NO. 15BPR.56

O1/27/2022REVISIONSSHEET NO.DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETEDNO. BY: DATE: NO. BY: DATE: S3-2013TOTAL SHEETS2478



REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

WITH THE ATTROVAL OF THE ENGINEER.

CONCRETE REPAIR

EXISTING


J - JACKET


SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE				
QUANTITIES				
EST	IMATE	ACTUAL		
AREA VOLUME SF CF		AREA SF	VOLUME CF	
0.0	0.0			
0.0	0.0			
0.0 0.0				
0.0	0.0			
0.0	0.0			
0.0	0.0			
EPOXY RESIN INJECTION			LF	
CAP				
	0.0			
	AREA SF  0.0  0.0  0.0  0.0  0.0  ION	OUANT     ESTIMATE	OUANTITIES  ESTIMATE ACT  AREA SF CF SF  0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.	

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.





BOTTOM OF CAP

PROJECT NO. 15BPR.56

BEAUFORT COUNTY

BRIDGE NO. 060028

SHEET 3 OF 48

DEPARTMENT OF TRANSPORTATION
RALEIGH

SUBSTRUCTURE
BENT 3 REPAIR

P. Korey Newton

4FFE39D1431B407...
01/27/2022

DOCUMENT NOT CONSIDERED
FINAL UNLESS ALL
SIGNATURES COMPLETED
2

SEAL 26445 TOREY NEW


REVISIONS

DATE: NO. BY: DATE: \$3-21

TOTAL SHEETS
78

 DRAWN BY :
 S. T. SANDOR
 DATE : 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE : 06/2021



REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


	EXISTING
CONCRETE REPAIR	J - JACKET

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE					
QUANTI				TIES	
BENT 5	EST	STIMATE AC		ACT	UAL
SHOTCRETE REPAIR	AREA SF	VOLUM CF	ME	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0			
CAP (HORIZONTAL FACE)	0.0	0.0			
COLUMN	0.5	0.3			
CONCRETE REPAIR					
CAP (VERTICAL FACE)	0.0	0.0			
CAP (HORIZONTAL FACE)	0.0	0.0			
COLUMN	0.0	0.0			
EPOXY RESIN INJECTION		LI	F		LF
CAP		0.	0		
COLUMN		0.	0		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6"

SPAN 5
SPAN 6
P1 P2 P3 P4 P5

BOTTOM OF CAP

 DRAWN BY :
 S. T. SANDOR
 DATE :
 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE :
 06/2021

Docusigned by:

P. Korey Newton

4FFE39D1431B407...

01/27/2022

BEAUFORT COUNTY
BRIDGE NO. 060028

SHEET 5 OF 48

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUBSTRUCTURE BENT 5 REPAIR

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS

SHEET NO.

STOTAL
SHEETS

78

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

		EXISTING
$\bigotimes$	CONCRETE REPAIR	J - JACKET

SHOTCRETE REPAIR


E - ENCAPSULATION


ERI EPOXY RESIN INJECTION

P - PILE

REPAIR QUANTITY TABLE				
QUANTITIES				
BENT 6	EST	ESTIMATE		TUAL
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.5	0.3		
CONCRETE REPAIR				
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECTION		LF		LF
CAP		0.0		
COLUMN		0.0		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.





BOTTOM OF CAP

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u> S. T. SANDOR DRAWN BY : . W.C.SMITH CHECKED BY :

\_\_\_ COUNTY BRIDGE NO. 060028 SHEET 6 OF 48 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH SEAL 26445 SUBSTRUCTURE BENT 6 REPAIR

P. Korey Newton 4FFE39D1431B407... 01/27/2022 DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS SHEET NO. DATE: S3-24 DATE: BY: TOTAL SHEETS 78

PROJECT NO. 15BPR.56

BEAUFORT

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


	EXISTING
CONCRETE REPAIR	J - JACKET

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE				
DENT 7		QUANT	ITIES	
BENT 7	EST	IMATE	АСТ	UAL
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
CONCRETE REPAIR				
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECTION		LF		LF
CAP		0.0		
COLUMN		0.0		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6"

SPAN 7
SPAN 8

P1 P2 P3 P4 P5

BOTTOM OF CAP

SEAL
26445

CONETA
DOCUSIGNED by:

P. Korey Newton

4FFE39D1431B407...

01/27/2022

SHEET 7 OF 48

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

\_\_ COUNTY

BEAUFORT

BRIDGE NO. 060028

SUBSTRUCTURE BENT 7 REPAIR

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED REVISIONS

O. BY: DATE: NO. BY: DATE: S3-25

TOTAL SHEETS

78

 DRAWN BY :
 S. T. SANDOR
 DATE :
 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE :
 06/2021

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

WITH THE APPROVAL OF THE ENGINEER.

CONCRETE REPAIR

EXISTING


J - JACKET

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE					
DENT 0		QUANT	ITIES		
BENT 8	EST	IMATE	ACT	UAL	
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF	
CAP (VERTICAL FACE)	17.3	8.7			
CAP (HORIZONTAL FACE)	0.7	0.4			
COLUMN	0.0	0.0			
CONCRETE REPAIR					
CAP (VERTICAL FACE)	0.0	0.0			
CAP (HORIZONTAL FACE)	0.0	0.0			
COLUMN	0.0	0.0			
EPOXY RESIN INJECTION		LF		LF	
CAP		0.0			
COLUMN		0.0			

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6"

SPAN 8
SPAN 9

P1 P2 P3 P4 P5

BOTTOM OF CAP

 DRAWN BY :
 S. T. SANDOR
 DATE :
 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE :
 06/2021

SEAL 26445

CONSERVICE NEW THREE TO THE TOPEY NEW THREE THREE TOPEY NEW THREE THREE

P. Korey Newton

PROJECT NO. 15BPR.56

BEAUFORT COUNTY

BRIDGE NO. 060028

SHEET 8 OF 48

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUBSTRUCTURE
BENT 8 REPAIR

SHEET NO.

S3-26

TOTAL SHEETS 78

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 REVISIONS

NO. BY: DATE: NO. BY:

1 3

1/24/2022 R:\Structures\Plans\Bridge\_060028\403\_051\_15BPR56\_SMU\_ B8\_026\_060028.dgn aygodfrey

ERI EPOXY RESIN INJECTION

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.


CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

TION
7

P - PILE

REPAIR QUANTITY TABLE					
				TIES	
BENT 9	EST	IMA	TE	ACTUAL	
SHOTCRETE REPAIR	AREA SF		VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0		0.0		
CAP (HORIZONTAL FACE)	0.0		0.0		
COLUMN	0.0		0.0		
CONCRETE REPAIR					
CAP (VERTICAL FACE)	0.0		0.0		
CAP (HORIZONTAL FACE)	0.0		0.0		
COLUMN	0.0		0.0		
EPOXY RESIN INJECTION			LF		LF
CAP			0.0		
COLUMN			0.0		
ALLIES IN CHART DEDDESENT ESTI	MATED DEDA	A TD	TOTALS A	ETED DEMOVA	I OF

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6"

SPAN 9
SPAN 10

P1 P2 P3 P4 P5

BOTTOM OF CAP

SEAL
26445

NCINEER OF WENT OF THE PROPERTY NEW TONO

DOCUSIGNED by:

P. Korey Newton

4FFE39D1431B407...
01/27/2022

BEAUFORT COUNTY
BRIDGE NO. 060028

SHEET 9 OF 48

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUBSTRUCTURE
BENT 9 REPAIR

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2

REVISIONS

DATE: NO. BY: DATE: S3-27

3 TOTAL SHEETS
78

 DRAWN BY :
 S. T. SANDOR
 DATE :
 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE :
 06/2021



ERI EPOXY RESIN INJECTION

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.


CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


P - PILE

	EXISTING
CONCRETE REPAIR	J - JACKET
SHOTCRETE REPAIR	E - ENCAPSULATION

REPAIR QUANTITY TABLE QUANTITIES BENT 10 ESTIMATE ACTUAL AREA VOLUME VOLUME SHOTCRETE REPAIR SF CAP (VERTICAL FACE) 0.0 0.0 CAP (HORIZONTAL FACE) 0.0 0.0 0.0 0.0 COLUMN CONCRETE REPAIR CAP (VERTICAL FACE) 0.0 0.0 CAP (HORIZONTAL FACE) 0.0 COLUMN 0.0 0.0 EPOXY RESIN INJECTION LF LF CAP 1.0 COLUMN

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.





BOTTOM OF CAP

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u> S. T. SANDOR DRAWN BY : . W.C.SMITH CHECKED BY :

SEAL 26445 P. Korey Newton

BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060028 SHEET 10 OF 48

PROJECT NO. 15BPR.56

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

SUBSTRUCTURE BENT 10 REPAIR

4FFE39D1431B407... 01/27/2022

REVISIONS SHEET NO.

TOTAL SHEETS 78

S3-28 DATE: DATE: BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


EXISTING CONCRETE REPAIR J - JACKET

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE						
DENT 11	QUANTITIES					
BENT 11	EST	IMATE	ACTUAL			
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
CAP (VERTICAL FACE)	1.5	0.8				
CAP (HORIZONTAL FACE)	0.0	0.0				
COLUMN	0.0	0.0				
CONCRETE REPAIR						
CAP (VERTICAL FACE)	0.0	0.0				
CAP (HORIZONTAL FACE)	0.0	0.0				
COLUMN	0.0					
EPOXY RESIN INJECT	LF		LF			
CAP		0.0				
COLUMN	0.0					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6" SPAN 11 SPAN 12 P2 P3 P5 P1 P4

BOTTOM OF CAP

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u> S. T. SANDOR DRAWN BY : . W.C.SMITH CHECKED BY :

P. Korey Newton

BEAUFORT \_\_ COUNTY BRIDGE NO. 060028

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 11 REPAIR

> > SHEET NO.


S3-29

TOTAL SHEETS 78

DATE:

4FFE39D1431B407... 01/27/2022 REVISIONS NO. BY: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

SHEET 11 OF 48



REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


EXISTING CONCRETE REPAIR J - JACKET

E - ENCAPSULATION SHOTCRETE REPAIR

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE					
DENT 17	QUA	NTITIES			
BENT 13	EST	IMATE		ACT	UAL
SHOTCRETE REPAIR	AREA SF	VOLUME CF	ARE SF		VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0			
CAP (HORIZONTAL FACE)	0.0				
COLUMN	0.0	0.0			
CONCRETE REPAIR					
CAP (VERTICAL FACE)	0.0	0.0			
CAP (HORIZONTAL FACE)	0.0	0.0			
COLUMN	0.0	0.0			
EPOXY RESIN INJECTION					LF
CAP		0.0			
COLUMN					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



SPAN 13 SPAN 14

P5

BEAUFORT \_\_ COUNTY

BRIDGE NO. 060028

SHEET 13 OF 48

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

SUBSTRUCTURE

P. Korey Newton 4FFE39D1431B407... 01/27/2022

BENT 13 REPAIR

REVISIONS SHEET NO. DATE: S3-31 NO. BY: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS 78

P1

P2

30'-6"

P3

BOTTOM OF CAP

P4

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

EXISTING J - JACKET

SHOTCRETE REPAIR

E - ENCAPSULATION


ERI EPOXY RESIN INJECTION


CONCRETE REPAIR

P - PILE

REPAIR QUANTITY TABLE				
DENT 1.4	QUANT	ITIES		
BENT 14	EST	IMATE	ACT	UAL
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
CONCRETE REPAIR				
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECT	LF		LF	
CAP	0.0			
COLUMN		0.0		
VALUES IN CHART REPRESENT ESTI	MATED REPA	AIR TOTALS	AFTER REMOVA	AL OF

UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.





BOTTOM OF CAP

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u> S. T. SANDOR DRAWN BY : . W.C.SMITH CHECKED BY :

PROJECT NO. 15BPR.56 BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060028 SHEET 14 OF 48 STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION
RALEIGH SEAL 26445 SUBSTRUCTURE

P. Korey Newton 4FFE39D1431B407... 01/27/2022

BENT 14 REPAIR

REVISIONS SHEET NO. DATE: S3-32 DATE: BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS 78

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


	EXISTING
CONCRETE REPAIR	J - JACKET

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE						
QUANT				ITIES		
BENT 15	EST	IMA	TE	ACTUAL		
SHOTCRETE REPAIR	AREA SF	,	VOLUME CF	AREA SF	VOLUME CF	
CAP (VERTICAL FACE)	0.0		0.0			
CAP (HORIZONTAL FACE)	0.0 0.0					
COLUMN	0.0 0.0					
CONCRETE REPAIR						
CAP (VERTICAL FACE)	0.0		0.0			
CAP (HORIZONTAL FACE)	0.0		0.0			
COLUMN	0.0		0.0			
EPOXY RESIN INJECTION			LF		LF	
CAP			0.0			
COLUMN			0.0			

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6"

SPAN 15
SPAN 16

P1 P2 P3 P4 P5

BOTTOM OF CAP

SEAL 26445

CONEEN NEW MENTINEER

SHEET 15 OF 48

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

BRIDGE NO. 060028

SUBSTRUCTURE
BENT 15 REPAIR

P. Korey. Newton

4FFE39D1431B407...
01/27/2022


DOCUMENT NOT CONSIDERED

FINAL UNLESS ALL

SIGNATURES COMPLETED

 DRAWN BY :
 S. T. SANDOR
 DATE :
 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE :
 06/2021



REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

CONCRETE REPAIR

EXISTING


J - JACKET

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE					
DENT 17	ITIES				
BENT 17	EST	IMATE	ACT	UAL	
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF	
CAP (VERTICAL FACE)	0.0	0.0			
CAP (HORIZONTAL FACE)	0.0	0.0			
COLUMN	0.0	0.0			
CONCRETE REPAIR					
CAP (VERTICAL FACE)	0.0	0.0			
CAP (HORIZONTAL FACE)	0.0	0.0			
COLUMN	LUMN 0.0				
EPOXY RESIN INJECT	LF		LF		
CAP		0.0			
COLUMN	0.0				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6"

SPAN 17
SPAN 18

P1 P2 P3 P4 P5

BOTTOM OF CAP

 DRAWN BY :
 S. T. SANDOR
 DATE :
 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE :
 06/2021

SHEET 17 OF 48

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

BRIDGE NO. 060028

SUBSTRUCTURE
BENT 17 REPAIR

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2

P. Korey Newton

REVISIONS
SHEET NO.

SHEET NO.

STOTAL
SHEETS

78



REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

EXISTING J - JACKET

SHOTCRETE REPAIR

CONCRETE REPAIR


E - ENCAPSULATION


ERI EPOXY RESIN INJECTION

P - PILE

REPAIR C	UANT:	ΙŢ	TY TA	BLE	
				ITIES	
BENT 18	EST	IΜΔ	TE	ACT	UAL
SHOTCRETE REPAIR	AREA SF		VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0		0.0		
CAP (HORIZONTAL FACE)	0.0		0.0		
COLUMN	0.0		0.0		
CONCRETE REPAIR					
CAP (VERTICAL FACE)	0.0		0.0		
CAP (HORIZONTAL FACE)	0.0		0.0		
COLUMN	0.0		0.0		
EPOXY RESIN INJECTION			LF		LF
CAP			0.0		
COLUMN			0.0		
/ALUES IN CHART REPRESENT ESTI	MATED REPA	۱R	TOTALS A	FTER REMOVA	AL OF

UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.





BOTTOM OF CAP

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u> S. T. SANDOR DRAWN BY : . W.C.SMITH CHECKED BY :

SEAL 26445 P. Korey Newton 4FFE39D1431B407... 01/27/2022

BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060028 SHEET 18 OF 48

PROJECT NO. 15BPR.56

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

SUBSTRUCTURE BENT 18 REPAIR

SHEET NO.

S3-36

TOTAL SHEETS 78

REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

NO. BY: DATE:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


	EXISTING
CONCRETE REPAIR	J - JACKET

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE				
DENT 10	ITIES			
BENT 19	EST	IMATE	ACT	UAL
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
CONCRETE REPAIR	CONCRETE REPAIR			
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECTION		LF		LF
CAP		0.0		
COLUMN		0.0		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6"

SPAN 19
SPAN 20

P1
P2
P3
P4
P5

BOTTOM OF CAP

20

BEAUFORT COUNTY
BRIDGE NO. 060028

SHEET 19 OF 48

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUBSTRUCTURE

BENT 19 REPAIR and by:

O1/27/2022REVISIONSSHEET NO.DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETEDNo. BY: DATE: No. BY: DATE: S3-3713TOTAL SHEETS2478

 DRAWN BY :
 S. T. SANDOR
 DATE :
 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE :
 06/2021

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

CONCRETE REPAIR

J - JACKET

EXISTING

SHOT


SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION

P - PILE

REPAIR QUANTITY TABLE						
DENT 00		QUANT]	ITIES			
BENT 20	EST	IMATE	<u>-</u>	ACTUAL		
SHOTCRETE REPAIR	AREA VOLUME SF CF			AREA SF	VOLUME CF	
CAP (VERTICAL FACE)	80.3	4	0.2			
CAP (HORIZONTAL FACE)	23.3	23.3 11.7				
COLUMN	0.0 0.0					
CONCRETE REPAIR						
CAP (VERTICAL FACE)	0.0		0.0			
CAP (HORIZONTAL FACE)	0.0		0.0			
COLUMN	0.0		0.0			
EPOXY RESIN INJECTION			LF		LF	
CAP			0.0			
COLUMN			0.0			

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



SOUTH END

SPAN 20 SPAN 21

P1 P2 2.5 SF P5

ELEVATION

(WEST SIDE)

BOTTOM OF CAP

 DRAWN BY :
 S. T. SANDOR
 DATE :
 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE :
 06/2021

NORTH END

SEAL 26445

ELEVATION

DEPARTMENT OF TRANSPORTATION
RALEIGH

SUBSTRUCTURE

BENT 20 REPAIR

SHEET 20 OF 48

Docusigned by:

P. Korey Newton

4FFE39D1431B407...

01/27/2022

DOCUMENT NOT CONSIDERED

FINAL UNLESS ALL

SIGNATURES COMPLETED

REVISIONS

NO. BY: DATE: NO. BY: DATE: S3-38

1 3 TOTAL SHEETS
78

PROJECT NO. 15BPR.56

\_\_ COUNTY

BEAUFORT

BRIDGE NO. 060028

1/24/2022 R:\Structures\Plans\Bridge\_060028\403\_075\_15BPR56\_SMU\_ B20\_038\_060028.dgn aygodfrey

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


		EXISTING	
X	CONCRETE REPAIR	J - JACKET	

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR C	UANT	ITY TA	BLE	
QUANTITIES				
BENT 21	EST	IMATE	ACT	UAL
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.3	0.2		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
CONCRETE REPAIR				
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECTION		LF		LF
CAP		0.0		
COLUMN		0.0		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6"

SPAN 21
SPAN 22

P1 P2 P3 P4 P5

BOTTOM OF CAP

 DRAWN BY :
 S. T. SANDOR
 DATE : 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE : 06/2021

SEAL 26445

CAROLARIAN

OF ESSION

SEAL

26445

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION
RALEIGH

\_\_ COUNTY

PROJECT NO. 15BPR.56

BEAUFORT

SHEET 21 OF 48

BRIDGE NO. 060028

SUBSTRUCTURE BENT 21 REPAIR

DocuSigned by:

P. Korey, Newton

4FFE39D1431B407...

01/27/2022

DOCUMENT NOT CONSIDERED

FINAL UNLESS ALL

SIGNATURES COMPLETED

REVISIONS

BY: DATE: NO. BY: DATE: \$3-39

TOTAL SHEETS

78

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

EXISTING J - JACKET

SHOTCRETE REPAIR

E - ENCAPSULATION


ERI EPOXY RESIN INJECTION


CONCRETE REPAIR

P - PILE

REPAIR C	UANT:	ΙŢ	Y TA	BLE	
DENT 00	QUANTITIES				
BENT 22	EST	IMA	TE	ACTUAL	
SHOTCRETE REPAIR	AREA SF		VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0		0.0		
CAP (HORIZONTAL FACE)	0.0		0.0		
COLUMN	0.0		0.0		
CONCRETE REPAIR					
CAP (VERTICAL FACE)	0.0		0.0		
CAP (HORIZONTAL FACE)	0.0		0.0		
COLUMN	0.0		0.0		
EPOXY RESIN INJECTION			LF		LF
CAP			0.0		
COLUMN			0.0		
/ALLIES IN CHART REPRESENT ESTI	MATED REPA	1 TR	ΤΟΤΔΙ S Δ	FTFR REMOVA	I OF

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.





BOTTOM OF CAP

\_ DATE : <u>05/2021</u> \_ DATE : <u>06/2021</u> S. T. SANDOR DRAWN BY : \_ W.C.SMITH CHECKED BY : .

PROJECT NO. 15BPR.56 BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060028 SHEET 22 OF 48 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

SEAL 26445 SUBSTRUCTURE BENT 22 REPAIR

4FFE39D1431B407... 01/27/2022 DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P. Korey Newton

REVISIONS SHEET NO. NO. BY: DATE: S3-40 TOTAL SHEETS 78

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


	EXISTING
CONCRETE REPAIR	J - JACKET

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE				
QUANTITIES				
BENT 23	EST	IMATE	ACT	UAL
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
CONCRETE REPAIR				
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECTION		LF		LF
CAP		0.0		
COLUMN		0.0		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6"

SPAN 23
SPAN 24

P1 P2 P3 P4 P5

BOTTOM OF CAP

 DRAWN BY :
 S. T. SANDOR
 DATE :
 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE :
 06/2021

SEAL
26445

Docusigned by:

P. Korey Newton

4FFE39D1431B407...

01/27/2022

BEAUFORT COUNTY
BRIDGE NO. 060028

SHEET 23 OF 48

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH


SUBSTRUCTURE
BENT 23 REPAIR


DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2

REVISIONS

DATE: NO. BY: DATE: S3-41

TOTAL SHEETS
78





REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


EXISTING CONCRETE REPAIR J - JACKET

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR C	UANT:	ITY TA	BLE	
QUANTITIES				
BENT 26	EST	IMATE	ACTUAL	
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.3	0.2		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
CONCRETE REPAIR				
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECTION		LF		LF
CAP		0.0		
COLUMN		0.0		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6" SPAN 26 SPAN 27 P2 P3 P5 P1 P4

BOTTOM OF CAP

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u> S. T. SANDOR DRAWN BY : . W.C.SMITH CHECKED BY :

BRIDGE NO. 060028

SHEET 26 OF 48 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

\_\_ COUNTY

BEAUFORT

SUBSTRUCTURE BENT 26 REPAIR

P. Korey Newton 4FFE39D1431B407... 01/27/2022 DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS SHEET NO. DATE: S3-44 NO. BY: DATE: TOTAL SHEETS 78

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

CONCRETE REPAIR


J - JACKET


SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE				
QUANTITIES				
BENT 27	EST	IMATE	AC.	TUAL
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
CONCRETE REPAIR				
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECTION		LF		LF
CAP		0.0		
COLUMN		0.0		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.





BOTTOM OF CAP

 DRAWN BY :
 S. T. SANDOR
 DATE : 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE : 06/2021

SEAL
26445

CONEENTOREY NEWTON

Docusigned by:

P. Korey Newton

4FFE39D1431B407...
01/27/2022

BEAUFORT COUNTY
BRIDGE NO. 060028

SHEET 27 OF 48

PROJECT NO. 15BPR.56

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION
RALEIGH

SUBSTRUCTURE
BENT 27 REPAIR

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2

REVISIONS SHEET NO.

BY: DATE: NO. BY: DATE: \$3-45

TOTAL SHEETS
78

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


	EXISTING
CONCRETE REPAIR	J - JACKET

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE				
QUANTITIES				
BENT 28	EST	IMATE	ACT	UAL
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
CONCRETE REPAIR				
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECTION		LF		LF
CAP		0.0		
COLUMN		0.0		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6"

SPAN 28
SPAN 29

P1 P2 P3 P4 P5

BOTTOM OF CAP

SEAL 26445

DEPARTMENT OF TRANSPORTATION
RALEIGH
SUBSTRUCTURE

BRIDGE NO. 060028

BENT 28 REPAIR

STATE OF NORTH CAROLINA

Document not considered by:

P. Korey Newton

4FFE39D1431B407...
01/27/2022

REVISIONS

NO. BY: DATE: NO. BY: DATE: S3-46

FINAL UNLESS ALL
SIGNATURES COMPLETED

P. Korey Newton

AFFE39D1431B407...

NO. BY: DATE: S3-46

TOTAL
SHEETS
78

SHEET 28 OF 48

1/24/2022 R:\Structures\Plans\Bridge\_060028\403\_091\_15BPR56\_SMU\_ B28\_046\_060028.dgn aygodfrey


\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u>

S. T. SANDOR

W.C.SMITH

DRAWN BY : .

CHECKED BY :



REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.


FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.


CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

	EXISTING
CONCRETE REPAIR	J - JACKET
SHOTCRETE REPAIR	E - ENCAPSULATION
ERI EPOXY RESIN INJECTION	P - PILE

REPAIR C	UANT	ΙΤ	Υ ΤΑ	BLE	
QUANTITIES					
BENT 30	EST	IMA	TE	ACT	UAL
SHOTCRETE REPAIR	AREA SF	,	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0		0.0		
CAP (HORIZONTAL FACE)	0.0		0.0		
COLUMN	0.0		0.0		
CONCRETE REPAIR					
CAP (VERTICAL FACE)	0.0		0.0		
CAP (HORIZONTAL FACE)	0.0		0.0		
COLUMN	0.0		0.0		
EPOXY RESIN INJECTION			LF		LF
CAP			0.0		
COLUMN			0.0		
ALLIES IN CHART REPRESENT ESTI	MATED REPA	\ TR	TOTALS	ETER REMOVA	J OF

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.





BOTTOM OF CAP

 DRAWN BY :
 S. T. SANDOR
 DATE :
 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE :
 06/2021

SEAL
26445

Docusigned by:

P. Korey Newton

4FFE39D1431B407...

01/27/2022

SHEET 30 OF 48

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

BRIDGE NO. 060028

SUBSTRUCTURE
BENT 30 REPAIR

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2

REVISIONS

DATE: NO. BY: DATE: S3-48

TOTAL SHEETS
78

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

EXISTING J - JACKET

SHOTCRETE REPAIR

E - ENCAPSULATION


ERI EPOXY RESIN INJECTION


CONCRETE REPAIR

P - PILE

REPAIR QUANTITY TABLE				
			ITIES	
BENT 31	EST	IMATE	АСТ	UAL
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
CONCRETE REPAIR				
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECTION				LF
CAP		0.0		
COLUMN		0.0		
ALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2" CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.





BOTTOM OF CAP

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u> S. T. SANDOR DRAWN BY : . W.C.SMITH CHECKED BY :

SEAL 26445 P. Korey Newton 4FFE39D1431B407... 01/27/2022

PROJECT NO. 15BPR.56 BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060028

SHEET 31 OF 48

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 31 REPAIR

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS SHEET NO. DATE: S3-49 DATE: BY: TOTAL SHEETS 78

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


	EXISTING
CONCRETE REPAIR	J - JACKET

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE					
QUANTITIES					
BENT 32	EST	IMATE		ACT	UAL
SHOTCRETE REPAIR	AREA SF	VOLUME CF	ARE SF		VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0			
CAP (HORIZONTAL FACE)	0.0	0.0			
COLUMN	0.0	0.0			
CONCRETE REPAIR					
CAP (VERTICAL FACE)	0.0	0.0			
CAP (HORIZONTAL FACE)	0.0	0.0			
COLUMN	0.0	0.0			
EPOXY RESIN INJECTION LF					LF
CAP		0.0			
COLUMN		0.0			

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6"

SPAN 32
SPAN 33

P1 P2 P3 P4 P5

BOTTOM OF CAP

1/24/2022 R:\Structures\Plans\Bridge\_060028\403\_099\_15BPR56\_SMU\_ B32\_050\_060028.dgn aygodfrey

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u>

S. T. SANDOR

W.C.SMITH

DRAWN BY : .

CHECKED BY :

BEAUFORT COUNTY
BRIDGE NO. 060028

SHEET 32 OF 48

STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION
RALEIGH

SEALUTION CAROLINA
CAROLINA
ESSIONALIA

SEALUTION CAROLINA
CA

SEAL SUBSTRUCTURE

SOURCE P. 100 A. 1

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED


P. Korey Newton

AFFE39D1431B407...

NO. BY: DATE: NO. BY: DATE: S3-50

TOTAL SHEETS

78



REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

CONCRETE REPAIR

EXISTING


J - JACKET

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE				
DENIT 74		QUANT	ITIES	
BENT 34	EST	IMATE	ACT	UAL
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
CONCRETE REPAIR				
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECTION LF LF			LF	
CAP		0.0		
COLUMN		0.0		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6"

SPAN 34
SPAN 35

P1 P2 P3 P4 P5

BOTTOM OF CAP

 DRAWN BY :
 S. T. SANDOR
 DATE :
 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE :
 06/2021

SEAL
26445

DocuSigned by:

P. Korey, Newton

BEAUFORT COUNTY
BRIDGE NO. 060028

SHEET 34 OF 48

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUBSTRUCTURE
BENT 34 REPAIR

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2

REVISIONS

BY: DATE: NO. BY: DATE: S3-52

3 TOTAL SHEETS
78



REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


		EXISTING
$\bigotimes$	CONCRETE REPAIR	J - JACKET
	SHOTCRETE REPAIR	E - ENCAPSULATION


ERI EPOXY RESIN INJECTION

P - PILE

REPAIR QUANTITY TABLE				
DENIT ZE		QUANT	ITIES	
BENT 35	EST	IMATE	ACT	UAL
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
CONCRETE REPAIR				
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECTION LF				LF
CAP		0.0		
COLUMN		0.0		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.





BOTTOM OF CAP

 DRAWN BY :
 S. T. SANDOR
 DATE :
 05/2021

 CHECKED BY :
 W. C. SMITH
 DATE :
 06/2021

SEAL
26445

Docusigned by:

P. Korey Newton

4FFE39D1431B407...

01/27/2022

BEAUFORT COUNTY
BRIDGE NO. 060028

SHEET 35 OF 48

PROJECT NO. 15BPR.56

DEPARTMENT OF TRANSPORTATION
RALEIGH

SUBSTRUCTURE
BENT 35 REPAIR

01/27/2022REVISIONSSHEET NO.DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETEDNo.BY:DATE:No.BY:DATE:S3-5313TOTAL SHEETS2478

CONCRETE REPAIR

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

J - JACKET


EXISTING

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR C	UANT	ITY TA	BLE	
1			ITIES	
BENT 36	EST	IMATE	AC <sup>-</sup>	TUAL
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
CONCRETE REPAIR				
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECT	ION	LF		LF
CAP		0.0		
COLUMN		0.0		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30′-6″ SPAN 36 SPAN 37 P2 P3 P5 P1 P4

BOTTOM OF CAP

SHEET 36 OF 48 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

BRIDGE NO. 060028

SUBSTRUCTURE BENT 36 REPAIR

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED


DocuSigned by:

P. Korey Newton

4FFE39D1431B407...

01/27/2022 REVISIONS SHEET NO. NO. BY: S3-54 DATE: DATE: TOTAL SHEETS 78

\_\_\_ DATE : 05/2021 \_\_\_ DATE : 06/2021 S.T.SANDOR W.C.SMITH DRAWN BY : . CHECKED BY :



ERI EPOXY RESIN INJECTION

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.


FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.


CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

	EXISTING
CONCRETE REPAIR	J - JACKET
SHOTCRETE REPAIR	E - ENCAPSULATION

P - PILE



VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6" SPAN 38 SPAN 39 P2 P3 P5 P1 P4

BOTTOM OF CAP

SHEET 38 OF 48 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 38 REPAIR

P. Korey Newton 4FFE39D1431B407... 01/27/2022 DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS SHEET NO. S3-56 DATE: DATE: BY:

TOTAL SHEETS 78

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u> 1/24/2022 R:\Structures\Plans\Bridge\_060028\403\_111\_15BPR56\_SMU\_ B38\_056\_060028.dgn aygodfrey

S. T. SANDOR

W.C.SMITH

DRAWN BY : .

CHECKED BY :

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

EXISTING J - JACKET

SHOTCRETE REPAIR

E - ENCAPSULATION


ERI EPOXY RESIN INJECTION


CONCRETE REPAIR

P - PILE

REPAIR QUANTITY TABLE				
DENT 70	QUANT	QUANTITIES		
BENT 39	EST:	IMATE	ACT	UAL
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
CONCRETE REPAIR				
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECTION		LF		LF
CAP		0.0		
COLUMN	0.0			
VALUES IN CHART REPRESENT ESTI	MATED REPA	AIR TOTALS A	AFTER REMOV <i>A</i>	AL OF

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2" CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.





BOTTOM OF CAP

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u> S. T. SANDOR DRAWN BY : . W.C.SMITH CHECKED BY :

SEAL 26445 P. Korey Newton 4FFE39D1431B407... 01/27/2022

PROJECT NO. 15BPR.56 BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060028

SHEET 39 OF 48

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

SUBSTRUCTURE BENT 39 REPAIR

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS SHEET NO. DATE: S3-57 DATE: BY: TOTAL SHEETS 78

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


EXISTING CONCRETE REPAIR J - JACKET

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE				
QUANTITIES				
BENT 40	EST	IMATE	ACT	UAL
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
CONCRETE REPAIR				
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL FACE)	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECTION LF				LF
CAP		0.0		
COLUMN		0.0		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6" SPAN 40 SPAN 41 P2 P3 P5 P1 P4

BOTTOM OF CAP

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u> S. T. SANDOR DRAWN BY : . W.C.SMITH CHECKED BY :

P. Korey Newton


BRIDGE NO. 060028 SHEET 40 OF 48 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

\_\_ COUNTY

SUBSTRUCTURE BENT 40 REPAIR

4FFE39D1431B407... 01/27/2022 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS SHEET NO. NO. BY: S3-58 DATE: TOTAL SHEETS 78



REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.


FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

	EXISTING
CONCRETE REPAIR	J - JACKET
SHOTCRETE REPAIR	E - ENCAPSULATION
ERI EPOXY RESIN INJECTION	P - PILE

REPAIR QUANTITY TABLE						
DENIT 40			QUANTI	TIES		
BENT 42	EST	IMAT	E	ACT	UAL	
SHOTCRETE REPAIR	AREA SF	V	OLUME CF	AREA SF	VOLUME CF	
CAP (VERTICAL FACE)	0.0		0.0			
CAP (HORIZONTAL FACE)	0.0		0.0			
COLUMN	0.0		0.0			
CONCRETE REPAIR						
CAP (VERTICAL FACE)	0.0		0.0			
CAP (HORIZONTAL FACE)	0.0		0.0			
COLUMN	0.0		0.0			
EPOXY RESIN INJECTION			LF		LF	
CAP			0.0			
COLUMN			0.0			
ALLIEC TAL CHART DEPRECEAT ECTT	AATED DEDA			CTCD DEMOVA	. 05	

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



 P3
 P4
 P5
 SPAN 42 SPAN 43

 BOTTOM OF CAP
 SPAN 43
 SPAN 43
 SPAN 43

SUBSTRUCTURE BENT 42 REPAIR

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION
RALEIGH

Docusigned by:

P. Korey Newton

4FFE39D1431B407...
01/27/2022

REVISIONS

SHEET NO.

BY: DATE: NO. BY: DATE: S3-60

FINAL UNLESS ALL
SIGNATURES COMPLETED

1 3 578

SHEET 42 OF 48

P2

P1

S. T. SANDOR

W.C.SMITH

DRAWN BY : .

CHECKED BY :

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u>



REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


EXISTING CONCRETE REPAIR J - JACKET


SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE						
QUANTITIES QUANTITIES						
BENT 43	EST:	IMATE	ACT	UAL		
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
CAP (VERTICAL FACE)	0.0	0.0				
CAP (HORIZONTAL FACE)	0.0	0.0				
COLUMN	3.0	1.5				
CONCRETE REPAIR						
CAP (VERTICAL FACE)	0.0	0.0				
CAP (HORIZONTAL FACE)	0.0	0.0				
COLUMN	0.0	0.0				
EPOXY RESIN INJECT	LF		LF			
CAP	0.0					
COLUMN		0.0				
VALUES IN CHART REPRESENT ESTI	MATED REPA	IR TOTALS	AFTER REMOVA	AL OF		

UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.





BOTTOM OF CAP

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u> S. T. SANDOR DRAWN BY : . W.C.SMITH CHECKED BY :

PROJECT NO. 15BPR.56 BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060028 SHEET 43 OF 48 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

SEAL 26445 SUBSTRUCTURE BENT 43 REPAIR

4FFE39D1431B407... 01/27/2022 REVISIONS SHEET NO. DATE: S3-61 NO. BY: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS 78

P. Korey Newton

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.


FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.


CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

	EXISTING
CONCRETE REPAIR	J - JACKET
SHOTCRETE REPAIR	E - ENCAPSULATION
ERI EPOXY RESIN INJECTION	P - PILE

REPAIR QUANTITY TABLE						
DENT 44	QUANT	ITIES				
BENT 44	EST	IMATE	ACT	UAL		
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
CAP (VERTICAL FACE)	0.0	0.0				
CAP (HORIZONTAL FACE)	0.0	0.0				
COLUMN	0.0	0.0				
CONCRETE REPAIR						
CAP (VERTICAL FACE)	0.0	0.0				
CAP (HORIZONTAL FACE)	0.0	0.0				
COLUMN	0.0	0.0				
EPOXY RESIN INJECTION		LF		LF		
CAP		0.0				
COLUMN		0.0				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.





BOTTOM OF CAP

SHE

OFESSION

SEAL

26445

Docusigned by:

P. Korey Newton

4FFE39D1431B407...

01/27/2022

SHEET 44 OF 48

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

BRIDGE NO. 060028

SUBSTRUCTURE
BENT 44 REPAIR

SHEET NO.

S3-62

TOTAL SHEETS 78

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 REVISIONS

NO. BY: DATE: NO. BY: DATE:

SIGNATURES COMPLETED 2

1/24/2022 R:\Structures\Plans\Bridge\_060028\403\_123\_15BPR56\_SMU\_ B44\_062\_060028.dgn aygodfrey


\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u>

S. T. SANDOR

W.C.SMITH

DRAWN BY : .

CHECKED BY :



REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


	EXISTING
CONCRETE REPAIR	J - JACKET

SHOTCRETE REPAIR E - ENCAPSULATION

ERI EPOXY RESIN INJECTION P - PILE

REPAIR QUANTITY TABLE							
DENT 40	ITIES						
BENT 46	EST	IMATE	ACT	UAL			
SHOTCRETE REPAIR	AREA SF	VOLUME CF	AREA SF	VOLUME CF			
CAP (VERTICAL FACE)	0.0	0.0					
CAP (HORIZONTAL FACE)	0.0	0.0					
COLUMN	0.0	0.0					
CONCRETE REPAIR							
CAP (VERTICAL FACE)	0.0	0.0					
CAP (HORIZONTAL FACE)	0.0	0.0					
COLUMN	0.0	0.0 0.0					
EPOXY RESIN INJECT	LF		LF				
CAP		0.0					
COLUMN		0.0					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



BEAUFORT COUNT

30'-6"

BRIDGE NO. 060028

SHEET 46 OF 48

STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION
RALEIGH

P3 P4 P5

SEAL 2644

BOTTOM OF CAP

Docustique

P5

DOCUMENT NOT CONSIDERED
FINAL UNLESS ALL
SIGNATURES COMPLETED

BENT 46 REPAIR

REVISIONS SHEET NO.
BY: DATE: NO. BY: DATE: S3-64

TOTAL SHEETS 78

SUBSTRUCTURE

1/24/2022 R:\Structures\Plans\Bridge\_060028\403\_127\_15BPR56\_SMU\_ B46\_064\_060028.dgn aygodfrey

P2

P1

S. T. SANDOR

W.C.SMITH

DRAWN BY : .

CHECKED BY :

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u>

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

		EXISTING		
$\ddot{\chi}$	CONCRETE REPAIR	J - JACKET		
7	SHOTCRETE REPAIR	E - ENCAPSULATIO		

ERI EPOXY RESIN INJECTION

E - ENCAPSULATION

P - PILE

BENT 47

COLUMN

COLUMN

CAP

COLUMN

SHOTCRETE REPAIR

CAP (VERTICAL FACE)

CAP (VERTICAL FACE)

CAP (HORIZONTAL FACE)

CAP (HORIZONTAL FACE)

CONCRETE REPAIR

EPOXY RESIN INJECTION

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

REPAIR QUANTITY TABLE

AREA

SF

0.0

0.0

0.0

0.0

0.0

ESTIMATE

VOLUME

0.0

0.0

0.0

0.0

0.0

0.0

LF


0.0


QUANTITIES

ACTUAL

VOLUME

LF





BOTTOM OF CAP

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u> S. T. SANDOR DRAWN BY : . W.C.SMITH CHECKED BY :

SEAL 26445 P. Korey Newton 4FFE39D1431B407... 01/27/2022

BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060028 SHEET 47 OF 48

PROJECT NO. 15BPR.56

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 47 REPAIR

> > BY:

SHEET NO. S3-65

TOTAL SHEETS 78

DATE:

REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

1/24/2022 R:\Structures\Plans\Bridge\_060028\403\_129\_15BPR56\_SMU\_ B47\_065\_060028.dgn aygodfrey

ERI EPOXY RESIN INJECTION

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.


CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

	EXISTING
CONCRETE REPAIR	J - JACKET
SHOTCRETE REPAIR	E - ENCAPSULATION

P - PILE

REPAIR C	UANT	ΙΤ	Υ ΤΑ	BLE		
QUANTITIES						
BENT 48	EST	IMA	TE	ACT	UAL	
SHOTCRETE REPAIR	AREA SF	\	VOLUME CF	AREA SF	VOLUME CF	
CAP (VERTICAL FACE)	0.0		0.0			
CAP (HORIZONTAL FACE)	0.0		0.0			
COLUMN	0.0		0.0			
CONCRETE REPAIR						
CAP (VERTICAL FACE)	0.0		0.0			
CAP (HORIZONTAL FACE)	0.0		0.0			
COLUMN	0.0		0.0			
EPOXY RESIN INJECTION			LF		LF	
CAP			0.0			
COLUMN			2.0			
ALLIES THE CHART REPRESENT ESTI	MATED REPA	\ T R	TOTALS A	ETER REMOVA	J OF	

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



30'-6"

SPAN 48
SPAN 49

P1 P2 P3 P4 P5

BOTTOM OF CAP

SHEET 48 OF 48

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

BRIDGE NO. 060028

SUBSTRUCTURE
BENT 48 REPAIR

P. Korey Newton

4FFE39D1431B407...
01/27/2022

DOCUMENT NOT CONSIDERED
FINAL UNLESS ALL
SIGNATURES COMPLETED

REVISIONS

BY: DATE: NO. BY: DATE: S3-66

TOTAL SHEETS
78

1/24/2022 R:\Structures\Plans\Bridge\_060028\403\_131\_15BPR56\_SMU\_ B48\_066\_060028.dgn aygodfrey

\_\_ DATE : <u>05/2021</u> \_\_ DATE : <u>06/2021</u>

S. T. SANDOR

W.C.SMITH

DRAWN BY : .

CHECKED BY :



INCIDENTAL MILLING - EXISTING APPROACH ASPHALT PAVING TO BE MILLED AS NECESSARY TO ATTAIN MINIMUM 11/2" DEPTH OF NEW ASPHALT PAVING. NEW ASPHALT PAVEMENT SHALL BE OF THICKNESS NECESSARY TO PROVIDE A SMOOTH TRANSITION BETWEEN THE ROADWAY AND THE BRIDGE DECK. THE NEW ASPHALT PAVEMENT THICKNESS MAY EXCEED 11/2" DUE TO SETTLEMENT OF THE EXISTING APPROACH.

TO SR 1741

65'-0" 1050"-6" (FILL FACE TO FILL FACE) 65'-0" ∕— Ç BRIDGE BRIDGE 
 →

### PLAN

PROPOSED VARIABLE DEPTH ASPHALT CONCRETE SURFACE COURSE, TYPE S9.5B, AT AN AVERAGE RATE OF 112 LBS. PER SQ. YD. PER 1"DEPTH. TO BE PLACED IN LAYERS NOT LESS THAN 11/2" IN DEPTH OR GREATER THAN 2"DEPTH.

INCIDENTAL MILLING

EXISTING WIDTH EXISTING

ACTUAL ESTIMATE 404.4 SY INCIDENTAL MILLING ASPHALT CONCRETE SURFACE COURSE, TYPE S9.5B 40.0 TONS ASPHALT BINDER FOR PLANT MIX 5.0 TONS

SUMMARY OF QUANTITIES

TYPICAL ROADWAY MILLING SECTION

BEAUFORT BRIDGE NO. 060028 STATE OF NORTH CAROLINA

EXISTING WIDTH — € ROADWAY TYPICAL PROPOSED ROADWAY SECTION

SEAL 3 26445 : NOINEER P. Korey Newton DEPARTMENT OF TRANSPORTATION
RALEIGH APPROACH MILLING AND TYPICAL ROADWAY SECTIONS

PROJECT NO. 15BPR.56

\_\_ COUNTY


\_\_ DATE : <u>12/2021</u> A. Y. GODFREY DRAWN BY : . P.K.NEWTON \_ DATE : <u>12/2021</u> CHECKED BY :

TO SR 1339

DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

1/19/2022 R:\Structures\Plans\Bridge\_060028\403\_133\_15BPR56\_SMU\_ AM\_067\_060028.dgn aygodfrey

4FFE39D1431B407... 01/27/2022 SHEET NO. REVISIONS S3-67 DATE: BY: TOTAL SHEETS 78




### PART TYPICAL SECTION

(SHOWING BENT DIAPHRAGM)
(FOR CHANNEL DETAILS, SEE "STRUCTURAL STEEL" SHEET 2 OF 2)

# TYPICAL SECTION

(SHOWING INTERMEDIATE DIAPHRAGM) (FOR CHANNEL DETAILS, SEE "STRUCTURAL STEEL" SHEET 2 OF 2)



#### NOTES

CLASSIC CONCRETE BRIDGE RAIL SHALL NOT BE CAST UNTIL ALL SLAB CONCRETE HAS BEEN CAST AND HAS REACHED A MINIMUM COMPRESSIVE STRENGTH OF 3,000 PSI.

NO CHAMFER IS REQUIRED ON CORNERS OF GIRDER BUILDUPS.

ALL BAR SUPPORTS AND ALL INCIDENTAL REINFORCING STEEL SHALL BE EPOXY COATED IN ACCORDANCE WITH THE STANDARD SPECIFICATIONS.

PROJECT NO. 15BPR.56 BEAUFORT \_\_ COUNTY BRIDGE NO. 060028



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

SUPERSTRUCTURE

TYPICAL SECTION (SPAN 25)

01/27/2022


SHEET NO. **REVISIONS** 


DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

NO. BY: S3-68 DATE: DATE: TOTAL SHEETS

SHEET 1 OF 2

\_\_ DATE : <u>11/3/21</u> \_\_ DATE : <u>12/2021</u> M.K. BEARD DRAWN BY : \_ Q.T. NGUYEN CHECKED BY : \_ DESIGN ENGINEER OF RECORD: D. SHACKELFORD DATE: 12/2021





\* #5G1 MAY BE SHIFTED SLIGHTLY, AS NECESSARY, TO CLEAR DIAPHRAGM AND REINFORCING STEEL.

PROJECT NO. 15BPR.56

BEAUFORT COUNTY

BRIDGE NO. 060028

SHEET 2 OF 2

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUPERSTRUCTURE

TYPICAL SECTION (SPAN 25)

DocuSigned by:

P. Korey Newton

4FFE39D1431B407...


01/27/2022

SEAL 26445

CHOINEER

4FFE39D1431B407							
01/27/2022			SHEET NO.				
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S3-69
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			A			l 78

DRAWN BY: M.K. BEARD DATE: 11/3/21
CHECKED BY: O.T. NGUYEN DATE: 12/2021
DESIGN ENGINEER OF RECORD: D. SHACKELFORD DATE: 12/2021



### PLAN OF SPAN & SIDEWALK


FOR CLASSIC CONCRETE BRIDGE RAIL REINFORCING STEEL & DETAILS, SEE "CLASSIC CONCRETE BRIDGE RAIL" SHEETS.

FOR SIDEWALK REINFORCING STEEL & DETAILS, SEE "SECTION THRU SIDEWALK" ON THE "TYPICAL SECTION" SHEET 2 OF 2.

PROJECT NO. 15BPR.56

BEAUFORT COUNTY

BRIDGE NO. 060028



STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUPERSTRUCTURE

PLAN OF SPAN & SIDEWALK

NO. BY:

SHEET NO.

S3-70

TOTAL SHEETS

DATE:

(SPAN 25)


DATE:

REVISIONS

DOCUMENT NOT CONSIDERED
FINAL UNLESS ALL
SIGNATURES COMPLETED

2

DRAWN BY :	M.K. BEARD	DATE :	11/8/21
CHECKED BY :	Q.T. NGUYEN		12/2021
DESIGN ENGINEER	OF RECORD: D. SHACKELFORD	DATE :	12/2021



PROJECT NO. 15BPR.56

BEAUFORT COUNTY

BRIDGE NO. 060028

### FRAMING PLAN



STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUPERSTRUCTURE

FRAMING PLAN (SPAN 25)

SHEET NO.

S3-71


TOTAL SHEETS 78


DATE:

DRAWN BY: M.K. BEARD DATE: 11/19/21
CHECKED BY: O.T. NGUYEN DATE: 12/2021
DESIGN ENGINEER OF RECORD: D. SHACKELFORD DATE: 12/2021


01/27/2022			REVIS	SION	۱S
OCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	E
FINAL UNLESS ALL	1			3	
SIGNATURES COMPLETED	2			4	

1/24/2022 R:\Structures\Plans\Bridge\_060028\403\_141\_15BPR56\_SMU\_FP\_071\_060028.dgn pknewton







## TYPICAL BENT DIAPHRAGM




BEARING STIFFENER




CONNECTOR PLATE DETAIL




### TYPICAL INTERMEDIATE DIAPHRAGM





# WELD TERMINATION DETAILS



15BPR.56 PROJECT NO.\_\_\_ BEAUFORT \_ COUNTY 060028 BRIDGE:

SHEET 2 OF 2

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

SUPERSTRUCTURE STRUCTURAL STEEL DETAILS (SPAN 25)

> SHEET NO. S3-73

> > TOTAL SHEETS 78

DATE:

P. Korey Newton 4FFE39D1431B407... 01/27/2022 REVISIONS NO. BY: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

STR. #28

SEAL 26445

NONES NEW

DRAWN BY: D. SHACKELFORD DATE: 11/2021
CHECKED BY: M.K. BEARD DATE: 12/2021
DESIGN ENGINEER OF RECORD: D. SHACKELFORD DATE: 11/2021

1/24/2022 R:\Structures\Plans\Bridge\_060028\403\_145\_15BPR56\_SMU\_GDR2\_073\_060028.dgn pknewton

		— (	DEA	) L	DAC	DE	FLE	CTI	ON	TAE	BLE	FOR	GI	RDE	RS						_
							В	EAMS	5 1 AI	ND 5											
TWENTIETH POINTS	0	.05	.10	<b>.</b> 15	<b>.</b> 20	<b>.</b> 25	.30	<b>.</b> 35	.40	<b>.</b> 45	<b>.</b> 50	<b>.</b> 55	.60	<b>.</b> 65	.70	<b>.</b> 75	.80	<b>.</b> 85	.90	<b>.</b> 95	0
DEFLECTION DUE TO WEIGHT OF GIRDER	0	0.001	0.002	0.002	0.003	0.004	0.004	0.005	0.005	0.005	0.005	0.005	0.005	0.005	0.004	0.004	0.003	0.002	0.002	0.001	0
DEFLECTION DUE TO WEIGHT V	0	0.008	0.016	0.023	0.029	0.035	0.040	0.044	0.047	0.049	0.049	0.049	0.047	0.044	0.040	0.035	0.029	0.023	0.016	0.008	0
DEFLECTION DUE TO WEIGHT OF PARAPET AND SIDEWALK	0	0.000	0.001	0.001	0.001	0.001	0.001	0.001	0.001	0.001	0.002	0.001	0.001	0.001	0.001	0.001	0.001	0.001	0.001	0.000	0
TOTAL DEAD LOAD DEFLECTION	0	0.009	0.019	0.026	0.033	0.040	0.045	0.050	0.053	0.055	0.056	0.055	0.053	0.050	0.045	0.040	0.033	0.026	0.019	0.009	0
VERTICAL CURVE ORDINATE	0	0.004	0.007	0.010	0.012	0.014	0.016	0.017	0.018	0.019	0.019	0.019	0.018	0.017	0.016	0.014	0.012	0.010	0.007	0.004	0
REQUIRED CAMBER	0	3/16"	5/16"	7∕ <sub>16</sub> "	1/2"	5/8"	3/4"	13/16"	7/8"	7/8"	7/8"	7/8"	7/8"	<sup>13</sup> / <sub>16</sub> "	3/4"	5/8"	1/2"	7∕ <sub>16</sub> "	5/16"	3/16"	0

	———— DEAD LOAD DEFLECTION TABLE FOR GIRDERS ——————																				
	BEAMS 2, 3 AND 4																				
TWENTIETH POINTS	0	.05	.10	.15	.20	.25	.30	.35	.40	.45	<b>.</b> 50	<b>.</b> 55	.60	.65	.70	.75	.80	.85	.90	<b>.</b> 95	0
DEFLECTION DUE TO WEIGHT V	0	0.001	0.002	0.002	0.003	0.004	0.004	0.005	0.005	0.005	0.005	0.005	0.005	0.005	0.004	0.004	0.003	0.002	0.002	0.001	0
DEFLECTION DUE TO WEIGHT V	0	0.006	0.012	0.017	0.022	0.027	0.031	0.034	0.036	0.037	0.038	0.037	0.036	0.034	0.031	0.027	0.022	0.017	0.012	0.006	0
DEFLECTION DUE TO WEIGHT OF PARAPET AND SIDEWALK	0	0.000	0.001	0.001	0.001	0.001	0.001	0.001	0.001	0.001	0.002	0.001	0.001	0.001	0.001	0.001	0.001	0.001	0.001	0.000	0
TOTAL DEAD LOAD DEFLECTION	0	0.007	0.015	0.020	0.026	0.032	0.036	0.040	0.042	0.043	0.045	0.043	0.042	0.040	0.036	0.032	0.026	0.020	0.015	0.007	0
VERTICAL CURVE ORDINATE	0	0.004	0.007	0.010	0.012	0.014	0.016	0.017	0.018	0.019	0.019	0.019	0.018	0.017	0.016	0.014	0.012	0.010	0.007	0.004	0
REQUIRED CAMBER	0	1/8"	1/4"	3/8"	7∕ <sub>16</sub> "	9/16"	5/8"	11/16"	3/4"	3/4"	3/4"	3/4"	3/4"	11/16"	5/8"	9/16"	7∕ <sub>16</sub> "	3/8"	1/4"	1/8"	0

\* INCLUDES SLAB AND BUILDUPS.
ALL VALUES ARE SHOWN IN FEET (DECIMAL FORM). EXCEPT "FINAL CAMBER", WHICH IS GIVEN IN INCHES (FRACTION FORM).

FABRICATORS SHALL DETAIL DIAPHRAGM MEMBERS AND CONNECTIONS FOR STEEL DEAD LOAD FIT UP.

PROJECT NO. 15BPR.56 BEAUFORT \_\_ COUNTY 060028 BRIDGE:\_



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUPERSTRUCTURE DEAD LOAD DEFLECTIONS


> > SHEET NO. S3-74


FINAL UNLESS ALL SIGNATURES COMPLETED 2

DocuSigned by:  P. Korey Newton  4FFE39D1431B407	(SPAN 25)								
01/27/2022			REVIS	SIO	NS				
DCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:			
CTAIN INDI CONSIDENED	ব			જ					


STR.#28

DRAWN BY: D. SHACKELFORD DATE: 12/2021
CHECKED BY: M.K. BEARD DATE: 12/2021
DESIGN ENGINEER OF RECORD: D. SHACKELFORD DATE: 12/2021





TYPICAL SECTION OF ELASTOMERIC BEARINGS



PLAN VIEW OF ELASTOMERIC BEARING

### TYPE I

3" 25/8"	5" 5"	213/16"	5" 5"	15/6"	5" 5"	
1′-8″	7	© 1 <sup>15</sup> / <sub>16</sub> '' Ø HOLES ————————————————————————————————————	7	© 1'5/ <sub>6</sub> '' Ø HOLES —	7-	2'-2"
3″	P1 (6 REC		P2 (FIXED)		P3 (FIXED)	- -

#### MAXIMUM ALLOWABLE SERVICE LOADS D.L.+L.L.(NO IMPACT)

k
k
k
_

#### NOTES

AT ALL FIXED POINTS OF SUPPORT. NUTS FOR ANCHOR BOLTS ARE TO BE TIGHTENED FINGER TIGHT AND THEN BACKED OFF  $\frac{1}{2}$  turn. The thread of the nut and bolt shall then be BÜRRED WITH A SHARP POINTED TOOL.

THE 2" Ø PIPE SLEEVE SHALL BE CUT FROM SCHEDULE 40 PVC PLASTIC PIPE. THE PVC PLASTIC PIPE SHALL MEET THE REQUIREMENTS OF ASTM D1785.

THE PAYMENT FOR THE PIPE SLEEVES SHALL BE INCLUDED IN THE SEVERAL PAY ITEMS.

FOR PAINTED STRUCTURAL STEEL (EXCLUDING AASHTO M270 GRADE 50W). SOLE PLATES. ANCHOR BOLTS. NUTS AND WASHERS SHALL BE GALVANIZED IN ACCORDANCE WITH THE STANDARD SPECIFICATIONS.

FOR AASHTO M270 GRADE 50W STRUCTURAL STEEL, SOLE PLATE SHALL BE AASHTO M270 GRADE 50W AND SHALL NOT BE GALVANIZED. ANCHOR BOLTS, NUTS AND WASHERS SHALL BE GALVANIZED IN ACCORDANCE WITH THE STANDARD SPECIFICATIONS.

ANCHOR BOLTS SHALL MEET THE REQUIREMENTS OF ASTM A449. NUTS SHALL MEET THE REQUIREMENTS OF AASHTO M291-DH OR AASHTO M292-2H. WASHERS SHALL MEET THE REQUIREMENTS OF AASHTO M293. SHOP DRAWINGS ARE NOT REQUIRED FOR ANCHOR BOLTS, NUTS AND WASHERS. SHOP INSPECTION IS REQUIRED.

WHEN FIELD WELDING THE SOLE PLATE TO THE GIRDER FLANGE, USE TEMPERATURE INDICATING WAX PENS, OR OTHER SUITABLE MEANS, TO ENSURE THAT THE TEMPERATURE OF THE SOLE PLATE DOES NOT EXCEED 300°F. TEMPERATURES ABOVE THIS MAY DAMAGE THE ELASTOMER.

ALL SURFACES OF BEARING PLATES SHALL BE SMOOTH AND STRAIGHT.

THE ELASTOMER IN THE STEEL REINFORCED BEARINGS SHALL HAVE A SHEAR MODULUS OF 0.160 KSI, IN ACCORDANCE WITH AASHTO M251.

FOR STEEL REINFORCED ELASTOMERIC BEARINGS, SEE SPECIAL PROVISIONS.

THE CONTRACTOR'S ATTENTION IS CALLED TO THE FOLLOWING PROCEDURE, WHICH MAY BE REQUIRED BY THE ENGINEER, TO RESET ELASTOMERIC BEARINGS DUE TO GIRDER TRANSLATION AND END ROTATION:

1. ONCE THE DECK HAS CURED, THE GIRDERS SHALL BE JACKED AND THE ELASTOMERIC BEARING SLOTS CENTERED AS NEARLY AS PRACTICAL ABOUT THE BEARING STIFFENER. THIS OPERATION SHALL BE PERFORMED AT APPROXIMATELY

THE CONTRACTOR MAY PROPOSE ALTERNATE METHODS, PROVIDED DETAILS ARE SUBMITTED TO THE ENGINEER FOR REVIEW AND APPROVAL.

CUT EXISTING ANCHOR BOLTS FLUSH TO THE TOP OF CONCRETE. BOLT ENDS SHALL BE COATED WITH AN APPROVED EPOXY PAINT.

THE CONTRACTOR SHALL CORE INTO EXISTING BENT CAP TO INSTALL ANCHOR BOLTS. BOLTS SHALL BE ADHESIVELY ANCHORED; SEE STANDARD SPECIFICATIONS. CONTRACTOR SHALL SUBMIT PROPOSED ADHESIVE FOR APPROVAL. ADHESIVE FOR NEW ANCHOR BOLTS SHALL BE ON THE NCDOT APPROVED PRODUCT LIST, FOR THE PROPOSED USE.

NEW ADHESIVELY ANCHORED BOLTS SHALL BE SUBJECT TO LEVEL 1 FIELD TESTING, IN ACCORDANCE WITH STANDARD SPECIFICATIONS ARTICLE 420-13 (C), EXCEPT THAT THE TEST LOAD SHALL BE 10,000 LBS. TENSION FOR ANCHOR BOLTS.

MINIMUM EMBEDMENT OF ANCHOR BOLT SHALL BE PER MANUFACTURER RECOMMENDATIONS. MINIMUM LENGTH OF ANCHOR BOLT SHALL BE SUFFICIENT FOR EMBEDMENT DEPTH, THICKNESS OF ELASTOMERIC BEARING, SOLE PLATE(S), AND FULL ENGAGEMENT OF ANCHOR BOLT NUT.

> PROJECT NO. 15BPR.56 BEAUFORT \_ COUNTY 060028 STATION:



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION STANDARD

ELASTOMERIC BEARING —— DETAILS ——

(STEEL SUPERSTRUCTURE) (SPAN 25)

P. Korey Newton SHEET NO. **REVISIONS** 01/27/2022 S3-75 DATE: DATE: BY: BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

SOLE PLATE DETAILS ("P")

DATE : 11/29/21

MAA/GM

AAC/MAA

MAA/THC


DATE : 1/14/22

ASSEMBLED BY : M.K. BEARD

CHECKED BY : ARB 11/87


CHECKED BY : D. SHACKELFORD

DRAWN BY: JMB II/87 REV. IO/I/II
CHECKED BY: ARB II/87 REV. 6/13



### ELEVATION OF CLASSIC CONCRETE BRIDGE RAIL

LEFT SIDE SHOWN, RIGHT SIDE SIMILAR.
DIMENSIONS ARE GIVEN ALONG OUTSIDE EDGE OF SUPERSTRUCTURE.



### PLAN OF CLASSIC CONCRETE BRIDGE RAIL

LEFT SIDE SHOWN, RIGHT SIDE SIMILAR. WINDOWS NOT SHOWN FOR CLARITY. DIMENSIONS ARE GIVEN ALONG OUTSIDE OF SUPERSTRUCTURE.

PROJECT NO. 15BPR.56 BEAUFORT \_\_ COUNTY BRIDGE NO. 060028

SHEET 1 OF 2

SEAL 26445

TOREY NEW

DocuSigned by:

4FFE39D1431B407... 01/27/2022

P. Korey Newton

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

SUPERSTRUCTURE

CLASSIC CONCRETE BRIDGE RAIL

(SPAN 25)


REVISIONS SHEET NO. NO. BY: DATE: S3-76 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS

\_\_ DATE : <u>11/18/21</u> DATE : 12/2021 DESIGN ENGINEER OF RECORD: <u>D. SHACKELFORD</u> DATE : <u>12/2021</u>


M.K. BEARD

Q.T. NGUYEN

DRAWN BY : \_



SECTION THRU POST




#### NOTES

ALL PARTS OF THE CLASSIC CONCRETE BRIDGE RAIL INCLUDING BUT NOT LIMITED TO THE REINFORCING STEEL, CLASS AA CONCRETE SHALL BE INCLUDED IN THE UNIT PRICE BID PER LINEAR FOOT FOR "CLASSIC CONCRETE BRIDGE RAIL". NO SEPARATE MEASUREMENT OR PAYMENT WILL BE MADE FOR THESE ITEMS.

CLASSIC CONCRETE BRIDGE RAIL SHALL NOT BE CAST UNTIL ALL SLAB CONCRETE IN THE UNIT HAS BEEN CAST AND HAS REACHED MINIMUM COMPRESSIVE STRENGTH OF 3000 PSI.

ALL REINFORCING STEEL IN CLASSIC CONCRETE BRIDGE RAIL SHALL BE EPOXY COATED. FOR CLASSIC CONCRETE BRIDGE RAIL, SEE SPECIAL PROVISIONS.




ALL BAR DIMENSIONS ARE OUT TO OUT

	BILL OF MATERIAL							
	BAR	NO.	SIZE	TYPE	LENGTH	WEIGHT		
*	B6	24	#4	STR	16'-10"	270		
*	B7	12	#4	STR	1'-7"	13		
*	B8	40	#4	STR	1'-4"	36		
*	S1	12	#4	1	6′-6″	52		
*	S2	240	#4	STR	5′-3″	842		


* EP	YXC	COATED	)
RF	TNFO	RCING	STFFL

REINFORCING STEEL	1213 LBS.
CLASS AA CONCRETE	
CONCRETE POST	O.6 CU.YDS.
CONCRETE RAIL	2.7 CU. YDS.
TOTAL	3.3 CU. YDS.


CONCRETE POST	6.67 LIN.F
CONCRETE RAIL	72.75 LIN.F
TOTAL	79.42 LIN.F








SECTION A-A



WINDOW DETAIL



PROJECT NO. 15BPR.56 BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060028

SHEET 2 OF 2

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

SUPERSTRUCTURE

CLASSIC CONCRETE BRIDGE RAIL

(SPAN 25)

P. Korey Newton


4FFE39D1431B407...

01/27/2022 REVISIONS SHEET NO. NO. BY: DATE: S3-77 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS 78


HILLIAN WALLER	SEAL 26445	
	DocuSigned by:	

DRAWN BY: M.K. BEARD DATE: 11/18/21
CHECKED BY: O.T. NGUYEN DATE: 12/2021
DESIGN ENGINEER OF RECORD: D. SHACKELFORD DATE: 12/2021

1/24/2022 R:\Structures\Plans\Bridge\_060028\403\_153\_15BPR56\_SMU\_CBR2\_077\_060028.dgn pknewton



(SQ.FT. = 1445)



SUPERSTRUCTURE REINFORCING STEEL LENGTHS ARE BASED ON THE FOLLOWING MINIMUM SPLICE LENGTHS

BAR SIZE	SUPERSTA EXCEPT A SLABS, PA AND BARRI	APPROACH ARAPETS,	APPROAC	CH SLABS	PARAPETS AND BARRIER RAILS		
	EPOXY COATED	UNCOATED	EPOXY COATED	UNCOATED			
#4	1'-11"	1'-7"	1'-11"	1'-7"	2'-6"		
<b>#</b> 5	2′-5″	2'-0"	2′-5″	2'-0"	3'-1"		
<b>#</b> 6	2′-10″	2′-5″	3′-7"	2′-5″	3′-8″		
<b>#</b> 7	4′-2″	2'-9"					
<b>#</b> 8	4′-9"	3′-2"					


— SUPERSI	RUCTURE BILL	OF MATERIAL —
	CLASS AA CONCRETE	EPOXY COATED REINFORCING STEEL
	(CU.YDS.)	(LBS.)
SPAN 25	42.8	9246
TOTALS**	42.8	9246

\*\* QUANTITIES FOR CLASSIC CONCRETE BRIDGE RAIL ARE NOT INCLUDED.

BILL OF MATERIAL					
BAR	NO.	SIZE	TYPE	LENGTH	WEIGHT
<b>*</b> A1	80	#5	STR	30'-1"	2510
<b>*</b> A2	80	#5	STR	30'-1"	2510
<b>∗</b> B1	21	#4	STR	39'-5"	553
<b>∗</b> B2	36	#5	STR	39'-5"	1480
<b>∗</b> B3	24	#4	STR	39′-5″	632
<b>∗</b> B4	160	#4	1	6′-5″	686
<b>∗</b> B5	158	#4	STR	3'-4"	352
* G1	2	#5	STR	30'-1"	63
		_			
* K1	16	#5	2	4'-10"	81
* K2	16	#5	3	7′-6″	125
<b>∗</b> K3	16	#5	STR	5′-10″	97
<b>*</b> S1	64	#4	4	3′-8″	157

\* EPOXY COATED REINFORCING STEEL 9246 LBS. CLASS AA CONCRETE 42.8 CU. YDS. GROOVING BRIDGE FLOOR 997 SQ.FT.

PROJECT NO. 15BPR.56 BEAUFORT COUNTY STATION: 060028



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

STANDARD

SUPERSTRUCTURE BILL OF MATERIAL


(SPAN 25)


4FFE39D1431B407... 01/27/2022 REVISIONS SHEET NO. S3-78 NO. BY: DATE: DATE: TOTAL SHEETS 78


DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED


ASSEMBLED BY : M.K. BEARD CHECKED BY : O.T. NGUYEN DATE: 12/14/21 DATE: 12/2021 MAA/GM MAA/THC BNB/THC DRAWN BY: JMB 5/87 CHECKED BY: SJD 9/87


STD. NO. BOM1

















FINAL JOINT SEALS SHALL NOT BE INSTALLED UNTIL THE OVERLAY OR SEALANT WORK IS COMPLETE.

THE CONTRACTOR SHALL FIELD VERIFY THE EXISTING JOINT OPENING PRIOR TO ORDERING JOINT SEAL MATERIAL. IF THE ACTUAL JOINT OPENING VARIES FROM THE OPENING INDICATED IN THE DETAILS BY MORE THAN 1/4", NOTIFY THE ENGINEER.

THE MANUFACTURER IS TO PROVIDE THE NOMINAL UNCOMPRESSED SEAL WIDTH OF THE FOAM JOINT SEAL FOR THE SIZE OF THE OPENING ON THE PLANS AND ACCOMODATE THE MINIMUM EXPANSION SHOWN ON THE PLANS.

FOAM JOINTS SHALL BE INSTALLED AS PER THE MANUFACTURER'S RECOMMENDATIONS.

THE CONTRACTOR SHALL TAKE CARE DURING JOINT REHAB OPERATIONS NOT TO DROP ANY MATERIAL BELOW THE BRIDGE, WITHOUT PROTECTIVE DEVICES BELOW TO CATCH THE MATERIAL. ANY MATERIAL THAT FALLS BELOW THE BRIDGE SHALL BE CONTAINED, REMOVED AND DISPOSED OF BY THE CONTRACTOR AT NO EXTRA COST TO THE DEPARTMENT. IF THE ENGINEER DETERMINES THAT THE PROTECTIVE DEVICES ARE NOT ADEQUATE OR NOT BEING EMPLOYED, THE WORK SHALL BE SUSPENDED UNTIL ADEQUATE PROTECTION IS PROVIDED.

THE CONTRACTOR WILL NOT BE PERMITTED TO FORM THE JOINTS IN LIEU OF SAWING THE JOINT.

THE INSTALLED FOAM JOINTS SHALL BE WATER TIGHT.

FOR FOAM JOINT SEALS FOR PRESERVATION, SEE SPECIAL PROVISIONS.

THE CONTRACTOR SHALL SAW CUT TO A NOMINAL DEPTH OF  $\frac{1}{2}$ " BUT REINFORCING STEEL SHALL NOT BE DAMAGED. CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO VERIFY THAT SAWCUT DEPTH WILL NOT DAMAGE EXISTING REINFORCING STEEL.

QUANTITIES SHOWN IN THE ELASTOMERIC CONCRETE FOR PRESERVATION TABLE ARE BASED ON THE MINIMUM JOINT DEMOLITION SHOWN.

FINAL SURFACE OF THE JOINT DEMOLITION AREA PRIOR TO PLACEMENT OF CONCRETE REPAIR MATERIAL OR ELASTOMERIC CONCRETE SHALL BE REASONABLY FLAT AND LEVEL. THE ENGINEER SHALL DETERMINE ACCEPTABILITY OF THE SURFACE.

FOR EXCAVATION BELOW THE BOTTOM OF PLANNED JOINT DEMOLITION, CONCRETE FOR DECK REPAIR SHALL BE PLACED IN THE EXCAVATED AREA TO THE ELEVATION AT THE BOTTOM OF THE PROPOSED ELASTOMERIC CONCRETE FOR PRESERVATION HEADERS SHOWN.

FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.

FOR ELASTOMERIC CONCRETE FOR PRESERVATION, SEE SPECIAL PROVISIONS.

FOR CONCRETE FOR DECK REPAIR, SEE SPECIAL PROVISIONS.

SHEET 1 OF 2

PROJECT NO. 15BPR.56

BEAUFORT COUNTY

BRIDGE NO. 060077

SEAL 26445

CONEE NEW NEW MINISTER IN THE PROPERTY NEW MINISTER IN THE PRO

DEPARTMENT OF TRANSPORTATION

RALEIGH

STANDARDS

JOINT REPAIR DETAILS

P. Korey Newton

4FFE39D1431B407...

01/27/2022

REVISIONS

NO. BY: DATE: NO.

FINAL LINEFSS ALL

3

DOCUMENT NOT CONSIDERED 1 1 SIGNATURES COMPLETED 2

CHECKED BY: P. K. NEWTON

DRAWN BY: NAP 08/2018

CHECKED BY: -

DATE: 01/2022

### ELASTOMERIC CONCRETE FOR PRESERVATION ACTUAL (CU. FT.) **ESTIMATED** LOCATION (CU. FT.) END BENT 1 BENT 2 8.0 BENT 4 8.0 BENT 6 8.0 BENT 8 8.0 BENT 10 BENT 12 8.0 BENT 14 8.0 BENT 16 8.0 BENT 18 8.0 BENT 20 8.0 BENT 22 8.0 BENT 24 BENT 26 8.0 BENT 28 8.0 BENT 30 8.0 BENT 32 8.0 BENT 34 BENT 36 END BENT 2

SAWED JOIN	T OPENIN	G TABLE	
	(P	SAWED JOINT OPEI ERPENDICULAR TO	VING JOINT)
LOCATION	AT	45° AT 60°	AT 90°
END BENT 1	2	½" 2 <sup>3</sup> / <sub>8</sub> "	23/16"
BENT 2	29	2 <sup>3</sup> / <sub>8</sub> "	2 <sup>15</sup> ⁄16"
BENT 4	29	2 <sup>3</sup> / <sub>8</sub> "	215/16"
BENT 6	29	2 <sup>3</sup> / <sub>8</sub> "	2 <sup>15</sup> ⁄16"
BENT 8	25	2 <sup>3</sup> / <sub>8</sub> "	2 <sup>15</sup> ⁄16"
BENT 10	2	<sup>5</sup> / <sub>8</sub> " 2 <sup>3</sup> / <sub>8</sub> "	113/16"
BENT 12	2	<sup>5</sup> / <sub>8</sub> " 2 <sup>3</sup> / <sub>8</sub> "	113/16"
BENT 14	2	<sup>5</sup> / <sub>8</sub> " 2 <sup>3</sup> / <sub>8</sub> "	113/16"
BENT 16	2	5/8" 2 <sup>3</sup> /8"	113/16"
BENT 18	2	5 <sub>8</sub> " 2 <sup>3</sup> 8"	113/16"
BENT 20	2	5/8" 2 <sup>3</sup> /8"	113/16"
BENT 22	2	5/8" 2 <sup>3</sup> /8"	113/16"
BENT 24	2	5/8" 2 <sup>3</sup> /8"	113/16"
BENT 26	2	5/8" 2 <sup>3</sup> /8"	113/16"
BENT 28	2	5/8" 2 <sup>3</sup> /8"	113/16"
BENT 30	2	5 <sub>8</sub> " 2 <sup>3</sup> <sub>8</sub> "	113/16"
BENT 32	2	5/8" 2 <sup>3</sup> /8"	113/16"
BENT 34	2	5 <sub>8</sub> " 2 <sup>3</sup> <sub>8</sub> "	113/16"
BENT 36	2	5/8" 23/8"	17/8"
END BENT 2	2	½" 2 <sup>3</sup> / <sub>8</sub> "	23/16"

JOINT REPAIR QUANTITY TABLE				
	ESTIMATED	ACTUAL		
FOAM JOINT SEALS FOR PRESERVATION	640.0 L.F.			

PROJECT NO. 15BPR.56

BEAUFORT COUNTY

BRIDGE NO. <u>060077</u>

SHEET 2 OF 2

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

JOINT REPAIR DETAILS

Docusigned by:

P. Korey Newton

4FFE39D1431B407...

01/27/2022


DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS			SHEET NO.			
NO.	BY:	DATE:	NO.	BY:	DATE:	S4-7
1			3			TOTAL SHEETS
2			4			17


DRAWN BY: S.T.SANDOR DATE: 01/2022
CHECKED BY: W.C.SMITH DATE: 01/2022
DESIGN ENGINEER OF RECORD: DATE:

TOTAL

160.0







\_ DATE : <u>07/2021</u> S. T. SANDOR DRAWN BY : \_ DATE : 12/2021 W.C.SMITH CHECKED BY :

P. Korey Newton 4FFE39D1431B407... 01/27/2022

SEAL 7 26445

NOINEER

AS-BUILT REPAIR QUANTITY TABLE				
DECK SURFACE REPAIRS - SPANS 1 THROUGH 3				
		ESTIMATE	ACTUAL	
SHOTBLASTING BRIDGE DECK		784.0 SQ. YD	S.	
SILANE DECK TREATMENT		784.0 SQ. YD	S.	
CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT		0.0 SQ.FT.		
DECK SURFACE REPAIRS	- A	PPROACH S	SLAB 1	
		ESTIMATE	ACTUAL	
SHOTBLASTING BRIDGE DECK		87.1 SQ. YDS.		
SILANE DECK TREATMENT		87.1 SQ. YDS.		
CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT		0.0 SQ.FT.		
BARRIER RA	4IL	REPAIRS		
		ESTIMATE	ACTUAL	
EPOXY RESIN INJECTION	3:	1.0 LIN.FT.		
JOINT	RE	PAIR		
			ACTUAL	
BRIDGE JOINT DEMOLITION	64	.O SQ.FT.		

### NOTES

FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR SECTIONS A-A AND B-B, SEE "JOINT REPAIR DETAILS" SHEET.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.

SHOTBLASTING AND SILANE DECK TREATMENT AREA

ERI - EPOXY RESIN INJECTION

BRIDGE JOINT DEMOLITION

PROJECT NO. 15BPR.56 BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060077


SHEET 1 OF 10


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

SUPERSTRUCTURE PLAN OF SPANS AND APPROACH SLAB

REVISIONS SHEET NO. NO. BY: S4-8 DATE: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS

1/24/2022 R:\Structures\Plans\Bridge\_060077\404\_015\_15BPR56\_SMU\_DSR1\_008\_060077.dgn





\_ DATE : <u>07/2021</u> S. T. SANDOR DRAWN BY : . \_ DATE : <u>12/2021</u> W.C.SMITH CHECKED BY :

AS-BUILT REPAIR QUANTITY TABLE DECK SURFACE REPAIRS - SPANS 4 THROUGH 7

ESTIMATE ACTUAL 1,045.3 SQ. YDS. SHOTBLASTING BRIDGE DECK SILANE DECK TREATMENT 1,045.3 SQ. YDS. CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT 0.0 SQ.FT.

BARRIER RAIL REPAIRS ESTIMATE ACTUAL EPOXY RESIN INJECTION O.O LIN.FT.

JOINT REPAIR ESTIMATE ACTUAL BRIDGE JOINT DEMOLITION 64.0 SQ.FT.

### NOTES

FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR SECTION B-B. SEE "JOINT REPAIR DETAILS" SHEET.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.

SHOTBLASTING AND SILANE DECK TREATMENT AREA

ERI - EPOXY RESIN INJECTION

BRIDGE JOINT DEMOLITION

PROJECT NO. 15BPR.56 BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060077

SHEET 2 OF 10

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

SUPERSTRUCTURE

PLAN OF SPANS


P. Korey Newton


SEAL 26445

4FFE39D1431B407... 01/27/2022 REVISIONS DATE:

SHEET NO. NO. BY: DATE: S4-9 DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS

1/24/2022 R:\Structures\Plans\Bridge\_060077\404\_017\_15BPR56\_SMU\_DSR2\_009\_060077.dgn pknewton





AS-BUILT REPAIR QUANTITY TABLE DECK SURFACE REPAIRS - SPANS 8 THROUGH 11 ESTIMATE ACTUAL 1,187.6 SQ. YDS. SHOTBLASTING BRIDGE DECK SILANE DECK TREATMENT 1,187.6 SQ. YDS. CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT 0.0 SQ.FT. BARRIER RAIL REPAIRS ESTIMATE ACTUAL EPOXY RESIN INJECTION O.O LIN.FT. JOINT REPAIR ESTIMATE ACTUAL BRIDGE JOINT DEMOLITION 64.0 SQ.FT.

### NOTES

FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR SECTION B-B, SEE "JOINT REPAIR DETAILS" SHEET.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.

SHOTBLASTING AND SILANE DECK TREATMENT AREA

ERI - EPOXY RESIN INJECTION

BRIDGE JOINT DEMOLITION

SEAL 7 26445 PROJECT NO. 15BPR.56

BEAUFORT COUNTY

BRIDGE NO. 060077

SHEET 3 OF 10

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUPERSTRUCTURE

PLAN OF SPANS


\_\_ DATE : <u>07/2021</u>

\_ DATE : <u>12/2021</u>


S. T. SANDOR

W.C.SMITH

DRAWN BY : .



PLAN
(SPANS 12 & 13)



AS-BUILT REPAIR QUANTITY TABLE

DECK SURFACE REPAIRS - SPANS 12 THROUGH 15

ESTIMATE ACTUAL

SHOTBLASTING BRIDGE DECK 1,329.8 SO. YDS.

SILANE DECK TREATMENT 1,329.8 SO. YDS.

CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT 0.0 SO. FT.

BARRIER RAIL REPAIRS

ESTIMATE ACTUAL

EPOXY RESIN INJECTION 0.0 LIN. FT.

JOINT REPAIR

ESTIMATE ACTUAL

BRIDGE JOINT DEMOLITION 64.0 SQ. FT.

NOTES

FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR SECTION B-B, SEE "JOINT REPAIR DETAILS" SHEET.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.

SHOTBLASTING AND SILANE DECK TREATMENT AREA

 $\sim$  ERI - EPOXY RESIN INJECTION

BRIDGE JOINT DEMOLITION

SEAL 26445

LACINEER

PROJECT NO. 15BPR.56

BEAUFORT COUNTY

BRIDGE NO. 060077

SHEET 4 OF 10

DEPARTMENT OF TRANSPORTATION
RALEIGH

SUPERSTRUCTURE

PLAN OF SPANS

P. Korey Newton

o1/27/2022

REVISIONS

SHEET NO

DOCUMENT NOT CONSIDERED
FINAL UNLESS ALL
SIGNATURES COMPLETED

2


REVISIONS

SHEET NO

BY:
DATE:
NO. BY:
DATE:
NO. BY:
DATE:
NO. BY:
17

 DRAWN BY :
 S. T. SANDOR
 DATE :
 07/2021

 CHECKED BY :
 W. C. SMITH
 DATE :
 12/2021



3,352'-0"TOTAL LENGTH OF BRIDGE (FILL FACE TO FILL FACE) (ALONG & BRIDGE)

94'-0" (SPAN 18)

94'-0" (SPAN 19)

BARRIER RAIL

(TYP.)

LIMITS OF SHOTBLASTING AND SILANE DECK TREATMENT

BENT 17

LIMITS OF SHOTBLASTING AND SILANE DECK TREATMENT

BRIDGE JOINT

DEMOLITION

BRIDGE

BR

PLAN
(SPANS 18 & 19)

DRAWN BY: S.T. SANDOR DATE: 07/2021
CHECKED BY: W.C. SMITH DATE: 12/2021

AS-BUILT REPAIR QUANTITY TABLE

DECK SURFACE REPAIRS - SPANS 16 THROUGH 19

ESTIMATE ACTUAL

SHOTBLASTING BRIDGE DECK 1,329.8 SQ. YDS.

SILANE DECK TREATMENT 1,329.8 SQ. YDS.

CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT 0.0 SQ. FT.

BARRIER RAIL REPAIRS

ESTIMATE ACTUAL

EPOXY RESIN INJECTION 0.0 LIN.FT.

JOINT REPAIR

ESTIMATE ACTUAL

BRIDGE JOINT DEMOLITION 64.0 SQ.FT.

# NOTES

FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR SECTION B-B, SEE "JOINT REPAIR DETAILS" SHEET.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.

SHOTBLASTING AND SILANE DECK TREATMENT AREA

✓ ERI - EPOXY RESIN INJECTION

BRIDGE JOINT DEMOLITION

SEAL 26445

: NOINEEP

P. Korey Newton

PROJECT NO. 15BPR.56

BEAUFORT COUNTY
BRIDGE NO. 060077

SHEET 5 OF 10

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION


RALEIGH


SUPERSTRUCTURE

PLAN OF SPANS

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 REVISIONS SHEET NO. BY: DATE: No. BY: DATE: S4-12

1/24/2022 R:\Structures\Plans\Bridge\_060077\404\_023\_15BPR56\_SMU\_DSR5\_012\_060077.dgn





AS-BUILT REPAIR QUANTITY TABLE DECK SURFACE REPAIRS - SPANS 20 THROUGH 23 ESTIMATE ACTUAL 1,329.8 SQ. YDS. SHOTBLASTING BRIDGE DECK SILANE DECK TREATMENT 1,329.8 SQ. YDS. CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT 0.0 SQ.FT. BARRIER RAIL REPAIRS ESTIMATE ACTUAL EPOXY RESIN INJECTION O.O LIN.FT. JOINT REPAIR ESTIMATE ACTUAL BRIDGE JOINT DEMOLITION 64.0 SQ.FT.

### NOTES

FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR SECTION B-B, SEE "JOINT REPAIR DETAILS" SHEET.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.

SHOTBLASTING AND SILANE DECK TREATMENT AREA

✓ ERI - EPOXY RESIN INJECTION

BRIDGE JOINT DEMOLITION

SEAL 26445

NOINEER

PROJECT NO. 15BPR.56

BEAUFORT COUNTY
BRIDGE NO. 060077

SHEET 6 OF 10

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUPERSTRUCTURE

PLAN OF SPANS

Docusigned by:

P. Korey Newton

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 REVISIONS SHEET NO. BY: DATE: No. BY: DATE: SHEETS

17

1/24/2022 R:\Structures\Plans\Bridge\_060077\404\_025\_15BPR56\_SMU\_DSR6\_013\_060077.dgn

S. T. SANDOR


W.C.SMITH


DRAWN BY : .

CHECKED BY :

\_ DATE : <u>07/2021</u>

\_ DATE : <u>12/2021</u>





AS-BUILT REPAIR QUANTITY TABLE DECK SURFACE REPAIRS - SPANS 24 THROUGH 27 ESTIMATE ACTUAL 1,329.8 SQ. YDS. SHOTBLASTING BRIDGE DECK SILANE DECK TREATMENT 1,329.8 SQ. YDS. CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT 0.0 SQ.FT. BARRIER RAIL REPAIRS ESTIMATE ACTUAL EPOXY RESIN INJECTION O.O LIN.FT. JOINT REPAIR

ESTIMATE ACTUAL BRIDGE JOINT DEMOLITION 64.0 SQ.FT.

### NOTES

FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR SECTION B-B. SEE "JOINT REPAIR DETAILS" SHEET.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.

SHOTBLASTING AND SILANE DECK TREATMENT AREA

ERI - EPOXY RESIN INJECTION

BRIDGE JOINT DEMOLITION

SEAL 26445

NOINEER

PROJECT NO. 15BPR.56 BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060077

SHEET 7 OF 10

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

SUPERSTRUCTURE

SHEET NO.

S4-14

TOTAL SHEETS

PLAN OF SPANS

P. Korey Newton 4FFE39D1431B407. REVISIONS DATE: DATE: BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

1/24/2022 R:\Structures\Plans\Bridge\_060077\404\_027\_15BPR56\_SMU\_DSR7\_014\_060077.dgn


\_ DATE : <u>12/2021</u>

\_ DATE : <u>07/2021</u>

S. T. SANDOR

W.C.SMITH

DRAWN BY : .



3,352'-0" TOTAL LENGTH OF BRIDGE (FILL FACE TO FILL FACE) (ALONG ← BRIDGE) 94'-0"(SPAN 30) 94'-0" (SPAN 31) BARRIER RAIL (TYP.) LIMITS OF SHOTBLASTING AND SILANE DECK TREATMENT € JOINT @ BENT 30 — € BENT 29 입 LIMITS OF SHOTBLASTING AND SILANE DECK TREATMENT — Ç BRIDGE BRIDGE JOINT DEMOLITION BRIDGE JOINT DEMOLITION

PLAN

S. T. SANDOR \_ DATE : <u>07/2021</u> DRAWN BY : . W.C.SMITH \_ DATE : 12/2021 CHECKED BY :

AS-BUILT REPAIR QUANTITY TABLE DECK SURFACE REPAIRS - SPANS 28 THROUGH 31 ESTIMATE ACTUAL SHOTBLASTING BRIDGE DECK 1,329.8 SQ. YDS. SILANE DECK TREATMENT 1,329.8 SQ. YDS. CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT 0.0 SQ.FT. BARRIER RAIL REPAIRS ESTIMATE ACTUAL EPOXY RESIN INJECTION O.O LIN.FT.

JOINT REPAIR ESTIMATE ACTUAL BRIDGE JOINT DEMOLITION 64.0 SQ.FT.

NOTES

FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR SECTION B-B. SEE "JOINT REPAIR DETAILS" SHEET.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.

SHOTBLASTING AND SILANE DECK TREATMENT AREA

ERI - EPOXY RESIN INJECTION

BRIDGE JOINT DEMOLITION

PROJECT NO. 15BPR.56 BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060077

SHEET 8 OF 10

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

SUPERSTRUCTURE

PLAN OF SPANS


SEAL 26445

TOREY NE

P. Korey Newton

4FFE39D1431B407 SHEET NO. REVISIONS S4-15 DATE: DATE: BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS

1/24/2022 R:\Structures\Plans\Bridge\_060077\404\_029\_15BPR56\_SMU\_DSR8\_015\_060077.dgn



3,352'-0" TOTAL LENGTH OF BRIDGE (FILL FACE TO FILL FACE) (ALONG ← BRIDGE) 94'-0"(SPAN 34) 94'-0"(SPAN 35) BARRIER RAIL (TYP.) € JOINT @ BENT 34 LIMITS OF SHOTBLASTING AND SILANE DECK TREATMENT LIMITS OF SHOTBLASTING AND SILANE DECK TREATMENT — Ç BRIDGE € BENT 35-BRIDGE JOINT DEMOLITION € BENT 33 ---BRIDGE JOINT DEMOLITION

PLAN
(SPANS 34 & 35)

AS-BUILT REPAIR QUANTITY TABLE DECK SURFACE REPAIRS - SPANS 32 THROUGH 35 ESTIMATE ACTUAL 1,329.8 SQ. YDS. SHOTBLASTING BRIDGE DECK SILANE DECK TREATMENT 1,329.8 SQ. YDS. CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT 0.0 SQ.FT. BARRIER RAIL REPAIRS ESTIMATE ACTUAL EPOXY RESIN INJECTION O.O LIN.FT.

JOINT REPAIR ESTIMATE ACTUAL BRIDGE JOINT DEMOLITION 64.0 SQ.FT.

### NOTES

FOR SILANE DECK TREATMENT. SEE SPECIAL PROVISIONS.

FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR SECTION B-B, SEE "JOINT REPAIR DETAILS" SHEET.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.

SHOTBLASTING AND SILANE DECK TREATMENT AREA

ERI - EPOXY RESIN INJECTION

BRIDGE JOINT DEMOLITION

PROJECT NO. 15BPR.56 BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060077

SHEET 9 OF 10

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

SUPERSTRUCTURE

PLAN OF SPANS

P. Korey Newton 4FFE39D1431B407

SEAL 26445

FOREY NE

REVISIONS SHEET NO. NO. BY: DATE: S4-16 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS

1/24/2022 R:\Structures\Plans\Bridge\_060077\404\_031\_15BPR56\_SMU\_DSR9\_016\_060077.dgn pknewton


\_ DATE : <u>07/2021</u>

\_ DATE : <u>12/2021</u>


S. T. SANDOR

W.C.SMITH

DRAWN BY : .



(SPANS 36 & 37)



AS-BUILT REPAIR QUANTITY TABLE DECK SURFACE REPAIRS - SPANS 36 THROUGH 38 ESTIMATE ACTUAL 855.1 SQ. YDS. SHOTBLASTING BRIDGE DECK SILANE DECK TREATMENT 855.1 SQ. YDS. CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT 0.0 SQ.FT. DECK SURFACE REPAIRS - APPROACH SLAB 2 ESTIMATE ACTUAL SHOTBLASTING BRIDGE DECK 87.1 SQ. YDS. 87.1 SQ. YDS. SILANE DECK TREATMENT CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT 0.0 SQ.FT. BARRIER RAIL REPAIRS ESTIMATE ACTUAL 0.0 LIN.FT. EPOXY RESIN INJECTION JOINT REPAIR ESTIMATE ACTUAL BRIDGE JOINT DEMOLITION 64.0 SQ.FT.

### NOTES

FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

- FOR SECTIONS A-A AND B-B. SEE "JOINT REPAIR DETAILS" SHEET.
- FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.
- FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.


SHOTBLASTING AND SILANE DECK TREATMENT AREA

ERI - EPOXY RESIN INJECTION

BRIDGE JOINT DEMOLITION

PROJECT NO. 15BPR.56 BEAUFORT \_\_\_ COUNTY BRIDGE NO. 060077

SHEET 10 OF 10




STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION


SUPERSTRUCTURE PLAN OF SPANS AND APPROACH SLAB 2


DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED


4FFE39D1431B407... 01/27/2022 SHEET NO. **REVISIONS** NO. BY: S4-17 DATE: DATE: TOTAL SHEETS


S. T. SANDOR \_ DATE : <u>07/2021</u> DRAWN BY : \_ DATE : 12/2021 W.C.SMITH CHECKED BY :
















# TYPICAL SECTION (EXISTING)



# TYPICAL SECTION (INTERMEDIATE)



TYPICAL SECTION

\_\_ DATE : <u>08/2020</u> M.K.BEARD DRAWN BY : \_ DATE : 10/2020 W.C.SMITH CHECKED BY :

(PROPOSED)


# NOTES

SEE TRANSPORTATION MANAGEMENT PLANS FOR LANE WIDTHS, SEQUENCING AND OTHER TRAFFIC CONTROL MEASURES FOR STAGING OF SURFACE PREPARATION AND SILANE DECK TREATMENT.

GIRDERS ARE AASHTO TYPE IV PRESTRESSED CONCRETE GIRDERS.


FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.



DETAIL FOR SILANE DECK TREATMENT

> PROJECT NO. 15BPR.56 PITT \_\_\_ COUNTY BRIDGE NO. 730127





STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH SUPERSTRUCTURE

TYPICAL SECTION FOR SILANE DECK TREATMENT

4FFE39D1431B407 DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS SHEET NO. S5-6 NO. BY: DATE: DATE: TOTAL SHEETS 13





# **NOTES**

FINAL JOINT SEALS SHALL NOT BE INSTALLED UNTIL THE OVERLAY OR SEALANT WORK IS COMPLETE.

THE CONTRACTOR SHALL FIELD VERIFY THE EXISTING JOINT OPENING PRIOR TO ORDERING JOINT SEAL MATERIAL. IF THE ACTUAL JOINT OPENING VARIES FROM THE OPENING INDICATED IN THE DETAILS BY MORE THAN 1/4", NOTIFY THE ENGINEER.

THE MANUFACTURER IS TO PROVIDE THE NOMINAL UNCOMPRESSED SEAL WIDTH OF THE FOAM JOINT SEAL FOR THE SIZE OF THE OPENING ON THE PLANS AND ACCOMODATE THE MINIMUM EXPANSION SHOWN ON THE PLANS.

FOAM JOINTS SHALL BE INSTALLED AS PER THE MANUFACTURER'S RECOMMENDATIONS.

THE CONTRACTOR SHALL TAKE CARE DURING JOINT REHAB OPERATIONS NOT TO DROP ANY MATERIAL BELOW THE BRIDGE, WITHOUT PROTECTIVE DEVICES BELOW TO CATCH THE MATERIAL. ANY MATERIAL THAT FALLS BELOW THE BRIDGE SHALL BE CONTAINED, REMOVED AND DISPOSED OF BY THE CONTRACTOR AT NO EXTRA COST TO THE DEPARTMENT. IF THE ENGINEER DETERMINES THAT THE PROTECTIVE DEVICES ARE NOT ADEQUATE OR NOT BEING EMPLOYED, THE WORK SHALL BE SUSPENDED UNTIL ADEQUATE PROTECTION IS PROVIDED.

THE CONTRACTOR WILL NOT BE PERMITTED TO FORM THE JOINTS IN LIEU OF SAWING THE JOINT.

THE INSTALLED FOAM JOINTS SHALL BE WATER TIGHT.

FOR FOAM JOINT SEALS FOR PRESERVATION, SEE SPECIAL PROVISIONS.

THE CONTRACTOR SHALL SAW CUT TO A NOMINAL DEPTH OF  $\frac{1}{2}$ " BUT REINFORCING STEEL SHALL NOT BE DAMAGED CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO VERIFY THAT SAWCUT DEPTH WILL NOT DAMAGE EXISTING REINFORCING STEEL.

QUANTITIES SHOWN IN THE ELASTOMERIC CONCRETE FOR PRESERVATION TABLE ARE BASED ON THE MINIMUM JOINT DEMOLITION SHOWN.

FINAL SURFACE OF THE JOINT DEMOLITION AREA PRIOR TO PLACEMENT OF CONCRETE REPAIR MATERIAL OR ELASTOMERIC CONCRETE SHALL BE REASONABLY FLAT AND LEVEL. THE ENGINEER SHALL DETERMINE ACCEPTABILITY OF THE SURFACE.

FOR EXCAVATION BELOW THE BOTTOM OF PLANNED JOINT DEMOLITION, CONCRETE FOR DECK REPAIR SHALL BE PLACED IN THE EXCAVATED AREA TO THE ELEVATION AT THE BOTTOM OF THE PROPOSED ELASTOMERIC CONCRETE FOR PRESERVATION HEADERS SHOWN.

FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.

FOR ELASTOMERIC CONCRETE FOR PRESERVATION, SEE SPECIAL PROVISIONS.

FOR CONCRETE FOR DECK REPAIR, SEE SPECIAL PROVISIONS.

PROJECT NO. 15BPR.56

BEAUFORT COUNTY

BRIDGE NO. 730127

SEAL 26445

NONEER OF SEAL 26445

P. Korey Newton

DEPARTMENT OF TRANSPORTATION
STANDARDS

STATE OF NORTH CAROLINA

JOINT REPAIR DETAILS

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 REVISIONS SHEET NO. BY: DATE: NO. BY: DATE: STEETS

1 3 13

SHEET 1 OF 2

2/21/2022 R:\Structures\Plans\Bridge\_730127\406\_013\_15BPR56\_SMU\_JT1\_007\_730127.dgn

CHECKED BY: P. K. NEWTON

DRAWN BY: NAP 08/2018

CHECKED BY: -

DATE: 01/2022

JOINT REPAIR QUANTITY TABLE				
	ESTIMATED	ACTUAL		
FOAM JOINT SEALS FOR PRESERVATION	330.0 L.F.			

ELASTOMERIC CONCRETE FOR PRESERVATION			
LOCATION	ESTIMATED (CU. FT.)	ACTUAL (CU. FT.)	
END BENT 1	7.5		
BENT 2	7.5		
BENT 4	7.5		
BENT 6	7.5		
BENT 8	7.5		
BENT 10	7.5		
BENT 12	7.5		
BENT 14	7.5		
BENT 16	7.5		
BENT 18	7.5		
END BENT 2	7.5		
TOTAL	82.5		

SAWED JOINT OP	ENING TA	ABLE	
	SAWED (PERPENI	JOINT OPENII DICULAR TO JO	NG DINT)
LOCATION	AT 45°	AT 60°	AT 90°
END BENT 1	21/8"	2"	111/16"
BENT 2	2 <sup>15</sup> ⁄16"	2 <sup>5</sup> / <sub>8</sub> "	2½6"
BENT 4	2 <sup>15</sup> ⁄16"	25/8"	2½6"
BENT 6	2 <sup>15</sup> ⁄16"	2 <sup>5</sup> / <sub>8</sub> "	2½6"
BENT 8	2 <sup>15</sup> ⁄16"	2 <sup>5</sup> / <sub>8</sub> "	2½16"
BENT 10	2 <sup>15</sup> ⁄16"	2 <sup>5</sup> / <sub>8</sub> "	2½16"
BENT 12	2 <sup>15</sup> ⁄16"	2 <sup>5</sup> / <sub>8</sub> "	2½6"
BENT 14	2 <sup>15</sup> ⁄16"	25/8"	2½6"
BENT 16	3"	23/4"	21/4"
BENT 18	3"	23/4"	21/4"
END BENT 2	21/8"	2"	1 <sup>11</sup> ⁄16"

PROJECT NO. 15BPR.56 PITT \_ COUNTY 730127

BRIDGE NO.\_\_\_\_

SHEET 2 OF 2

DocuSigned by:
P. Korey Newton


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH


JOINT REPAIR DETAILS


4FFE39D1431B407... 02/23/2022 REVISIONS SHEET NO. DATE: NO. BY: S5-8 DATE: TOTAL SHEETS 13

\_\_ DATE : <u>01/2022</u> \_\_ DATE : <u>01/2022</u> DRAWN BY: S.T.SANDOR
CHECKED BY: W.C.SMITH DESIGN ENGINEER OF RECORD: \_ \_ DATE : \_\_

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED









FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT, SEE SPECIAL PROVISIONS.

FOR SECTION B-B, SEE "JOINT REPAIR DETAILS" SHEET.

FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.


# AS-BUILT REPAIR QUANTITY TABLE

DECK SURFACE REPAIRS	S - SPANS M	THRU P
	ESTIMATE	ACTUAL
SHOTBLASTING BRIDGE DECK	1,300.0 SQ. YDS.	
SILANE DECK TREATMENT	1,300.0 SQ. YDS.	
CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT	0.0 SQ.FT.	
BRIDGE JOINT DEMOLITION	60.0 SQ. FT.	
		_

SHOTBLASTING BRIDGE DECK AND SILANE DECK TREATMENT AREA

✓ ERI - EPOXY RESIN INJECTION

BRIDGE JOINT DEMOLITION



# PLAN OF SPANS (SPANS M & N)

BRIDGE JOINT @ JOINT @ BENT 15

BARRIER RAIL

PLAN OF SPANS

(SPANS Q & P)

PROJECT NO. 15BPR.56
PITT COUNTY
BRIDGE NO. 730127

SHEET 4 OF 5

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUPERSTRUCTURE PLAN OF SPANS

DocuSigned by:

P. Korey Newton

4FFE39D1431B407...
02/23/2022

REVISIONS

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2

REVISIONS

REVISIONS

SHEET NO. BY: DATE: No. BY: DATE: S5-12

TOTAL SHEETS

13


2/21/2022 R:\Structures\Plans\Bridge\_730127\406\_023\_15BPR56\_SMU\_DSR4\_012\_730127.dgn ssandor

\_\_\_ DATE : <u>07/2021</u> \_\_\_ DATE : <u>07/2021</u>

S. T. SANDOR

W.C.SMITH

DRAWN BY : .



# STANDARD NOTES

# DESIGN DATA:

SPECIFICATIONS	A.A.S.H.T.O. (CURRENT)
LIVE LOAD	SEE PLANS
IMPACT ALLOWANCE	SEE A.A.S.H.T.O.
STRESS IN EXTREME FIBER OF STRUCTURAL STEEL - AASHTO M270 GRADE 36	20,000 LBS.PER SQ.IN
- AASHTO M270 GRADE 50W	27,000 LBS. PER SQ. IN
- AASHTO M270 GRADE 50	27,000 LBS. PER SQ. IN
REINFORCING STEEL IN TENSION - GRADE 60	24,000 LBS. PER SQ. IN
CONCRETE IN COMPRESSION	1,200 LBS. PER SQ. IN.
CONCRETE IN SHEAR	SEE A.A.S.H.T.O.
STRUCTURAL TIMBER - TREATED OR UNTREATED EXTREME FIBER STRESS	1,800 LBS. PER SQ. IN.
COMPRESSION PERPENDICULAR TO GRAIN OF TIMBER	375 LBS. PER SQ. IN.
EQUIVALENT FLUID PRESSURE OF EARTH	30 LBS.PER CU.FT. (MINIMUM)

### MATERIAL AND WORKMANSHIP:

EXCEPT AS MAY OTHERWISE BE SPECIFIED ON PLANS OR IN THE SPECIAL PROVISIONS, ALL MATERIAL AND WORKMANSHIP SHALL BE IN ACCORDANCE WITH THE 2018 "STANDARD SPECIFICATIONS FOR ROADS AND STRUCTURES" OF THE N. C. DEPARTMENT OF TRANSPORTATION.

STEEL SHEET PILING FOR PERMANENT OR TEMPORARY APPLICATIONS SHALL BE HOT ROLLED.

### CONCRETE:

UNLESS OTHERWISE REQUIRED ON PLANS, CLASS A CONCRETE SHALL BE USED FOR ALL PORTIONS OF ALL STRUCTURES WITH THE EXCEPTION THAT: CLASS AA CONCRETE SHALL BE USED IN BRIDGE SUPERSTRUCTURES, ABUTMENT BACKWALLS, AND APPROACH SLABS; AND CLASS B CONCRETE SHALL BE USED FOR SLOPE PROTECTION AND RIP RAP.

#### CONCRETE CHAMFERS:

UNLESS OTHERWISE NOTED ON THE PLANS, ALL EXPOSED CORNERS ON STRUCTURES SHALL BE CHAMFERED 3/4" WITH THE FOLLOWING EXCEPTIONS: TOP CORNERS OF CURBS MAY BE ROUNDED TO 11/2" RADIUS WHICH IS BUILT INTO CURB FORMS; CORNERS OF TRANSVERSE FLOOR EXPANSION JOINTS SHALL BE ROUNDED WITH A 1/4" FINISHING TOOL UNLESS OTHERWISE REQUIRED ON PLANS; AND CORNERS OF EXPANSION JOINTS IN THE ROADWAY FACES AND TOPS OF CURBS AND SIDEWALKS SHALL BE ROUNDED TO A 1/4" RADIUS WITH A FINISHING STONE OR TOOL UNLESS OTHERWISE REQUIRED ON PLANS.

### DOWELS:

DOWELS WHEN INDICATED ON PLANS AS FOR CULVERT EXTENSIONS, SHALL BE EMBEDDED AT LEAST 12" INTO THE OLD CONCRETE AND GROUTED INTO PLACE WITH 1:2 CEMENT MORTAR.

# ALLOWANCE FOR DEAD LOAD DEFLECTION, SETTLEMENT,

# ETC. IN CASTING SUPERSTRUCTURES:

BRIDGES SHALL BE BUILT ON THE GRADE OR VERTICAL CURVE SHOWN ON PLANS. SLABS, CURBS AND PARAPETS SHALL CONFORM TO THE GRADE OR CURVE.

ALL DIMENSIONS WHICH ARE GIVEN IN SECTION AND ARE AFFECTED BY DEAD LOAD DEFLECTIONS ARE DIMENSIONS AT CENTER LINE OF BEARING UNLESS OTHERWISE NOTED ON PLANS. IN SETTING FORMS FOR STEEL BEAM BRIDGES AND PRESTRESSED CONCRETE GIRDER BRIDGES, ADJUSTMENTS SHALL BE MADE DUE TO THE DEAD LOAD DEFLECTIONS FOR THE ELEVATIONS SHOWN. WHERE BLOCKS ARE SHOWN OVER BEAMS FOR BUILDING UP TO THE SLAB, THE VERTICAL DIMENSIONS OF THE BLOCKS SHALL BE ADJUSTED BETWEEN BEARINGS TO COMPENSATE FOR DEAD LOAD DEFLECTIONS, VERTICAL CURVE ORDINATE, AND ACTUAL BEAM CAMBER. WHERE BOTTOM OF SLAB IS IN LINE WITH BOTTOM OF TOP FLANGES, DEPTH OF SLAB BETWEEN BEARINGS SHALL BE ADJUSTED TO COMPENSATE FOR DEAD LOAD DEFLECTION, VERTICAL CURVE ORDINATE, AND ACTUAL BEAM CAMBER.

IN SETTING FALSEWORK AND FORMS FOR REINFORCED CONCRETE SPANS, AN ALLOWANCE SHALL BE MADE FOR DEAD LOAD DEFLECTIONS, SETTLEMENT OF FALSEWORK, AND PERMANENT CAMBER WHICH SHALL BE PROVIDED FOR IN ADDITION TO THE ELEVATIONS SHOWN. AFTER REMOVAL OF THE FALSEWORK, THE FINISHED STRUCTURES SHALL CONFORM TO THE PROFILE AND ELEVATIONS SHOWN ON THE PLANS AND CONSTRUCTION ELEVATIONS FURNISHED BY THE ENGINEER.

DETAILED DRAWINGS FOR FALSEWORK OR FORMS FOR BRIDGE SUPERSTRUCTURE AND ANY STRUCTURE OR PARTS OF A STRUCTURE AS NOTED ON THE PLANS SHALL BE SUBMITTED TO THE ENGINEER FOR APPROVAL BEFORE CONSTRUCTION OF THE FALSEWORK OR FORMS IS STARTED.

#### REINFORCING STEEL:

ALL REINFORCING STEEL SHALL BE DEFORMED. DIMENSIONS RELATIVE TO PLACEMENT OF REINFORCING ARE TO CENTERS OF BARS UNLESS OTHERWISE INDICATED IN THE PLANS. DIMENSIONS ON BAR DETAILS ARE TO CENTERS OF BARS OR ARE OUT TO OUT AS INDICATED ON PLANS.

WIRE BAR SUPPORTS SHALL BE PROVIDED FOR REINFORCING STEEL WHERE INDICATED ON THE PLANS. WHEN BAR SUPPORT PIECES ARE PLACED IN CONTINUOUS LINES, THEY SHALL BE SO PLACED THAT THE ENDS OF THE SUPPORTING WIRES SHALL BE LAPPED TO LOCK LEGS ON ADJOINING PIECES.

# STRUCTURAL STEEL:

AT THE CONTRACTOR'S OPTION, HE MAY SUBSTITUTE 1/8" Ø SHEAR STUDS FOR THE 3/4" Ø STUDS SPECIFIED ON THE PLANS. THIS SUBSTITUTION SHALL BE MADE AT THE RATE OF 3 - 1/8" Ø STUDS FOR 4 - 3/4" Ø STUDS, AND STUD SPACING CHANGES SHALL BE MADE AS NECESSARY TO PROVIDE THE SAME EQUIVALENT NUMBER OF 1/8" Ø STUDS ALONG THE BEAM AS SHOWN FOR 3/4" Ø STUDS BASED ON THE RATIO OF 3 - 1/8" Ø STUDS FOR 4 - 3/4" Ø STUDS. STUDS OF THE LENGTH SPECIFIED ON THE PLANS MUST BE PROVIDED. THE MAXIMUM SPACING SHALL BE 2'-O".

EXCEPT AT THE INTERIOR SUPPORTS OF CONTINUOUS BEAMS WHERE THE COVER PLATE IS IN CONTACT WITH BEARING PLATE, THE CONTRACTOR MAY, AT HIS OPTION, SUBSTITUTE FOR THE COVER PLATES DESIGNATED ON THE PLANS COVER PLATES OF THE EQUIVALENT AREA PROVIDED THESE PLATES ARE AT LEAST 16" IN THICKNESS AND DO NOT EXCEED A WIDTH EQUAL TO THE FLANGE WIDTH LESS 2" OR A THICKNESS EQUAL TO 2 TIMES THE FLANGE THICKNESS. THE SIZE OF FILLET WELDS SHALL CONFORM TO THE REQUIREMENTS OF THE CURRENT ANSI/AASHTO/AWS "BRIDGE WELDING CODE". ELECTROSLAG WELDING WILL NOT BE PERMITTED.

WITH THE SOLE EXCEPTION OF EDGES AT SURFACES WHICH BEAR ON OTHER SURFACES, ALL SHARP EDGES AND ENDS OF SHAPES AND PLATES SHALL BE SLIGHTLY ROUNDED BY SUITABLE MEANS TO A RADIUS OF APPROXIMATELY 1/6 INCH OR EQUIVALENT FLAT SURFACE AT A SUITABLE ANGLE PRIOR TO PAINTING, GALVANIZING, OR METALLIZING.

### HANDRAILS AND POSTS:

METAL STANDARDS AND FACES OF THE CONCRETE END POSTS FOR THE METAL RAIL SHALL BE SET NORMAL TO THE GRADE OF THE CURB, UNLESS OTHERWISE SHOWN ON PLANS. THE METAL RAIL AND TOPS OF CONCRETE POSTS USED WITH THE ALUMINUM RAIL SHALL BE BUILT PARALLEL TO THE GRADE OF THE CURB.

METAL HANDRAILS SHALL BE IN ACCORDANCE WITH THE PLANS. RAILS SHALL BE AS MANUFACTURED FOR BRIDGE RAILING. CASTINGS SHALL BE OF A UNIFORM APPEARANCE. FINS AND OTHER DEFORMATIONS RESULTING FROM CASTING OR OTHERWISE SHALL BE REMOVED IN A MANNER SO THAT A UNIFORM COLORING OF THE COMPLETED CASTING SHALL BE OBTAINED. CASTINGS WITH DISCOLORATIONS OR OF NON-UNIFORM COLORING WILL NOT BE ACCEPTED. CERTIFIED MILL REPORTS ARE REQUIRED FOR METAL RAILS AND POSTS.

### SPECIAL NOTES:

GENERALLY, IN CASE OF DISCREPANCY, THIS STANDARD SHEET OF NOTES SHALL GOVERN OVER THE SPECIFICATIONS, BUT THE REMAINDER OF THE PLANS SHALL GOVERN OVER NOTES HEREON, AND SPECIAL PROVISIONS SHALL GOVERN OVER ALL. SEE SPECIFICATIONS ARTICLE 105-4.

ENGLISH