REPAIR QUANTITY TABLE **NOTES** REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE UNDERSIDE OF DECK BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE **ESTIMATE** DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE AREA ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME SHOTCRETE REPAIRS REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE REPAIR QUANTITY TABLE. UNDERSIDE OF DECK & OVERHANG 0 0 CONTRACTOR SHALL SAWCUT TO A NOMINAL DEPTH OF $\frac{1}{2}$ " BUT REINFORCING STEEL SHALL NOT BE DAMAGED. CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO BENT DIAPHRAGMS 39.0 13.0 VERIFY THAT SAWCUT WILL NOT DAMAGE EXISTING REINFORCING STEEL. FOR CONCRETE GIRDER AND DIAPHRAGM REPAIR DETAILS, SEE PRESTRESSED AREA VOLUME GIRDER REPAIRS CONCRETE GIRDER AND DIAPHRAGM REPAIR DETAILS SHEET S2-5. FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS. PC GIRDERS 2.0 0.5 VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, 1" BEHIND REBAR AND MIN. 2" CLEARANCE TO SAWCUT. © BENT 1 _ 2.1 SF ·-· GIRDER #1 -·-·-1.0 SF 5.8 SF 1.0 SF BENT DIAPHRAGM END BENT — DIAPHRAGMS 1.0 SF — | \ \ \ ___ 3.9 SF FILL FACE @ _ END BENT 1 5.5 SF 101'-10¹³/₁₆" (SPAN A) 105'-0⁵/₈" (SPAN B) $206'-11\frac{7}{16}$ " (FILL FACE TO FILL FACE) PROJECT NO. HI-0007 WILSON BRIDGE NO. ___ PLAN OF SPANS - UNDERSIDE REPAIRS REPAIR KEY STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION DIAPHRAGM REPAIR PRESTRESSED CONCRETE GIRDER REPAIR DRAWN BY: G. AYES DATE: 4/2022 CHECKED BY: A. Y. GODFREY/A. G. ABRAHA DATE: 5/2022 DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED DESIGN ENGINEER OF RECORD: _

6/22/2022 S:\DPG1\Division4\HI-0007\Plans\970244\402_007_HI-0007_SMU_G*_S2-4_970244.dgn aabraha

SUPERSTRUCTURE CONCRETE REPAIRS

FILL FACE @

END BENT 2

COUNTY

970244

QUANTITIES

ACTUAL

VOLUME

VOLUME

AREA

SF

AREA SF

SHEET NO REVISIONS S2-4