



REPAIR QUANTITY TABLE		
SLOPE PROTECTION @ BRIDGE 970287	POURABLE SILICONE JOINT SEALANT	
	ESTIMATE	ACTUAL
END BENT 1	30.0	
END BENT 2	25.0	


NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

SEAL CRACKS IDENTIFIED AND JOINTS ALONG THE TOP OF SLOPE PROTECTION AND BERM WITH POURABLE SILICONE JOINT SEALANT. FOR DETAILS SEE PROPOSED JOINT SEAL DETAILS, SHEET S2-6.



SLOPE PROTECTION REPAIR LOCATIONS




SLOPE PROTECTION TYPICAL SECTION ALONG C_L BRIDGE

REPAIR KEY

~~~~~ SLOPE PROTECTION CRACKS

PROJECT NO. **HI-0007**  
**WILSON** COUNTY  
 BRIDGE NO. **970287**



STATE OF NORTH CAROLINA  
 DEPARTMENT OF TRANSPORTATION  
 RALEIGH

**SLOPE PROTECTION  
 REPAIR DETAILS**

DRAWN BY : G. AYES DATE : 5/2022  
 CHECKED BY : A. G. ABRAHA DATE : 5/2022  
 DESIGN ENGINEER OF RECORD: \_\_\_\_\_ DATE : \_\_\_\_\_

DOCUMENT NOT CONSIDERED  
 FINAL UNLESS ALL  
 SIGNATURES COMPLETED

| REVISIONS |     |       |     |     |       | SHEET NO.<br>S4-8<br>TOTAL SHEETS<br>8 |
|-----------|-----|-------|-----|-----|-------|----------------------------------------|
| NO.       | BY: | DATE: | NO. | BY: | DATE: |                                        |
| 1         |     |       | 3   |     |       |                                        |
| 2         |     |       | 4   |     |       |                                        |