

AS-BUILT REPAIR QUANTITY TABLE BENT 71 SF - SF - CF - LF SF PILE CONCRETE RESTORATION 16.0 SF | 6.3 CF FRP PROTECTIVE SYSTEM AWL 126.5 SF FRP PROTECTIVE SYSTEM BWL 49.5 SF DENIT 70

BEN1 (2							
CAP REPAIRS							
SHOTCRETE REPAIRS	- SF	- CF	SF	CF			
EPOXY RESIN INJECTION	_	LF		LF			
PILE REPAIRS							
PILE CONCRETE RESTORATION	33.8 SF	13.6 CF	SF	CF			
FRP PROTECTIVE SYSTEM AWL	176.	0 SF					
FRP PROTECTIVE SYSTEM BWL	66.0 SF						

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2 CL. TO SAWCUT. SEE REPAIR DETAILS.

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE "TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS" & "PILE CONCRETE RESTORATION DETAILS" SHEETS.

FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE "PILE FRP PROTECTIVE SYSTEM DETAILS" SHEET.

ESTIMATED PILE CRACK QTY. TABLE									
		NW	W	SW	S	SE	E	NE	Ν
BENT 71	PILE 1	_	_	_	_	2	_	5	_
	PILE 2	_	_	_	_	_	_	_	-
	PILE 3	_	6	_	6	6	=	_	_
	PILE 4	_	3	2	_	_	-	_	5
	5 = 1 = 4								
	PILE 1	_	-	_	1	_	2	4	_
BENT 72	PILE 2	_	_	8	6	_	6	_	4
	PILE 3	_	_	3	_	6	_	_	4
	PILE 4	_	-	3	-	_	-	_	5
OTE, EAR THEARMATTAN AND RIF CANDITTAN AND V									

NOTE: FOR INFORMATION ON PILE CONDITION ONLY.

PROJECT NO. DARE

COUNTY

270009 BRIDGE NO.

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

BENT 71 & BENT 72

OCUMENT NOT CONSIDERE FINAL UNLESS ALL SIGNATURES COMPLETED

		SHEET NO					
ED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-151
	1			3			TOTAL SHEETS
)	2			4			355