

AS-BUILT REPAIR QUANTITY TABLE BENT 201 SF 1.0 SF | 0.5 CF - LF SF - SF 140.3 SF 54.9 SF BENT 202 SF 2.0 SF 1.0 CF - LF PILE CONCRETE RESTORATION 23.8 SF | 10.1 CF SF 122.0 SF

FOR CAP REPAIRS: VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2

54.9 SF

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE "TYPICAL CAP, COLUMN & UNDERDECK REPAIR DETAILS" & "PILE CONCRETE RESTORATION DETAILS" SHEETS.

FOR PILE CONCRETE RESTORATION, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM, SEE SPECIAL PROVISIONS.

FOR FRP PROTECTIVE SYSTEM DETAILS AND UNDERWATER MORTAR REPAIRS, SEE "PILE FRP PROTECTIVE SYSTEM DETAILS" SHEET.

ESITMATED FILE CRACK QIT. TABLE										
		NW	W	SW	S	SE	E	NE	Ν	
BENT 201	PILE 1	_	5	8	8	5	3	7	7	
	PILE 2	_	_	_	_	_	_	_	_	
	PILE 3	3	4	6	_	3	5	5	-	
	PILE 4	-	3	-	4	3	3	6	4	
BENT 202	PILE 1	_	3	_	_	6	_	_	5	
	PILE 2	_	_	_	_	_	_	_	_	
	PILE 3	3	3	_	_	5	_	_	3	
	PILE 4	_	3	2	3	3	5	6	_	
OTE FOR INFORMATION ON PILE CONDITION ONLY										

NOTE: FOR INFORMATION ON PILE CONDITION UNLY.

COUNTY

270009 BRIDGE NO.

DARE

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

BENT 201 & BENT 202

OCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

		SHEET NO.					
NO.	BY:	DATE:	NO.	BY:	DATE:	S-270	
1			3			TOTAL SHEETS	
2			4			355	