




PLAN - BOTTOM OF CAP



SPAN C VIEW - ELEVATION





VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1" BEHIND REBAR AND MINIMUM OF 2" CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE ``TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



SHOTCRETE REPAIR AREA

✓ ERI - EPOXY RESIN INJECTION

I-5950 PROJECT NO.___ **DAVIDSON** _ COUNTY

280137 BRIDGE NO.__

SHEET 2 OF 2

07/25/2022

SEAL 031583

Krishna P. Sedai

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

BENT 2 SPAN C FACE

SHEET NO.

S2-18

TOTAL SHEETS

REVISIONS NO. BY: DATE: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

__ DATE : <u>3/2022</u> __ DATE : <u>5/2022</u>

A. SORSENGINH

E.BAYISSA

DRAWN BY : .

CHECKED BY :