

+

+

	•						
DECK UNDERSIDE REPAIRS SPAN B	QUANTITIES						
	ESTI	MATE	ACTUAL				
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF			
UNDERSIDE OF DECK	0	0					
BENT DIAPHRAGM	32.9	16.5					
OVERHANG	6.0	2.0					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 2" CLEAR TO SAWCUT. SEE REPAIR DETAILS.

## AS-BUILT REPAIR QUANTITY TABLE

## NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

THE CONTRACTOR SHALL SAW CUT TO A NOMINAL DEPTH OF 1/2" BUT REINFORCING STEEL SHALL NOT BE DAMAGED.

THE CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO VERIFY THAT SAWCUT DEPTH WILL NOT DAMAGE EXISTING REINFORCING STEEL.

SHOTCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR UNDERSIDE DECK REPAIR, SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIR AREA



GIRDER NUMBER

	PROJEC	T NO.		I	-5950			
	[	DAVID	SC	DN	CC	UNTY		
	BRIDGE NO. 280146							
	SHEET 2 0	F 4						
07/25/2022 TH CAROL MARTH CAROL MARTH	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH							
SEAL O3I583 PRASAD	DECK UNDERSIDE REPAIR SPAN B							
Krishna P. Sedai EA6F794150BF4B7								
	REVISIONS SHEET NO							
DCUMENT NOT CONSIDERED	NO. BY:	DATE:	N0.	BY:	DATE:	S3-05		
FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		3 4			total sheets 15		