
DocuSign Envelope ID: B5DE3F97-6763-421C-95A1-4AF257E0EAEA


+

+

 \mathbb{M} \leftarrow \sim \geq \triangleleft Ш Н Ē \square لر لر لے



BENT 1 (WEST FACE)



	BENT 1
	(EAST FACE)
DRAWN BY :ALLEN J.MCSWAIN DATE :D1/2022 CHECKED BY :FIDEL L.FLORESDATE :01/2022	
DESIGN ENGINEER OF RECORD: DIEGO A. AGUIRRE DATE : D1/2022	

4/21/2022 I5915B_SMU_SBR01_480073.dgn daguirre

	LEGEND	
A 2	CONCRETE REPAIR AREA (CR)	
L L L L	SHOTCRETE REPAIR AREA (SCR)	SHO
	EPOXY RESIN INJECTION (ERI)	

, - - $\overline{}$

DOCUMENT	NOT	СО
FINAL SIGNATU		
JIONATU	NLJ	CON

AS-BUILT REPAIR QUANTITY TABLE				
	QUANTITIES			
	ESTI	MATE	ACT	UAL
HOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.
CAP/BACKWALL	-	-		
COLUMN/PILE	75.8	28.2		
ONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.
САР	-	_		
POXY RESIN INJECTION	LIN.	,FT.	LIN.	,FT.
CAP/BACKWALL	-	-		
COLUMN/PILE	-	-		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS" SHEETS.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE TABLE ABOVE.

CRACKING LOCATIONS AND QUANTITIES FOR LOCATIONS DESCRIBED AS ``SCATTERED THROUGHOUT'' IN THE INSPECTION REPORT ARE BASED ON THE BEST INFORMATION AVAILABLE. THE ENGINEER AND CONTRACTOR SHALL IDENTIFY AND REPAIR ALL CRACKS >=1/16" as described in the special PROVISIONS AT EACH BENT.

AVERAGE CONCRETE COVER IS EXPECTED TO BE FROM 2"TO 3" ON THE CAP AND FROM $1^{1}/_{2}$ " TO 2" ON THE PILES. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING EXCAVATION/ DEMOLITION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE "CONCRETE RESTORATION DETAILS" SHEETS.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

REPAIRS TO THE BENT CAP MAY REQUIRE BRIDGE JACKING.FOR BRIDGE JACKING, SEE SPECIAL PROVISIONS.

	PROJECT NO. <u>I-5915B</u> <u>IREDELL</u> COUNTY BRIDGE NO. <u>480073</u> Sheet 2 of 3
DocuSigned by SEAL Dicgo & Aguive 048223 4/29/2022	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE REPAIRS
KCA	BENT 1
KISINGER CAMPO	REVISIONS SHEET NO.
& ASSOCIATES ONSIDERED 301 FAYETTEVILLE ST., SUITE 1500 State State	NO.BY:DATE:S12-913TOTAL SHEETS
SALRALEIGH, NC 27601 (919) 882-7839MPLETEDNC FIRM LICENSE: C-1506	1 0 SHEETS 2 4 10