
+




+

BENT 1 (West face)

CHECKED BY :FIDEL L.FLORESDATE :01/2022DESIGN ENGINEER OF RECORD:DIEGO A.AGUIRREDATE :01/2022	DRAWN BY :	ALLEN J.MCSWAIN	DATE : <u>01/2022</u>
DESIGN ENGINEER OF RECORD:	CHECKED BY :	FIDEL L.FLORES	DATE : <u>01/2022</u>
	DESIGN ENGINEER	OF RECORD:A.AGUIRRE	DATE : <u>01/2022</u>

4/21/2022 I5915B_SMU_SBR01_480096.dgn daguirre

LEGEND		
	CONCRETE REPAIR AREA (CR)	
	SHOTCRETE REPAIR AREA (SCR)	Sł
	EPOXY RESIN INJECTION (ERI)	
τ <u>.</u>		





DOCUMENT	NOT	С
FINAL	UNL	ES
SIGNATU	res	С(

AS-BUILT REPAIR QUANTITY TABLE QUANTITIES ESTIMATE ACTUAL AREA SQ.FT. VOLUME CU.FT. SHOTCRETE REPAIRS AREA SQ.FT VOLUME CU.FT. 3.7 CAP/BACKWALL 1.3 12.4 4.3 COLUMN/PILE VOLUME CU.FT. AREA SQ.FT VOLUME CU.FT. AREA SQ.FT. CONCRETE REPAIRS CAP _ _ EPOXY RESIN INJECTION LIN.FT. LIN.FT. CAP/BACKWALL — COLUMN/PILE -

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS" SHEETS.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE.IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE TABLE ABOVE.

CRACKING LOCATIONS AND QUANTITIES FOR LOCATIONS DESCRIBED AS "SCATTERED THROUGHOUT" IN THE INSPECTION REPORT ARE BASED ON THE BEST INFORMATION AVAILABLE. THE ENGINEER AND CONTRACTOR SHALL IDENTIFY AND REPAIR ALL CRACKS >=1/16" AS DESCRIBED IN THE SPECIAL PROVISIONS AT EACH BENT.

AVERAGE CONCRETE COVER IS EXPECTED TO BE FROM 2"TO 3" ON THE CAP AND FROM $1\frac{1}{2}$ "TO 2" ON THE PILES. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING EXCAVATION/ DEMOLITION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE "CONCRETE RESTORATION DETAILS" SHEETS.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

REPAIRS TO THE BENT CAP MAY REQUIRE BRIDGE JACKING.FOR BRIDGE JACKING, SEE SPECIAL PROVISIONS.

	PROJECT NO. <u>I-5915B</u> <u>IREDELL</u> COUNTY BRIDGE NO. <u>480096</u>			
A111111111	SHEET 2 OF 3			
DocuSigned by: Dicas & Agurn Otherson Officer 47269F43B320323D4FB Dicas & Agurn Otherson Officer Dicas & Agurn Officer Dicas	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE REPAIRS			
KCA	BENT 1			
KISINGER CAMPO	REVISIONS SHEET NO.			
& ASSOCIATESCONSIDERED301 FAYETTEVILLE ST., SUITE 1500	NO. BY: DATE: NO. BY: DATE: S13-8			
SSALLRALEIGH, NC 27601 (919) 882-7839OMPLETEDNC FIRM LICENSE: C-1506	1 3 TOTAL SHEETS 2 4 9			