
BARRIER RAIL





**EXPANSION JOINT DETAILS** 

## SUGGESTED REPAIR INSTALLATION PROCEDURE

- 1. LOOSEN THE EXISTING SCREWS AND HOLD-DOWN PLATES TO REMOVE AND REPLACE THE EXISTING GLAND.
- 2. REMOVE THE EXISTING NEOPRENE SEALANT AND CLEAN THE EXISTING BASE ANGLE AND BOLT HOLES OF OIL, GREASE AND OTHER LATENTS.
- 3. LAY THE NEW GLAND ON THE BASE ANGLE AND FIELD MARK THE NEW GLAND FOR THE BOLT HOLES. HOLES IN THE NEW GLAND SHALL BE PUNCHED  $\frac{7}{8}$ " IN DIAMETER WITH A HAND PUNCH.
- 4. IN ORDER TO CHECK FOR PROPER ALIGNMENT, PLACE THE NEW GLAND AND HOLD-DOWN PLATES ON THE BASE ANGLE. DO NOT APPLY NEW NEOPRENE SEALANT. BOLT THE HOLD-DOWN PLATES TO THE BASE ANGLE, BUT DO NOT TIGHTEN. THE ENGINEER WILL INSPECT THE JOINT SEAL DEVICE FOR PROPER ALIGNMENT.
- 5. AFTER INSPECTION, REMOVE THE HOLD-DOWN PLATES AND NEW GLAND. APPLY NEW NEOPRENE SEALANT TO THE BASE ANGLE IN ACCORDANCE WITH THE "INSTALLATION SKETCH". PLACE NEW GLAND AND HOLD-DOWN PLATES ON THE BASE ANGLE. BOLT THE HOLD-DOWN PLATES TO THE BASE ANGLE ASSEMBLY AND TORQUE THE SCREWS TO 88 FT-LBS WITH A TORQUE WRENCH. CHECK THE TORQUE AFTER THREE (3) HOURS AND, IF NECESSARY, RETIGHTEN TO 88 FT-LBS A FINAL CHECK SHALL BE MADE AT SEVEN (7) DAYS. TORQUE SHALL NOT BE LESS THAN 80 FT-LBS AFTER SEVEN (7) DAYS.
- 6. AFTER PROPER TORQUING, CLEAN THE BOLT HOLE RECESSES AND THE RECESS BETWEEN THE JOINT SEAL DEVICE AND CONCRETE. COMPLETELY FILL THESE RECESSES WITH NEW NEOPRENE SEALANT.
- 7. CONDUCT WATER-TIGHTNESS TEST.

	DIM 'A' MOVEMENT AT JOINT	
LOCATION	PERPENDICULAR JOINT OPENING AT 51°F	
BENT 1	1%"	
BENT 2	15/8"	
·		





I-6039 PROJECT NO. NEW HANOVER \_ COUNTY 640059 BRIDGE NO. SHEET 3 OF 3 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

JOINT DETAILS

SHEET NO REVISIONS S4-6 DATE: BY: DATE: BY:

**INSTALLATION SKETCH** 

**BOLT HOLE** 

i-----

PLAN VIEW

4/17/2023 640059\_I6039\_SMU\_JT03.dgn

DATE: 01/2023

JASON M. DEBONE

CHECKED BY: ALLEN J. MCSWAIN

DESIGN ENGINEER OF RECORD: JACOB H. DUKE

DATE: 01/2023

01/2023 ALLEN J. MCSWAIN

DOCUMENT NOT CONSIDERED FINAL 301 FAYETTEVILLE ST., SUITE 1500 RALEIGH, NC 27601 (919) 882-7839 NC FIRM LICENSE: C-1506

043777

**NEOPRENE SEALANT** 

ADEQUATE PROTECTION IS PROVIDED.

**GENERAL NOTES** 

OPENING PRIOR TO ORDERING JOINT SEAL MATERIAL. IF THE

INDICATED IN THE DETAILS BY MORE THAN  $\frac{1}{4}$ ", NOTIFY THE

THE MANUFACTURER IS TO PROVIDE THE NOMINAL GLAND

CONTRACTOR SHALL FIELD VERIFY THE EXISTING JOINT

ACTUAL JOINT OPNEING VARIES FROM THE OPENING

ENGINEER.

MOVEMENTS.

THE CONTRACTOR SHALL TAKE CARE DURING JOINT REHAB OPERATIONS NOT TO DROP ANY MATERIAL BELOW THE BRIDGE, WITHOUT PROTECTIVE DEVICES BELOW TO CATCH THE MATERIAL. ANY MATERIAL THAT FALLS BELOW THE BRIDGE SHALL BE CONTAINED, REMOVED AND DISPOSED OF BY THE CONTRACTOR AT NO EXTRA COST TO THE DEPARTMENT. IF THE ENGINEER DETERMINES THAT THE PROTECTIVE DEVICES ARE NOT ADEQUATE OR NOT BEING EMPLOYED, THE WORK SHALL BE SUSPENDED UNTIL

RETAIN ALL EXISTING HOLD-DOWN PLATES AND HARDWARE. CLEAN AND REPAIR AS NEEDED. CONTRACTOR SHALL REPLACE DAMAGED HOLD-DOWN PLATES AND/OR HARDWARE AS NEEDED OR DIRECTED BY THE ENGINEER AT NO EXTRA COST TO THE DEPARTMENT.

ALL HOLD-DOWN SCREWS SHALL CONFORM TO ASTM F593 ALLOY 304 STAINLESS STEEL AND WASHERS SHALL CONFORM TO ASTM F844 EXCEPT THEY SHALL BE MADE FROM ALLOY 304 STAINLESS STEEL

A PREMOLDED CORRUGATED OR NON-CORRUGATED GLAND SHALL BE 130°.

THE FINISHED EXPANSION SEAL DEVICE SHALL BE A MINIMUM SLAB.

FOR EXPANSION JOINT SEAL REPAIR, SEE SPECIAL PROVISIONS.

NO SEPARATE PAYMENT WILL BE MADE FOR REMOVING AND REINSTALLING MEDIAN AND BARRIER RAIL COVER PLATES. THE ENTIRE COST OF THIS WORK SHALL BE INCLUDED IN THE LINEAR FEET PRICE BID FOR "EXPANSION JOINT SEALS FOR PRESERVATION".