


SPAN C

BEAM REPAIR QUANTITIY TABLE								
	BOLTED STEEL PLATES		STEEL PLATES		STEEL DIAPHRAGM		BEAM REPAIR CUT-OUT	
	LBS.		LBS.		LBS.		LBS.	
	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL
	0.0		191.0		0.0		0.0	

ANTICIPATED STEEL REPAIR LOCATIONS							
REPAIR TYPE	BEAM	LOCATION	DIM. "A"	DIM. "B''	DIM. "C"	DIM. "D''	
W	1	BENT 2	18"	16"			
W	1	BENT 3	15"	15"			

(SEE SHEETS S2-26, S2-27 AND S2-28 FOR BEAM REPAIR DETAILS AND DIMENSIONS.)


S. T. SANDOR	DATE : <u>1/31/23</u>
W.C.SMITH	DATE : <u>5/31/23</u>



LIMITS OF ZONE PAINTING

DECK UNDERSIDE	REPAIR	QUANT	ITY TA	BLE		
DECK UNDERSIDE REPAIRS	QUANTITIES					
SPAN C	ESTIN	МАТЕ	ACTUAL			
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
UNDERSIDE OF DECK	5.0	1.6				
CONCRETE DIAPHRAGM	33.0	24.1				
OVERHANG	2.0	0.6				
CONCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
UNDERSIDE OF DECK	0	0				
CONCRETE DIAPHRAGM	0	0				
OVERHANG	0	0				
EPOXY RESIN INJECTION	LINEAR FT		LINEAR FT			
CONCRETE DIAPHRAGM	16.0					
CONCRETE OVERHANG	0					
ZONE PAINTING		AREA SF		AREA SF		
BEAM ENDS		225.4				


VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 2" CLEAR TO SAWCUT. SEE REPAIR DETAILS.




SHOTCRETE REPAIR AREA



CONCRETE REPAIR AREA



ZONE PAINTING



EPOXY RESIN INJECTION



WEB PLATING REPAIR

BOLTED WEB PLATE REPAIR

BOTTOM FLANGE PLATING REPAIR

BOLTED FLANGE PLATE REPAIR

BEAM REPAIR CUT-OUT

B-5981 PROJECT NO. ____

DUPLIN

__ COUNTY

BRIDGE NO. 300017

SHEET 3 OF 5

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

DECK UNDERSIDE REPAIR SPAN C

William C. Smith

SEAL 7 054816

SHEET NO. REVISIONS 10/24/2023 S2-12 NO. BY: DATE: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

10/17/2023 R:\Structures\Plans\300017\402_023_B5981_SMU_DUR_C_S2-12_300017.dgn