

oles


Strain



## Attachment of Cable to Intermediate Metal Pole




## Metal Pole Grounding Detail



NONE

SEAL AUGUST 2013 REVIEWED BY: C.F. ANDREWS INIT. DATE Debesh C. Sarkar 8/26/2014 SIG. INVENTORY NO.



## Strain Pole Attachments

Note: Strap all signal cables to the side of the pole with 3/4" stainless steel straps when the distance between the spanwire attachment clamp and the weatherheads exceeds 36"