



### Strain Pole Attachments

Note: Strap all signal cables to the side of the pole with 3/4" stainless steel straps when the distance between the spanwire attachment clamp and the weatherheads exceeds 36"



### Attachment of Cable to Intermediate Metal Pole



### Metal Pole Grounding Detail

	<b>Construction Details Strain Poles</b>		
	PLAN DATE: AUGUST 2013 PREPARED BY: N. BITTING	REVIEWED BY: C.F. ANDREWS REVIEWED BY: D.C. SARKAR	
REVISIONS: _____ INIT. DATE _____		DocuSigned by: <i>Debesh C. Sarkar</i> 8/26/2014 44E8E32E147E4C4 DATE SIG. INVENTORY NO. _____	