

28-JAN-2016 12:22 K:\TIPProjects-I\I5788\Structures\Finalplans\250157\_plans.dgn tfang

+

REPAIR QUANTITY TABLE							
UNDERSIDE OF DECK REPAIRS							
	ESTIMATE		ACTUAL				
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF			
UNDERSIDE OF DECK & OVERHANGS	1.5	0.4					
BENT DIAPHRAGMS	9.0	2.3					
RC DECK GIRDERS							
	ESTIMATE		ACTUAL				
EPOXY RESIN INJECTION	4.0 LF						

VALUES IN CHARTS REPRESENT ESTIMATED UNDERSIDE OF DECK REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN.OF 1" BEHIND REBAR AND MIN.1" CLEAR TO SAWCUT. SEE REPAIR DETAILS.

## NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. FOR BENT DIAPHRAGM AND RC DECK GIRDER REPAIR DETAILS SEE SHEET S-24. REPAIR CONCRETE BENT DIAPHRAGMS AS DIRECTED BY THE ENGINEER.

PROJECT NO. <u>I-5788</u>						
CUMBERLAND COUNTY						
BRIDGE NO. 157						
SHEET 5 OF 5						
STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH						
SUPERSTRUCTURE REPAIR SPAN E						
NBL						
		SIONS		SHEET NO. S-29		
NO. ВҮ: <b>1</b>	DATE:	NO. BY:	DATE:	TOTAL SHEETS		
2		4		72		

