


TOP OF CAP

AS-BUILT REPAIR QUANTITY TABLE

REPAIRS BENT 2	QUANTITIES			
	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP	0.9	0.8 *		
COLUMN	5.0	4.2 *		
	•			
EPOXY RESIN INJECTION		LN. FT		LN. FT
CAP		20.1		
COLUMN		5.0		
EPOXY COATING		SQ. FT		SQ. FT
TOP OF BENT CAP		0		

VALUES IN CHARTS REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN.1" CLEAR TO SAWCUT.



END VIEW

SPAN B FACE

-SPAN B FACE -SPAN C FACE

SPAN B FACE

UNDERSIDE OF CAP

PROJECT NO. I-5756 HAYWOOD COUNTY 208 BRIDGE NO.

DAMAGED AREA

-DocuSigned by: SHEET 2 OF 2 John d. Yannaccon

SEAL 3 32492

-7BC36E9CERSALE CARO

3/21/2016

SPAN C FACE

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

BENT 2

REVISIONS S-25 DATE: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS 122

21-MAR-2016 13:14 R:\Structures\FinalDrawings\430208\I5756_430208_SD_B*'s.dgn

DATE : 11/15 DATE : 12/15

END VIEW

W.O.KEITH

J. YANNACCONE

DRAWN BY : CHECKED BY : 0.6 LF EPOXY RESIN-INJECTION