
NOTES

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR CAP REPAIRS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.




NO REPAIRS NOTED FOR BENT 2 DURING INSPECTION BY STRUCTURES MANAGEMENT UNIT. THE CONTRACTOR AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK.

AS-BUILT REPAIR QUANTITY TABLE

REPAIRS BENT 2		QUANTITIES			
	EST	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF	
CAP	0.0	0.0			
COLUMN	0.0	0.0			
EPOXY RESIN INJECTION		LN. FT		LN. FT	
CAP		0.0			
COLUMN		0.0			
EPOXY COATING		SQ. FT		SQ. FT	
TOP OF BENT CAP		0			

VALUES IN CHARTS REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 1" CLEAR TO SAWCUT.






END VIEW NORTH FACE

SPAN B FACE

END VIEW SOUTH FACE

SPAN C FACE



SHEET 2 OF 2 John d. Yannaccon ESPAROL CAROL SEAL 3 32492

3/21/2016

PROJECT NO. I-5756 HAYWOOD COUNTY 224 BRIDGE NO.

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

BENT 2

S-65

TOTAL SHEETS 122

REVISIONS DATE: NO. BY: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

DATE : __09/15 __DATE : __12/15 R. Z. DEAN DRAWN BY : CHECKED BY : J. YANNACCONE

21-MAR-2016 13:15 R:\Structures\FinalDrawings\430224\I5756_430224_SD_B*.dgn