

+

+

.

AP A	AS-BUILT REPAIR QUANTITY TABLE						
Indicate Repairs APEA VOLUME APEA A	REPAIRS BENT 2	FCT			ΤΠΛΙ		
AP 13.5 12.0 # OLUMN 39.7 83.3 # SONCRETE REPAIRS AREA VOLUME AREA VOLUME APP 0.0 0.0 OLUMN 0.0 0.0 POXY RESIN INJECTION LN. FT AP 0.0 0.0 0.0 POXY RESIN INJECTION LN. FT AP 3.0	SHOTCRETE REPAIRS	AREA	VOLUME	AREA	VOLUME		
NORRETE REPAIRS AREA VOLUME SF OF OF AREA VOLUME SF OF OF AREA VOLUME SF OF OF AREA VOLUME SF OF OF AP 0.0 0.0 0.0 0.0 0.0 IQUUMN 0.0 0.0 0.0 0.0 0.0 POXY RESIN INJECTION LN. FT LN. FT LN. FT LN. FT LN. FT AP 3.0 1.0 1.0 1.0 1.0 OULUMN 1.0 1.0 1.0 1.0 INCOMPTORY RESIN INJECTION FT SO. 1.0 1.0 POXY COATING SO. FT 1.64 1.0 1.0 1.0 PROXY COATING SO. FT I.64 1.0 1.0 1.0 AND ESTIMATED OUNTITIES ARE GIVEN WITH THE BEST NOTACT TO SAWOUT. SO. 1.64 1.0 SHOTCRETE NOTELS SO. 1.0 1.0 1.0 AND ESTIMATED OUNTITIES ARE GIVEN WITH THE BEST NOTACT TO SAWOUT. SO. 1.0 1.0 1.0 AND ESTIMATED OUNTITIES ARE GIVEN WITH THE BEST LABUE TO ANTOL TO SAWOUT. INCELL REPART OUNTITIES 1.0 1.0 1.0 AND ESTIMATED OUNTHE OFFACE OF	CAP			<u>٦</u> ٢	UF		
NOTES SF CF SF CF AP 0.0 0.0 0.0 0.0 OLUMN 0.0 0.0 0.0 0.0 POXY RESIN INJECTION FT FT FT AP 3.0 0 0 OLUMN 1.0 0 0 0 POXY RESIN INJECTION FT FT FT AP 3.0 0 0 OLUMN 1.0 0 0 POXY COATING FT FT FT POD OF BENT CAP 164 0 0 ALUES IN CAREST REPRESENT ESTIMATED REPAIR TOTALS AFTER AND ESTIMATED OUANTITIES AFTER TOTALS AFTER NOTES AND ESTIMATED OUANTITIES ARE GIVEN WITH THE BEST AND ESTIMATED OUANTITIES ARE GIVEN WITH THE BEST AND ESTIMATED OUANTITIES ARE GIVEN WITH THE BEST AND ESTIMATED OUANTITIES ARE GIVEN WITH THE BEST OLUMN THE CONCINCERTER WIND OF THE CAP BENART AND OUANTITIES AND COLUMN REPAIRS OF THE CAP ADONRY OLUMN THE EXTREMENT OF THE CAP BENART AND OUANTITIES ENTERED INTO THE CAP BENART AND <				ARE A			
OLUMN 0.0 0.0 0.0 POXY RESIN INJECTION IN IN IN AP 3.0 0 IN OLUMN 1.0 IN FT OULUMN 1.0 IN FT OP OF BENT CAP 164 FT OP OF DENT CAP 164 Int AULES IN CHARTS REPRESENT ESTIMATED REPAIR TOTALS AFTER FT MOVELAR TO SAWCUT. SHOWN ON THE BRAIN NOT INT SHOTCRETE INTO THE PATRS NOT SHOWN ON THE BRAINNES AND AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST AND SHORTH THE ENCINEER WILL NOTE ON THE AND SHOTCRETE INTO THE PATRS NOT SHOWN ON THE DRAWINGS AND OULANTITIES ENTERED INTO THE AS-BUILT REFAIN AND AND ESTIMATED QUANTITIES ARE GIVEN WITH THE MASONRY OULANTITIES ENTERED INTO THE AS-BUILT REFAIN AND OULANTITIES ENTERED INTO THE AS-BUILT REFAIN OUANTITY ALL BE APPLIED TO THE TOP FACE OF THE CAP. THE MASONRY COATING, SEE SPECIAL PROVISIONS. SHEET NO. ISTERT OUANTITIES ALL BARGED DUE TO THE OF PACE OF THE CAP. THE MASONRY COATING, SEE SPECIAL PROVISIONS. SHEET NO. ISTERT OUANTITIES NICREASED DUE TO THE POTENTIAL FOR FURTHER COUNTY <td>CONCRETE REPAIRS</td> <td>SF</td> <td>CF</td> <td></td> <td></td>	CONCRETE REPAIRS	SF	CF				
POT RESIN INSECTION FT FT FT AP 3.0 0 OLUMN 1.0 0 OP OF BENT CAP 164 0 ALUES IN CHARTS REPRESENT ESTIMATED REPAIR TOTALS AFTER MOVAL OF UNSOUND CONCRETE, MIN. OF 1' BEHIND REBAR AND 164 SHOTES 164 0 AND ESTIMATED OUANTITIES ARE GIVEN WITH THE BEST LABLE. IF ADDITIONAL REPAIRS NOT SOUND ON THE DRAWINGS SOUTHATE LOATIONS, AND DESCRIPTION OF THE REPAIRS AND OUANTITIES ENTERED INTO THE AS-BUILT REPAIR OUANTITY ALL BE APPLIED TO THE TOP FACE OF THE CAP. THE NOT COAT THE AREA OF THE CAP BENEATH THE MASORY COATING, SEE SPECIAL PROVISIONS. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS' SHEET. N INCREASED DUE TO THE POTENTIAL FOR FURTHER NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. INCREASED DUE TO THE POTENTIAL FOR FURTHER NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. INCREASED DUE TO THE 2 OF 4 ALL MALESTAR INCREASED DUE TO THE POTENTIAL FOR FURTHER NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. INCREASED DUE TO THE OF 4 ALL MALESTAR BENDER 2 BERIDEE NO. SEAT SEAT SHEET 2 OF 4 BENT 2 BENT 2 BENT 2 <	CAP COLUMN						
POT RESIN INSECTION FT FT FT AP 3.0 0 OLUMN 1.0 0 OP OF BENT CAP 164 0 ALUES IN CHARTS REPRESENT ESTIMATED REPAIR TOTALS AFTER MOVAL OF UNSOUND CONCRETE, MIN. OF 1' BEHIND REBAR AND 164 SHOTES 164 0 AND ESTIMATED OUANTITIES ARE GIVEN WITH THE BEST LABLE. IF ADDITIONAL REPAIRS NOT SOUND ON THE DRAWINGS SOUTHATE LOATIONS, AND DESCRIPTION OF THE REPAIRS AND OUANTITIES ENTERED INTO THE AS-BUILT REPAIR OUANTITY ALL BE APPLIED TO THE TOP FACE OF THE CAP. THE NOT COAT THE AREA OF THE CAP BENEATH THE MASORY COATING, SEE SPECIAL PROVISIONS. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS' SHEET. N INCREASED DUE TO THE POTENTIAL FOR FURTHER NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. INCREASED DUE TO THE POTENTIAL FOR FURTHER NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. INCREASED DUE TO THE 2 OF 4 ALL MALESTAR INCREASED DUE TO THE POTENTIAL FOR FURTHER NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. INCREASED DUE TO THE OF 4 ALL MALESTAR BENDER 2 BERIDEE NO. SEAT SEAT SHEET 2 OF 4 BENT 2 BENT 2 BENT 2 <			1. NI		1. 1.1		
OLUMN 1.0 1.0 IPOXY COATING 50. FT FT OP OF BENT CAP 164 164 ALUES IN CHARTS REPRESENT ESTIMATED REPAIR TOTALS AFTER MOVAL OF UNSOUND CONCRETE, MIN. OF 1' BEHIND REBAR AND SATE SHOTCRETE NOTES AND ESTIMATED OUANTITIES ARE GIVEN WITH THE BEST LABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARY BY THE ENCINEER, THE ENDITER WILL NOTE ON THE OXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIR OUANTITY ALL BE APPLIED TO THE TOP FACE OF THE CAP. THE NOT COAT THE AREA OF THE CAP DENEATH THE MASONRY COATING, SEE SPECIAL PROVISIONS. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET. N INCREASED DUE TO THE POTENTIAL FOR FURTHER NOT COAT THE AREA OF THE CAP DENEATH THE MASONRY COATING, SEE SPECIAL PROVISIONS. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET. N INCREASED DUE TO THE POTENTIAL FOR FURTHER NOE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. INCREASED DUE TO THE POTENTIAL FOR FURTHER NGE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. BRIDGE NO. 228 MEMONY SHEET 2 OF 4 MEMONY SHEET 2 OF 4 INTERMENT OF TRANSPORTATION RALEDW SHEET 100. SEAL SHEET 2 OF 4 INT OT CONSIDERED SHEET 100. RENT 2 SHEET 100. S	POXY RESIN INJECTION		FT				
POXY COATING S0. FT S0. FT S0. FT OP OF BENT CAP 164 Idd ALUES IN CHARTS REPRESENT ESTIMATED REPAIR TOTALS AFTER MOVAL OF UNSOUND CONCRETE, MIN. OF 1' BEHIND REBAR AND IN. 1' CLEAR TO SAWCUT. SHOTCRETE AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST LABLE IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ANY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE OXITIME LOCATIONS AND DESCRIPTION OF THE REPAIRS AND . QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY ALL BE APPLIED TO THE TOP FACE OF THE CAP. THE NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY COATING, SEE SPECIAL PROVISIONS. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET. N INCREASED DUE TO THE POTENTIAL FOR FURTHER NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. INCREASED DUE TO THE POTENTIAL FOR FURTHER NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. INCREASED DUE TO THE POTENTIAL FOR FURTHER NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. INCREASED DUE TO THE POTENTIAL FOR FURTHER NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. INCREASED DUE TO THE POTENTIAL FOR FURTHER NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. INCREASED DUE TO THE POTENTIAL FOR FURTHER NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. INCREASED DUE TO THE POTENTIAL FOR TRANSPORTATION RELIDING SHEET 2 OF 4 INT OT CONSIDERED INTER THE INFORMATION RELIDING SHEET 100 SHEET NO. SHEET NO. SHEET 20 FA							
PORT CONTINUE FT PT DT Desconder State Desc							
ALUES IN CHARTS REPRESENT ESTIMATED REPAIR TOTALS AFTER MOVAL OF UNSOUND CONCRETE, MIN. OF 1' BEHIND REBAR AND IN. 1' CLEAR TO SAWCUT. SHOTCRETE AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST LABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARY BY THE ENGINEER THE ENGINEER WILL NOTE ON THE OXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY ALL BE APPLIED TO THE TOP FACE OF THE CAP. THE NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY COATING, SEE SPECIAL PROVISIONS. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET. NICREASED DUE TO THE POTENTIAL FOR FURTHER NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. PROJECT NO. <u>I-5756</u> <u>HAYWOOD</u> COUNTY BRIDGE NO. <u>228</u> Ned by: SHEET 2 OF 4 A. YANAWAYCON SEAL SCHET YOL CONSIDERED NEEVISIONS SHEET 2 OF 4 A. YANAWAYCON BRIDGE NO. <u>228</u> SHEET 2 OF 4 A. YANAWAYCON BRIDGE NO. <u>228</u> SHEET 2 OF 4 A. YANAWAYCON BRIDGE NO. <u>228</u> SHEET 2 OF 4 ME BENT 2 NALE OF MORTH CAMBELTAN BENT 2 NALE OF MORTH CAMBELTAN BENT 2 NALE OF MORTH CAMBELTAN BENT 2 NOT CONSIDERED	POXY COATING				SQ. FT		
MOYAL OF UNSOUND CONCRETE, MIN. OF 1' BEHIND REBAR AND SHOTCRETE AND ESTIMATED QUANTITIES ARE CIVEN WITH THE BEST LABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS AND DESTIMATE LOCATIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ANY BY THE ENGINEER THE ENGINEER WILL NOTE ON THE YOXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND OLIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND DAMAGED DUE TO THE POTENTIAL FOR FURTHER NEET THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. INCREASED DUE TO THE POTENTIAL FOR FURTHER NEET THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. INCREASED DUE TO THE POTENTIAL FOR FURTHER NEET THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. INCREASED DUE TO THE POTENTIAL FOR FURTHER NEET 2 OF 4 INCREASED DUE TO THE POTENTIAL FOR MARTICARDUM BRIDGE NO	TOP OF BENT CAP						
AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST LABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS HARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE ROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND . QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY ALL BE APPLIED TO THE TOP FACE OF THE CAP. THE NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY COATING, SEE SPECIAL PROVISIONS. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET. N INCREASED DUE TO THE POTENTIAL FOR FURTHER NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. PROJECT NO. <u>1-5756</u> <u>HAYWOOD</u> COUNTY BRIDGE NO. <u>228</u> NOMED TO THE OF A SHEET 2 OF 4 A. MANAGED AREA DEPARTMENT OF TRANSPORTATION RALEIGH BENT 2 <u>ALL UNLESS ALL</u> <u>NOT CONSIDERED</u> <u>NOT CONSIDERED</u> <u>N</u>	IN.1" CLEAR TO SAWCUT. SHOTCRETE			-			
SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET. N INCREASED DUE TO THE POTENTIAL FOR FURTHER NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. PROJECT NO. <u>1-5756</u> <u>HAYWOOD</u> COUNTY BRIDGE NO. <u>228</u> NOT BRIDGE NO. <u>228</u> SHEET 2 OF 4 A. MONECONSTIDERED SHEET 2 OF 4 BENT 2 BENT 2 SHEET NO. BENT 2 SHEET NO. SHEET NO.	NOTES AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST LABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS SARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE ROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND L QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY						
NINCREASED DUE TO THE POTENTIAL FOR FURTHER NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT.	ALL BE APPLIED TO THE TOP FACE OF THE CAP. THE NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY COATING,SEE SPECIAL PROVISIONS.						
NCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. Image: Comparison of the state of north cardument of the state of nor	SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.						
PROJECT NO. <u>I-5756</u> <u>HAYWOOD</u> COUNTY BRIDGE NO. <u>228</u> ned by: <u>SHEET 2 OF 4</u> <i>A. YANACOM</i> SEAL <i>J. YANACOM</i> <i>BENT 2</i> <i>BENT 2</i> <i>BENT 2</i> <i>BENT 2</i> <i>BENT 2</i> <i>BENT 2</i>							
BRIDGE NO. 228 BRIDGE NO. 228 SHEET 2 OF 4 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH BENT 2 BENT 2	PROJECT NO. 1-5756						
SHEET 2 OF 4 SHEET 2 OF 4 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION REVISIONS SEAL 32492 BENT 2 REVISIONS SHEET NO.	BRIDGE NO.						
A. UNIT CAROUND STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH BENT 2 REVISIONS SHEET NO. BENT 2 REVISIONS SHEET NO. BENT 2 REVISIONS SHEET NO. S-80 TOTAL UNLESS ALL STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH BENT 2 SHEET NO. S-80 TOTAL SHEET NO. SHEET NO. S-80 TOTAL							
REVISIONS SHEET NO. ENT NOT CONSIDERED NO. BY: DATE: NO. BY: DATE: S-80 INAL_UNLESS_ALL 1 3 SHEET NO. SHEET NO.	A. UANNALLOND DEPARTMENT	DEPARTMENT OF TRANSPORTATION					
ENT NOT CONSIDERED NO. BY: DATE: NO. BY: DATE: S-80 INAL_UNLESS_ALL			۷	<u>,,</u>			
INAL UNLESS ALL 1 SHEETS	IENT NOT CONSTDERED NO. BY: DATE: N	0. BY:	DATE				
	INAL UNLESS ALL 🚺						