

oles


Strain



Attachment of Cable to Intermediate Metal Pole




Metal Pole Grounding Detail



SIG. INVENTORY NO.

NONE



Strain Pole Attachments

Note: Strap all signal cables to the side of the pole with 3/4" stainless steel straps when the distance between the spanwire attachment clamp and the weatherheads exceeds 36"