## NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.


FOR CAP REPAIR DETAILS, SEE "TYPICAL CAP REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

FOR "EPOXY RESIN INJECTION", SEE SPECIAL PROVISIONS.

CAP CAP PILE PILE EP0> САР

VALUES REMOVA MIN.2″



+

.

+

REPAIR QUANTITY TABLE				
OLIANTITIES				
REPAIRS BENT 39-S	ESTI	MATE	AC	TUAL
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL, CORNER)	0.0	0.0		
PILE COLLAR (VERT FACE)	0.0	0.0		
PILE COLLAR (HORIZ FACE)	0.0	0.0		
EPOXY RESIN INJECTI	ON	LN.FT.		LN.FT.
CAP		0.0		
/ALUES IN CHART REPRESENT EST; REMOVAL OF UNSOUND CONCRETE, M MIN. 2"CL TO SAWCUT. SEE REPAIR	DETAILS.			
EAST FACE				
PRC		10 RELL		36 OUNTY
SEAL 23739 C. Bruth		STATE OF NORTH NT OF TR RALEIGH	ANSPORT	ATION
		REVISIONS		SHEET NO.
DOCUMENT NOT CONSIDERED	BY: DATE	NO. BY:	DATE:	S-354
FINAL UNLESS ALL 1 SIGNATURES COMPLETED 2		3 4	_	TOTAL SHEETS 394

.

.