WEST FACE

PLAN
BOTTOM OF CAP



SOUTH FACE

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.


FOR CAP REPAIR DETAILS, SEE "TYPICAL CAP REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

FOR "EPOXY RESIN INJECTION", SEE SPECIAL PROVISIONS.

REPAIR QUANTITY TABLE				
REPAIRS BENT 55-S	QUANTITIES			
	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL, CORNER)	0.0	0.0		
PILE COLLAR (VERT FACE)	0.0	0.0		
PILE COLLAR (HORIZ FACE)	0.0	0.0		
EPOXY RESIN INJECTION		LN. FT.		LN. FT.
CAD		0.0		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.



EAST FACE

PROJECT NO. B-5936

TYRRELL COUNTY
BRIDGE NO. 7

DEP

STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION

BENT 55-S

NO REPAIRS NOTED DURING INSPECTION BY STRUCTURES
MANAGEMENT UNIT. THE CONTRACTOR AND ENGINEER SHALL
INSPECT THE BENT PRIOR TO BEGINNING WORK.

Docusigned by:

Paul Bryant
3653D2AF1B77448...

8/11/2016

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

TOM OF CAP

8/11/2

19-JUL-2016 14:49 R:\Structures\FINAL DGNS\401\_021\_B5936\_SMU\_S38 THRU 380\_BT.dgn pbryant

 DRAWN BY:
 P. D. BRYANT
 DATE : 4-2016

 CHECKED BY:
 W. M. CLARKE
 DATE : 4-2016

NORTH FACE