




PLAN - TOP OF CAP




SPAN A VIEW - ELEVATION



PLAN - BOTTOM OF CAP



SPAN B VIEW - ELEVATION



AS-BUILT REPAIR QUANTITY TABLE


NOTES:


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE, IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR


CLEAN AND REMOVE DEBRIS FROM TOP OF CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP FACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

* QUANTITY HAS BEEN INCREASED DUE TO THE POTENTIAL FOR FURTHER DETERIORATION SINCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT.

FOR REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.







STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

BENT 1

REVISIONS DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED DATE: DATE: S-45 TOTAL SHEETS 68

27-SEP-2016 14:36
R:\Structures\FinalDrawings\McDowell151\I-5809_SD_BT1_#151.dgn

DATE : _5/2016

DATE : 5/2016

J.P. ADAMS

DRAWN BY : CHECKED BY :