

AS-BUILT REPA	IR QU	JANTI	ΓΥ ΤΔ	BLE		
REPAIRS BENT 2		QUANT				
SHOTCRETE REPAIRS	AREA	IMATE VOLUME	AREA	VOLUME		
САР	SF 0.0	CF 0.0	SF	CF		
COLUMN	0.0	0.0				
CONCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
CAP COLUMN	8.4 21.5	5.3 * 14.0 *				
EPOXY RESIN INJECT	ION	LN. FT		LN. FT		
		0.0				
		0.0				
EPOXY COATING	EPOXY COATING			SQ. FT		
TOP OF BENT CAP		125	C 15755			
VALUES IN CHART REPRESENT ES REMOVAL OF UNSOUND CONCRETE, MINIMUM 2" CLEAR TO SAWCUT.	MINIMUM (OF 1" BEHIND	LS AFIER REBAR AN	ID		
NOTES:						
* QUANTITY HAS BEEN INCREASED FIELD INSPECTION BY STRUCTUF FOR REPAIR DETAILS, SEE ``TYPI FOR BRIDGE JACKING DETAILS, S	RES MANAGE ICAL CAP A	MENT UNIT.	REPAIR DE			E THE
		DAMAGED	AREA			
1.0 SF CONCRETE REPAIR		EPOXY R	ESIN INJE	CTION		
CONCRETE REPAIR		F	ROJEC	T NO	I-580	9
		_			<u> </u>	
		F		NO	1 - 1	
SIDE VIEW COLUMN 1	Signed by:	_	HEET 2 OF			
John	SEAL 32492 16	nnaccou	ı	STATE OF N RTMENT OF RA	ORTH CAROLINA TRANSPORTA LEIGH	TION
=,=:,=						
		ļ		REVISIONS		SHEET NO.

27-SEP-2016 14:36 R:\Structures\FinalDrawings\McDowell151\I-5809_SD_BT2_*151.dgn

+

+

.