

Span #	Component	Location (ft. from nearest bent, etc)	Bent #	Defect Description	Length(ft.)	Width(ft.)	*Depth(ft.)	Span #	Component	Location (ft. from nearest bent, etc)	Bent #	Defect Description	Length(ft.)	Width(ft.)	*Depth(ft.)
164	Under Deck	mid span	164	Spalling/rebar exposed	1.5	0.5	0.167	201	Girder 4	1' from bent	200	Delam at patch	1.25	0.5	0.5
165	End Diaphragm	bay 3	164	(x4)Spalling/rebar exposed	3	0.5	0.167	201	Girder 4	10' from bent	201	Delam at patch	1.75	0.5	0.5
165	Girder 2	1' from bent	165	Delam	1	0.5	0.5	202	Girder 2	18' from bent, bottom left flange	201	Spalling/strands exposed (10% loss)	1.75	0.5	0.5
165	Under Deck	bay 2, 1' from bent	165	Delam	1	1	0.167	203	Girder 4	26' from bent, bottom face	202	Spalling	1	0.75	0.167
166	Girder 4	1' from bent	165	Delam at patch	2	0.75	0.75	203	Girder 4	6' from bent, bottom face	202	Spalling/strands exposed (20% loss)	2.5	1.75	0.5
167	End Diaphragm	bay 1	166	Spalling/rebar exposed	1.75	1.5	0.167	203	Girder 3	15' from bent	202	Delam at patch	5	1	0.75
168	End Diaphragm	bay 1	167	Spalling/rust spot	4	0.5	0.5	203	Girder 4	5'Bent	203	Delam at patch	2.25	0.5	0.5
168	Girder 3	20' from bent	167	Spalling/strands exposed (10% loss)	2	0.5	0.5	203	Girder 4	1' from bent	203	Delam at patch	2	0.75	0.5
168	Girder 3	3' from bent	168	Delam at patch	2	0.75	0.5	204	Girder 2	2' from bent, bottom right flange	204	Spalling/strands exposed (10% loss)	2.25	0.5	0.5
169	Girder 4	30' from bent	168	Exposed steel on bottom face	0.25	0.25	0.167	204	Girder 1	2' from bent	204	Delam	2.25	0.75	0.5
171	Girder 1	20' from bent	170	Delam at patch	2.5	1	0.5	205	Girder 2	at bent, bottom right flange	204	Spalling/strands exposed behind bearing	0.75	0.75	0.5
171	Girder 3	26' from bent, bottom face	171	Exposed steel	0.25	0.25	0.167	205	Girder 3	9' from bent	204	Delam	1.25	1	0.167
172	End Diaphragm	bay 3	171	Spalling/rebar exposed	1.5	0.5	0.167	205	Girder 2	at bent	204	Delam at patch	1.5	0.75	0.5
172	End Diaphragm	bay 1	172	Spalling/rebar exposed	1.25	1	0.75	205	End Diaphragm	bay 2	205	Delam/cracking	4	0.67	0.25
173	Girder 4	at bent, bottom left flange	173	Spalling/strands exposed	1.5	1	0.5	205	End Diaphragm	bay 3	205	Spalling/rebar exposed	1.25	1	0.75
173	Girder 4	21' from bent, bottom face	173	Delam	2	1.5	0.167	206	Girder 1	2' from bent	205	Delam at patch	3.5	0.75	0.75
173	Girder 3	28' from bent	173	Delam at patch	3	1.75	0.75	206	Girder 1	1' from bent, bottom right flange	206	Spalling/strands exposed (10% loss)	3.75	1	0.25
173	End Diaphragm	bay 1	173	Spalling/rebar exposed	1	1	0.75	206	Girder 2	1' from bent	206	Delam	1.5	0.5	0.5
174	Under Deck	bay 2	174	Spalling/steel exposed	0.5	0.5	0.167	207	Under Deck	bay 1	206	Spalling/rebar exposed, delam	1.75	0.75	0.167
174	Under Deck	bay 3	174	Spalling/steel exposed	0.25	0.25	0.167	208	Girder 3	8' from bent	207	Delam	1.75	1.25	0.33
175	Girder 3	at bent, bottom right flange	174	Spalling/strands exposed (10% loss)	3.75	0.5	0.5	208	Girder 2	20' from bent, bottom right flange	208	Spalling/strands exposed (10% loss)	2	0.33	0.33
175	Girder 3	23' from bent, bottom face	175	Spalling/steel exposed	0.5	0.5	0.167	208	Girder 2	at bent	208	Delam	2	0.5	0.5
176	Under Deck	bay 2, 3' from bent	175	Spalling/rebar exposed	1	1	0.167	208	Under Deck	bay 2, 5' from bent	208	Spalling/rebar exposed	1.5	1	0.167
176	Girder 3	27' from bent, bottom face	176	Spalling	0.5	0.5	0.167	209	End Diaphragm	bay 2	208	Spalling/rebar exposed; cracking	3.5	0.75	0.5
178	Girder 3	at bent, bottom left flange	177	Spalling/strands exposed	1.5	0.75	0.33	209	End Diaphragm	bay 1	208	Delam/cracking	4	0.67	0.5
178	Under Deck	bay 3	177	Delam	1.25	1.25	0.167	209	Girder 3	19' from bent, bottom face	209	Delam	1	0.5	0.167
178	Under Deck	bay 3	178	Spalling/steel exposed	0.75	0.5	0.167	209	Girder 4	1' from bent, bottom left flange	209	Spalling/strands exposed	2.5	0.5	0.5
178	Under Deck	bay 2	178	Spalling/rebar exposed	0.5	0.5	0.167	209	Girder 3	2' from bent	209	Delam at patch	1.25	0.75	0.5
178	Girder 2	24' from bent, bottom face	178	Spalling/strand exposed	1.25	1	0.167	210	Under Deck	bay 1, near bent	209	Spalling/rebar exposed	0.5	0.5	0.167
178	Girder 3	22' from bent, bottom face	178	Spalling	1.5	0.33	0.167	210	Girder 2	1' from bent	209	Delam at patch	1.75	0.5	0.5
180	End Diaphragm	bay 1	180	Spalling/steel exposed	1	1	0.167	210	Girder 2	5' from bent	209	Delam	1.5	1	0.25
181	End Diaphragm	bay 1	180	Spalling/steel exposed	1	1	0.167	210	Girder 4	6' from bent, bottom left flange	209	Spalling/strands exposed (20% loss)	2.25	0.75	0.5
181	Girder 4	1' from bent	180	Spalling/strand exposed	1	0.5	0.5	211	Girder 2	1' from bent, bottom left flange	210	Delam on edge of girder	1.75	0.33	0.33
182	Under Deck	bay 2, mid span	181	Spalling/rebar exposed	0.5	0.5	0.167	211	Girder 2	25' from bent, bottom face	211	Delam	2	0.75	0.167
182	Girder 2	20' from bent	182	Spalling/strand exposed	1.5	0.75	0.167	212	Girder 2	20' from bent, bottom left flange	212	Spalling/strands exposed (20% loss)	2.25	0.75	0.33
183	Girder 1	24' from bent, bottom face	182	Spalling/strands exposed (90% loss)	2.25	1.25	0.25	212	Girder 2	at bent, behind bearing	212	Spalling/strands exposed	0.75	0.75	0.5
183	Girder 2	30' from bent, bottom face	183	Spalling/strands exposed	2	0.5	0.167	214	Girder 2	18' from bent	213	Delam	1.5	1	0.167
183	Girder 2	22' from bent	183	Spalling/strand exposed	1.5	0.75	0.5	214	Girder 3	5' from bent	213	Delam	0.75	0.5	0.167
183	Girder 2	18' from bent, bottom left flange	183	(x2)Spalling/strands exposed (10% loss)	2.25	1	0.33	214	Girder 3	at bent, behind bearing	214	Delam	0.75	0.75	0.167
183	Girder 4	18' from bent	183	Spalling/strand exposed	1	1	0.167	216	Int. Diaphragm	bay 3	216	Spalling/rebar exposed	1.25	0.33	0.167
183	Girder 2	30' from bent	183	Spalling/strands exposed	1.25	1	0.25	217	Girder 2	20' from bent, bottom left flange	216	Spalling/strands exposed (10% loss)	2.25	0.5	0.167
184	Girder 2	20' from bent, bottom left flange	183	Spalling/strands exposed (10% loss)	2	0.5	0.167	217	Girder 1	19' from bent, bottom left flange	217	Spalling/strands exposed	2	0.5	0.5
184	Girder 2	18' from bent, bottom right flange	183	Spalling/strands exposed (10% loss)	2.25	1	0.33	218	Girder 3	3' from bent, bottom left flange	217	Spalling/strands exposed (10% loss)	2.25	0.5	0.5
184	Girder 2	25' from bent, bottom left flange	183	Spalling/strands exposed (10% loss)	1.5	1	0.167	218	Girder 2	20' from bent, bottom face	217	Delam	0.5	0.5	0.167
184	Girder 4	mid span, bottom face	184	Spalling	1.5	0.5	0.167	218	Girder 3	13' from bent	218	(x2)Delam at patch	3	0.75	0.75
185	Girder 3	9' from bent, bottom face	184	Spalling/steel exposed	0.25	0.25	0.167	218	Girder 3	12' from bent, bottom left flange	218	Spalling/strands exposed	1.25	0.5	0.33
185	Girder 1	at bent	186	Spalling/strand exposed	1	1	0.167	219	End Diaphragm	at right overhang	218	Spalling/rebar exposed	1	0.75	0.167
186	Girder 2	21' from bent, bottom right flange	186	Spalling/strands exposed (10% loss)	2	0.75	0.33	219	Girder 2	20' from bent, bottom left flange	218	Spalling/strands exposed	2.25	0.5	0.33
186	Girder 4	at Bent both spans maybe?	186	Spalling/Delam at bearing	1	1	0.167	220	Girder 4	1' from bent, bottom left flange	220	Spalling/strands exposed (90% loss)	3.25	0.75	0.75
186	Girder 4														