
DocuSign Envelope ID: EAE7CC49-66B8-47EE-87E7-008CFC5F470F



ANTICIPATED BEAM REPAIR LOCATIONS LOCATION DIM 'A' DIM 'B' DIM 'C' DIM 'D' SPAN BEAM TYPE BENT 1 BENT 2 7" 50" BENT 2 7" 16" 4" BENT 2

BEAM REPAIR LOCATIONS

(OTHER LOCATIONS MAY EXIST. SEE NOTES)

* PLATE REPAIR IS AT TOP OF WEB

BEAM REPAIR													
BEAM REPA	IR CUT-OUT	BEAM REPA	IR PLATING	STIFFENE	R REPAIR	DIAPHRAGM REPAIR							
LBS.		LBS.		LE	BS.	LBS.							
ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL						
424		22		8									

5430 Wade Park Blvd, Suite 410 Raleigh, NC 27607 Tel. 919-854-0344 Fax. 919-854-0355 NC License No. F-0765

NOTES

FOR BEAM PLATE REPAIRS, SEE "BEAM REPAIR PLATING DETAILS" SHEET.


FOR BEAM CUT-OUT REPAIRS, SEE "BEAM REPAIR CUT-OUT DETAILS" SHEET.

THE LOCATIONS AND DIMENSIONS OF THE AREAS FOR REPAIR ARE BASED ON THE BEST INFORMATION AVAILABLE. THE CONTRACTOR, IN CONJUNCTION WITH THE ENGINEER, SHALL VERIFY THE LOCATION AND EXTENTS OF REPAIR AREAS PRIOR TO STEEL FABRICATION. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE QUANTITIES ON INTO THE REPAIR QUANTITY

CONTRACTOR SHALL ENSURE THAT EXISTING UTILITIES ADJACENT TO THE BRIDGE ARE NOT DAMAGED DURING REPAIR OPERATIONS.

REPLACEMENT OF MISSING OR DETERIORATED NUTS IS INCIDENTAL TO THE COST FOR VARIOUS BEAM REPAIR PAY ITEMS.

- BEAM NUMBER
- BEAM REPAIR CUT-OUT
- BEAM REPAIR PLATING
- FLANGE PLATE REPAIR
- STIFFENER REPAIR
- REPLACE ANCHOR BOLT NUT



PROJECT NO. I-5927 POLK COUNTY BRIDGE NO. 740023

1/11/2023

DEPARTMENT OF TRANSPORTATION

STATE OF NORTH CAROLINA

BEAM REPAIR LOCATIONS

		REVISIONS					
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-8
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			79

DRAWN BY: R. BEAUCHAMP DATE: 7/21 CHECKED BY : E. MURRAY DATE : 12/22