

	C
	ō
	0
	8
	20
	ğ
	01_011_I-6052_SMU_FP1_59028
	5
	Ē.
	- '
	ž
	N.
	Ň
	02
	õ
	ц
	ij
	Ξ
	0
	2
	9S/4
	Ē
	5
	ΰ
	Ĵ
	÷
	Ś
	~
	5
	÷
	Ö
	^o reservation/Structure
	ē
	S
	υ
	.•
	Б
	-
	20
	Ξ.
	×
	ĕ
	Ž
	ົດ
	Ĕ
	ß
	0
	ů ľ
	н
	ດ່
	m,
	<u></u>
	ŏ
	21
	Σ
	6
	Ű
	p P
	÷
	፵
ת	Z
Ĕ	2
Ē	ż
	e: N:\NC Bridges\M21001.39_I-6052_(10) Me
ž	Filename
	Б
1	Č
ັກ	ie.
D	LL.

+

ANTICIPATED BEAM REPAIR LOCATIONS								
SPAN	BEAM	LOCATION	DETAIL Type	DIM.``A''	DIM.``B''	DIM.``C''	DIM.``D''	DIM.``E''
В	3	BENT 2	С	26¾″	10″	3″	12″	-
С	3	BENT 2	D	5 /2″	-	-	12″	-
С	4	BENT 2	D	5 /2″	10″	_	6″	_

BEAM REPAIR QUANTITY TABLE					
SPANS A THRU C					
STEEL PLATES		STIFFENER		STEEL BEARING KEEPER ANGLE ASSEMBLY	
LE	LBS. LBS.		EA.		
ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL
145		45		1	
BEAM REPAIR CUT-OUT BEAM REPAIR					
LE	S.	LBS.			
ESTIMATE	ACTUAL	ESTIMATE	ACTUAL		
_		_			

/2023	57 AM	- Hoooio
1/12/2	9:17:57	
	.	

+

drawn by : B.E. LANNING	DATE :	10/2022
	DATE :	10/2022
		10/2022

NOTES:

PROVISIONS.

