

SHOTCRETE REPAIR

✓ ERI EPOXY RESIN INJECTION

CONCRETE REPAIR



AS-BUILT REPAIR QUANTITY TABLE						
END BENT 2	QUANTITIES					
	ESTIMATE		ACTUAL			
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
CAP (VERTICAL FACE)	0.0	0.0				
CAP (HORIZONTAL FACE)	0.0	0.0				
CONCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
САР	0.0	0.0				
EPOXY RESIN INJECTION	LIN.FT.		LIN.FT.			
САР	0.0					
CURTAIN WALL	0.0					
EPOXY COATING	AREA SF		AREA SF			
TOP OF CAP	72.5					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MIN.OF 1"BEHIND REBAR AND MIN. 2"CL. TO SAWCUT. SEE REPAIR DETAILS.

## NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR REPAIRS, SEE ``TYPICAL CAP, COLUMN AND UNDERDECK REPAIR DETAILS" SHEET.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING TO THE TOP SURFACES OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING AND DEBRIS REMOVAL, SEE SPECIAL PROVISIONS.

PROJECT NO	I - (	6052
MECKLENB	URG	_ COUNTY
BRIDGE NO	590	341

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE

## END BENT 2

1/12/2023					
CUMENT NOT CONSIDERED FINAL ESS ALL SIGNATURES COMPLETED					
MI ENGINEERING	REVISIONS				SHEET NO.
	NO. BY:	DATE:	NO. BY:	DATE:	S7-10
RALEIGH, NC 27606 (919) 851-6606	1		3		TOTAL SHEETS
FIRM PE NUMBER : P-0671	2		4		108