

-

+

DESIGN ENGINEER OF RECORD:


## SUGGESTED REPAIR INSTALLATION PROCEDURE

- 1. LOOSEN THE EXISTING BOLTS AND HOLD-DOWN PLATES TO REMOVE AND REPLACE THE EXISTING GLAND.
- 2. REMOVE THE EXISTING NEOPRENE SEALANT AND CLEAN THE EXISTING BASE ANGLE AND BOLT HOLES OF OIL, GREASE AND OTHER LATENTS.
- 3. LAY THE NEW GLAND ON THE BASE ANGLE AND FIELD MARK THE NEW GLAND For the bolt holes. Holes in the New Gland shall be punched  $\frac{7}{8}$ " in DIAMETER WITH A HAND PUNCH.
- 4. IN ORDER TO CHECK FOR PROPER ALIGNMENT, PLACE THE NEW GLAND AND HOLD-DOWN PLATES ON THE BASE ANGLE. DO NOT APPLY NEW NEOPRENE SEALANT. BOLT THE HOLD-DOWN PLATES TO THE BASE ANGLE, BUT DO NOT TIGHTEN. THE ENGINEER WILL INSPECT THE JOINT SEAL DEVICE FOR PROPER ALIGNMENT.
- 5. AFTER INSPECTION, REMOVE THE HOLD-DOWN PLATES AND NEW GLAND. APPLY NEW NEOPRENE SEALANT TO THE BASE ANGLE IN ACCORDANCE WITH THE "INSTALLATION SKETCH". PLACE NEW GLAND AND HOLD-DOWN PLATES ON THE BASE ANGLE. BOLT THE HOLD-DOWN PLATES TO THE BASE ANGLE ASSEMBLY AND TORQUE THE BOLTS TO 88 FT-LBS WITH A TORQUE WRENCH. CHECK THE TORQUE AFTER THREE (3) HOURS AND, IF NECESSARY, RETIGHTEN TO 88 FT-LBS. A FINAL CHECK SHALL BE MADE AT SEVEN (7) DAYS. TORQUE SHALL NOT BE LESS THAN 80 FT-LBS AFTER SEVEN (7) DAYS.
- 6. AFTER PROPER TORQUING, CLEAN THE BOLT HOLE RECESSES AND THE RECESS BETWEEN THE JOINT SEAL DEVICE AND CONCRETE. COMPLETELY FILL THESE RECESSES WITH NEW NEOPRENE SEALANT.
- 7. CONDUCT WATER-TIGHTNESS TEST.

MOVEMENT AND SETTING AT JOINT							
LOCATION	SKEW ANGLE	TOTAL MOVEMENT (ALONG € RDWY)	PERPENDICULAR JOINT OPENING AT 32°F	PERPENDICULAR JOINT OPENING AT 60°F	PERPENDICULAR JOINT OPENING AT 90°F		
END BENT 2	57° 36' 01"	2 <sup>1</sup> ⁄ <sub>4</sub> "	2 <sup>3</sup> ⁄8"	1 <sup>15</sup> ⁄16"	1% <sub>16</sub> "		

**JOINT DIMENSIONS ARE FROM ORIGINAL AS-BUILT PLANS** 

JOINT REPAIR QUANTITY TABLE					
	ESTIMATED	ACTUAL			
EXPANSION JOINT SEALS FOR PRESERVATION	73.4 LIN.FT.				



PLAN VIEW

## **GENERAL NOTES**

CONTRACTOR SHALL FIELD VERIFY THE EXISTING JOINT OPENING PRIOR TO ORDERING JOINT SEAL MATERIAL. IF THE ACTUAL JOINT OPNEING VARIES FROM THE OPENING INDICATED IN THE DETAILS BY MORE THAN  $\frac{1}{4}$ ", NOTIFY THE ENGINEER.

THE MANUFACTURER IS TO PROVIDE THE NOMINAL GLAND SIZE BASED ON EXISTING JOINT OPENINGS AND ANTICIPATED MOVEMENTS.

THE CONTRACTOR SHALL TAKE CARE DURING JOINT REHAB OPERATIONS NOT TO DROP ANY MATERIAL BELOW THE BRIDGE, WITHOUT PROTECTIVE DEVICES BELOW TO CATCH THE MATERIAL. ANY MATERIAL THAT FALLS BELOW THE BRIDGE SHALL BE CONTAINED, REMOVED AND DISPOSED OF BY THE CONTRACTOR AT NO EXTRA COST TO THE DEPARTMENT. IF THE ENGINEER DETERMINES THAT THE PROTECTIVE DEVICES ARE NOT ADEQUATE OR NOT BEING EMPLOYED, THE WORK SHALL BE SUSPENDED UNTIL ADEOUATE PROTECTION IS PROVIDED.

RETAIN ALL EXISTING HOLD-DOWN PLATES AND HARDWARE. CLEAN AND REPAIR AS NEEDED. CONTRACTOR SHALL REPLACE DAMAGED HOLD-DOWN PLATES AND/OR HARDWARE AS NEEDED OR DIRECTED BY THE ENGINEER AT NO EXTRA COST TO THE DEPARTMENT.

ALL HOLD-DOWN BOLTS SHALL CONFORM TO ASTM F593 ALLOY 304 STAINLESS STEEL AND WASHERS SHALL CONFORM TO ASTM F844 EXCEPT THEY SHALL BE MADE FROM ALLOY 304 STAINLESS STEEL.

FOR EXPANSION JOINT SEAL FOR PRESERVATION, SEE SPECIAL PROVISIONS.

NO SEPARATE PAYMENT WILL BE MADE FOR REMOVING AND REINSTALLING MEDIAN, SIDEWALK AND BARRIER RAIL COVER PLATES. THE ENTIRE COST OF THIS WORK SHALL BE INCLUDED IN THE LINEAR FEET PRICE BID FOR "EXPANSION JOINT SEALS FOR PRESERVATION".

- NEOPRENE SEALANT

	PROJECT NO. 15BPR.12 WAKE CO BRIDGE NO. 911039	DUNTY		
SEAL OSTATOS NONE SEAL NONE SE	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH STANDARD EXPANSION JOINT SEAL REPAIR DETAILS			
	REVISIONS	SHEET NO.		
DOCUMENT NOT CONSIDERED	NO. BY: DATE: NO. BY: DATE: 1 3	S2-06 TOTAL SHEETS		
FINAL UNLESS ALL SIGNATURES COMPLETED	1 2 4	SHEETS 18		