CAP **CURTAIN WALL** WINGWALL CAP **CURTAIN WALL** WINGWALL CAP **CURTAIN WALL** WINGWALL TOP OF CAP **NOTES** QUANTITY TABLE. **ELEVATION** DRAWN BY: D.A. CANTRELL
CHECKED BY: A.Y. GODFREY
DESIGN ENGINEER OF RECORD: N.A. PIERCE

DATE: 03/2021
DATE: 10/2022
DATE: 12/2022

SUBSTRUCTURE REPAIR QUANTITY TABLE QUANTITIES END BENT 1 ACTUAL **ESTIMATE** AREA AREA VOLUME VOLUME SHOTCRETE REPAIRS SF 0 AREA AREA SF VOLUME VOLUME CONCRETE REPAIRS 0 LINEAR LINEAR **EPOXY RESIN INJECTION** FΤ AREA AREA EPOXY COATING 506.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 2" CLEAR TO SAWCUT. SEE REPAIR DETAILS.

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE REPAIR

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

SHOTCRETE REPAIR AREA

CONCRETE REPAIR AREA

EPOXY RESIN INJECTION

PROJECT NO. 15BPR.124.3 WAKE COUNTY 911084

BRIDGE NO.____



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE REPAIR

END BENT 1

REVISIONS

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

SHEET NO. NO. BY: S4-12 DATE: DATE: TOTAL SHEETS 21