


CONCRETE REPAIR AREA



SHOTCRETE REPAIR AREA

EPOXY RESIN INJECTION (ERI)

AS-BUILT REPAIR QUANTITY TABLE QUANTITIES BENT 4 SPAN D FACE **ESTIMATE** ACTUAL VOLUME AREA VOLUME AREA SF SHOTCRETE REPAIRS CF CF 0.5 CAP 0.3 7.5 COLUMN 14.9 AREA VOLUME **VOLUME** AREA **CONCRETE REPAIRS** SF 0.0 CAP 0.0 LIN. FT. LIN. FT. **EPOXY RESIN INJECTION** CAP 0.0 0.0 COLUMN **EPOXY COATING** SQ. FT. SQ. FT. TOP OF BENT CAP 93.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1" BEHIND REBAR AND MINIMUM OF 2" CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS. SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

> PROJECT NO. 15BPR.125.3 CHEROKEE ___ COUNTY

190009 BRIDGE NO. ___

SHEET 1 OF 2

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

BENT 4 SPAN D FACE

SHEET NO.

S1-22

TOTAL SHEETS 25

DATE:

REVISIONS DATE: DOCUMENT NOT CONSIDERED 1
FINAL UNLESS ALL 1
SIGNATURES COMPLETED 2

SEAL 9

CONEER

Krishna P. Sedan

BY:

DATE : 6/2022

CHECKED BY: S. AGUILA HERNANDEZ