

Groundwater:

Groundwater was never encountered during this investigation. This was likely due to the nature of our small shallow hand auger holes. Furthermore, it should be noted that soils toward the bottom of our 4 and 5 foot deep holes was wet indicating the likelihood that the groundwater table was near.

Respectfully Submitted,

J.E. Beverly, Project Geologist

A handwritten signature in cursive script that reads "J E Beverly". The signature is written in black ink and is positioned below the typed name.