NC DEPARTMENT OF TRANSPORTATION DIVISION OF HIGHWAYS BRIDGE MAINTENANCE UNIT **ATTENTION**

BRIDGE INSPECTION REPORT

INSPECTION TIPE.	Roddine mapeodion		
COUNTY ROBESON	BRIDGE NUMBER	770169 INSPECTION CY	YCLE 2 YRS
ROUTE SR1718	ACROSS 195	-	M.P. 0
OCATION 0.3 MI. E. JCT. US 301		<u>16</u>	
UPERSTRUCTURE REINFORCED CONC	RETE FLOOR ON PR	ESTRESSED CONCRETE GIF	RDERS
UBSTRUCTURE E.BTS:RC CAPS/PRE: 1 at 55.25ft, 2 at 55.00ft, 1 at 55.2 PANS 1@55'3,2@55',1@55'3		T.BTS:RCP&BEAM	
	78° 57' 23.2"	LATITUDE 34° 54' 50.0"	34° 54' 29.8"
RESENT CONDITION FAIR		INVENTORY RATING	HS-17
ISPECTION DATE 07/31/2006		OPERATING RATING	H8-37
RESENT POSTING Not Posted		PROPOSED POSTING	N.P.
OMPUTER UPDATE 4-23-	07	ANALYSIS DATE	4-13-07
OSTING LETTER DATE		SUFFICIENCY RATING	
THER SIGNS PRESENT 2 VERTICAL C	LEARANCE		



No	LOW CL	.EARAN

WEIGHT LIMIT

DELINEATORS

NARROW BRIDGE
ONE LANE BRIDGE

SIGN NOTICE ISSUED FOR No

No

No

NUMBERED REQUIRED

LOOKING EAST

NATIONAL BRIDGE INVENTORY------ STRUCTURE INVENTORY AND APPRAISAL

IDENTIFICATION —			
(1) STATE NAME -NORTH CAROLINA BRIDGE (8) STRUCTURE NUMBER(FEDERAL)		SUFFICIENCY RATING =	78.7
	000000001550169	STATUS = Not Deficient	
INVENTORY ROUTE (ON/UNDER) - ON	131017180		
(2) STATE HIGHWAY DEPARTMENT DISTRICT	6		ODE
(3) COUNTY CODE 155 (4) PLACE CODE		(112)NBIS BRIDGE SYSTEM -	YES
(6) FEATURE INTERSECTED - 195		(104)HIGHWAY SYSTEM NON NHS Route	(
(7) FACILITY CARRIED SR1718		(26) FUNCTIONAL CLASS - Local	09
(9) LOCATION 0.3 MI. E. JCT. US301		(100)STRAHNET HIGHWAY - Not a STRAHNET Route	(
(11)MILEPOINT	0	(101)PARALLEL STRUCTURE - No Parallel Structure	١
	7' 23.2"	(102)DIRECTION OF TRAFFIC - 2-way Traffic	2
	SHARE	(103)TEMPORARY STRUCTURE - Not Temporary	
(99)BORDER BRIDGE STRUCTURE NO		(110)DESIGNATED NATIONAL NETWORK - Not Part of	(
		(20) TOLL On Free Road	3
STRUCTURE TYPE AND MATERIAL		(31) MAINTAIN - State Highway Agency	01
(43) STRUCTURE TYPE MAIN: Prestressed Concrete		(22) OWNER - State Highway Agency	01
TYPE - Stringer Mutlibeam or Girder	CODE 502	(37) HISTORICAL SIGNIFICANCE - Not Eligible	5
(44) STRUCTURE TYPE APPR: Prestressed Concrete			
TYPE - Slab	CODE 501	CONDITION ——— CO	DDE
(45) NUMBER OF SPANS IN MAIN UNIT	3	(58) DECK	5
(46) NUMBER OF APPROACH SPANS	1	(59) SUPERSTRUCTURE	6
(107)DECK STRUCTURE TYPE - Concrete cast-in-place	CODE 1	(60) SUBSTRUCTURE	8
(108)WEARING SURFACE / PROTECTIVE SYSTEM:		(61) CHANNEL & CHANNEL PROTECTION	٨
(A) TYPE OF WEARING SURFACE - Concrete	CODE 1	(62) CULVERTS	N
(B) TYPE OF MEMBRANE - None	CODE 0		
(C) TYPE OF DECK PROTECTION - None	CODE 0		DDE
		(31) DESIGN LOAD H 15	2
AGE AND SERVICE		(64) OPERATING RATING - HS-38	168
(27) YEAR BUILT	1959	(66) INVENTORY RATING - HS-17	131
(106)YEAR RECONSTRUCTED	0	(70) BRIDGE POSTING - Posting Required	5
(42) TYPE OF SERVICE : ON - Highway		(41) STRUCTURE OPEN, POSTED ,OR CLOSED	A
UNDER - Highway	CODE 11	DESCRIPTION - Open, No Restriction	
(28) LANES: ON STRUCTURE 2 UNDER STRUCT	URE 4		
(29) AVERAGE DAILY TRAFFIC	280	APPRAISAL ———— CO	ODE
(30) YEAR OF ADT 2001 (109) TRUCK ADT PCT	6 %	(67) STRUCTURAL EVALUATION	e
(19) BYPASS OR DETOUR LENGTH	6 MI	(68) DECK GEOMETRY	5
GEOMETRIC DATA		(69) UNDERCLEARANCES, VERTI & HORIZ	2
(48) LENGTH OF MAXIMUM SPAN	55 FT	(71) WATERWAY ADEQUACY	N
(49) STRUCTURE LENGTH	221 FT	(72) APPROACH ROADWAY ALIGNMENT	8
(50)CURB OR SIDEWALK: LEFT 1.1 FT RIGHT	1.1 FT	(36) TRAFFIC SAFETY FEATURES	0010
(51) BRIDGE ROADWAY WIDTH CURB TO CURB	24.0 FT	(11)SCOUR CRITICAL BRIDGES	N
(52) DECK WIDTH OUT TO OUT	26.5 FT		
(32) APPROACH ROADWAY WIDTH (W/SHOULDERS)	18.0 FT	PROPOSED IMPROVEMENTS —	
(33) BRIDGE MEDIAN - No Median	CODE 0	(75) TYPE OF WORK - CODE	311
(34) SKEW 97° (35) STRUCTURE FLARED	NO		21 FT
(10) INVENTORY ROUTE MIN VERT CLEAR	99 FT 99 IN		3,000
(47) INVENTORY ROUTE TOTAL HORIZ CLEAR	24.0 FT		8,000
(53) MIN VERT CLEAR OVER BRIDGE RDWY	99 FT 99 IN		0,000
(54) MIN VERT UNDERCLEAR REF Highway	14 FT 08 IN		2007
(55) MIN LAT UNDERCLEAR RT REF Highway	9.2 FT		2025
(56) MIN LAT UNDERCLEAR LT REF -	16.0 FT		
	100 100 mm/s	(90) INSPECTION DATE	
NAVIGATION DATA		(90) INSPECTION DATE 07/31/	/2006
(38) NAVIGATION CONTROL - Not Applicable	CODE N	(92) CRITICAL FEATURE INSPECTION: (93) CFI DATE	
(111)PIER PROTECTION - Not Applicable	CODE	A) FRACTURE CRIT DETAIL - NO A)	
(39) NAVIGATION VERTICAL CLEARANCE	0	B) UNDERWATER INSP - NO B)	
(116)VERT - LIFT BRIDGE NAV MIN VERT CLEAR		C) OTHER SPECIAL INSP NO C)	
(40) NAVIGATION HORIZONTAL CLEARANCE	0	SCOUR	

NATIONAL BRIDGE INVENTORY----- STRUCTURE INVENTORY AND APPRAISAL

(1) STATE NAME -NORTH CAROLINA BRIDGE	77016	SUFFICIENCY RATING =	78.
(8) STRUCTURE NUMBER(FEDERAL)	00000000155016	STATUS = Not Deficient	
INVENTORY ROUTE (ON/UNDER) - UNDER	21100095		
(2) STATE HIGHWAY DEPARTMENT DISTRICT		CLASSIFICATION ———	- CODE
(3) COUNTY CODE 155 (4) PLACE CODE		(112)NBIS BRIDGE SYSTEM -	YES
(6) FEATURE INTERSECTED - 195		(104)HIGHWAY SYSTEM NHS Route	
(7) FACILITY CARRIED SR1718		(26) FUNCTIONAL CLASS - Arterial - Interstate	0
(9) LOCATION 0.3 MI. E. JCT. US301		(100)STRAHNET HIGHWAY - Interstate STRAHNET Route	
(11)MILEPOINT		(101)PARALLEL STRUCTURE - No Parallel Structure	1
(16)LAT 34° 54' 29.8" (17)LONG 78° 57	" 23.2"	(102)DIRECTION OF TRAFFIC - 2-way Traffic	8
(98)BORDER BRIDGE STATE CODE PCT S	SHARE	(103)TEMPORARY STRUCTURE - Not Temporary	
(99)BORDER BRIDGE STRUCTURE NO		(110)DESIGNATED NATIONAL NETWORK - Is Part of	
		(20) TOLL On Free Road	
STRUCTURE TYPE AND MATERIAL		(31) MAINTAIN - State Highway Agency	0
(43) STRUCTURE TYPE MAIN: Prestressed Concrete		(22) OWNER - State Highway Agency	0
TYPE - Stringer Mutlibeam or Girder C	ODE 50	2 (37) HISTORICAL SIGNIFICANCE - Not Eligible	4
(44) STRUCTURE TYPE APPR : Prestressed Concrete			
TYPE - Slab Co	ODE 50		- CODE
(45) NUMBER OF SPANS IN MAIN UNIT		(58) DECK	- 1
(46) NUMBER OF APPROACH SPANS		(59) SUPERSTRUCTURE	
(107)DECK STRUCTURE TYPE - Concrete cast-in-place	CODE	(60) SUBSTRUCTURE	
(108)WEARING SURFACE / PROTECTIVE SYSTEM:		(61) CHANNEL & CHANNEL PROTECTION	1
(A) TYPE OF WEARING SURFACE - Concrete	CODE	(62) CULVERTS	1
(B) TYPE OF MEMBRANE - None	CODE		
(C) TYPE OF DECK PROTECTION - None	CODE	LOAD RATING AND POSTING	- CODE
		(31) DESIGN LOAD H 15	
AGE AND SERVICE		(64) OPERATING RATING - HS-38	168
(27) YEAR BUILT	195	(66) INVENTORY RATING - HS-17	13
(106)YEAR RECONSTRUCTED		(70) BRIDGE POSTING - Posting Required	
(42) TYPE OF SERVICE : ON - Highway		(41) STRUCTURE OPEN, POSTED ,OR CLOSED	F
UNDER - Highway	CODE 1	DESCRIPTION - Open, No Restriction	
(28) LANES: ON STRUCTURE 2 UNDER STRUCTU			
(29) AVERAGE DAILY TRAFFIC	28	AL LIVIONE	- CODE
(30) YEAR OF ADT 2001 (109) TRUCK ADT PCT	6 9		(
(19) BYPASS OR DETOUR LENGTH	6 M		
GEOMETRIC DATA (48) LENGTH OF MAXIMUM SPAN	55.5	(69) UNDERCLEARANCES, VERTI & HORIZ	
(49) STRUCTURE LENGTH	55 F		1
(50)CURB OR SIDEWALK: LEFT 1.1 FT RIGHT	221 F		004
(51) BRIDGE ROADWAY WIDTH CURB TO CURB	24.0 F		0010
(52) DECK WIDTH OUT TO OUT	26.5 F	The state of the s	
(32) APPROACH ROADWAY WIDTH (W/SHOULDERS)	18.0 F		
(33) BRIDGE MEDIAN - No Median	CODE		31
(34) SKEW 97° (35) STRUCTURE FLARED	N	2	221 F
(10) INVENTORY ROUTE MIN VERT CLEAR	19 FT 10 II	* *	\$473,000
(47) INVENTORY ROUTE TOTAL HORIZ CLEAR	47.3 F		\$118,000
(53) MIN VERT CLEAR OVER BRIDGE RDWY	99 FT 99 II		\$710,000
(54) MIN VERT UNDERCLEAR REF Highway	14 FT 08 IN		2007
(55) MIN LAT UNDERCLEAR RT REF Highway	9.2 F	(114)FUTURE ADT 660 (115) YEAR FUTURE ADT	2025
(56) MIN LAT UNDERCLEAR LT REF -	16.0 F		
NAVIGATION DATA		INSPECTIONS —	07/31/2006
(38) NAVIGATION CONTROL - Not Applicable	CODE I	(02) CRITICAL FEATURE INCRECTION :	
(111)PIER PROTECTION - Not Applicable		A) FRACTURE CRIT DETAIL - NO A)	
(39) NAVIGATION VERTICAL CLEARANCE	CODE	B) UNDERWATER INSP - NO B)	
(116)VERT - LIFT BRIDGE NAV MIN VERT CLEAR		C) OTHER SPECIAL INSP NO C)	
THE PART OF THE PROPERTY OF THE PART OF TH		-, -, -, -, -, -, -, -, -, -, -, -, -, -	

BRIDGE I & A FORM1 (90)A

BRIDGE INSPECTION RECORD AND SUMMARY

INSPECTION TYPE BRIDGE NO. 770169

Routine Inspection

COUNTY ROBESON

OVER 195

STRUCTURE TYPE REINFORCED CONCRETE FLOOR ON PRESTRESSED CONCRETE GIRDERS ROUTE ORIENTATION W - E

SPANS 1@55'3,2@55',1@55'3

EVALUATION CODE: 0-2 CRITICAL, 3 & 4 POOR, 5 & 6 FAIR, 7-9 GOOD

INSPECTION ITEM	0 2 011110/1	2,00,110011,0	C 2 00 01 20 1 0 0 0 0		
	GRADES	45. CHANNEL			
marine de tros a tras como tras de como como como como como como como com		& CHANNEL			
(2-05-2)(25-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1		PROT.	110.000		-
TO VISIANUS CONTROL OF THE PROPERTY OF THE PRO			Description of the second	RIP-RAP DIKES ETC	
OTEEL DI ANNO		50 APPROAC			6
				2111011	
	7			CODE	
THE RESERVE OF THE PARTY OF THE			71 E.W	CODE	
		The state of the s	E TO LIVE LOAD		8
					18
15 Sept. 15	7				
		60 REGULAT	ORY SIGN NOTICE	ISSUED	No
	,				No
				0025	No
20110000010110011				IDE WRITE LIP)(MAN HR)	7
	7				0
BI EW BOTH WITH SERVICE					0
	1) 7	OS. TOTAL TIC	ATTIO CONTROL T	IIVIL (IVI/AIT TITO)	v
AND (MOLODES EXOLOG OMADIOTOTOTO	, ,	7	O SI&A GENERAL	CONDITION RATINGS	
SUPER STR (FM 1 (90)B TRUSS) ITEM	59		O. OIGH CENTER I	CONTAINED TO THE PROPERTY OF THE PARTY OF TH	5
	1		RUCTURE	E. O. CANADA STATE	6
		The Server Street Street		ACCOUNTS OF THE PARTY OF THE PA	8
	8				NA
		G. OTIMITEE	G OFFICIAL TOT.	TILMOT	11/1
			71 SIRA FIELD AF	PPRAISAL RATINGS	
	7	a WATERWA		T TOTIONE TOTTINGO	NA
		2 2 2 3 1 2 3 2 3 1 3 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	INCREMISE TO SERVICE OF THE PROPERTY OF THE PR		8
	0	b. Al Fix. RD	VI. ALIOIWILIVI		-
2 OF AN MACHINARY		72 FIELD SCO	DUR EVALUATION		N
IB STR ITEMS ITEM 60 (INCLUDE SCO	UR)	72.11225 000	JOIN EVALUATION		
,		11	SE OF INSP. ACCE	SSIBILITY FOLIPMENT	_
The Constitution and Constitution of the Const					No
	3		002 0, 4, 01(11)	11110	No
			ICK		No
					No
A STATE OF THE SEA PRODUCT OF TH		-			No
	LLS 8				2287
	100				
		SPECIAL INS	PECTION REQUES	TED FOR	
The management of the second s		0, 200, 200	LONGINEGOLO	1207011	
The state of the s		NOTE			
	7	1,012			
	- 1	80 INSPECTE	D BV:	1 1600	
O I O I LIVIO		OU. INSPECTE	.001.	Lynn I thehe	
	INSPECTION ITEM DECK ITEMS SURFACE a. CONCRETE b. TIMBER c. STEEL PLANK d. OPEN GRID a. CONCRETE b. TIMBER c. ALUMINUM d. STEEL HEELGUARDS, PARAPETS, MEDIANS S (ON OR ATTACHED TO STRUCTURE a. STEEL PL OR FINGER b. MISC PREFAB c. COMPRESSION SEAL d. STANDARD JOINTS e. OPEN JOINTS RIS (INCLUDES EXCESS SAND/GRAVE SUPER STR. (FM. 1 (90)B TRUSS) ITEM DINAL BEAMS OR GIRDERS DINAL JOIST OR STRINGERS 'S, X-FRAMES, BRACING & CONN'S EAMS AND CONNECTIONS ASSEMBLIES (INCLUDING MISALIGN) E SYSTEM (ON STRUCTURE) E SPAN MACHINARY IB STR. ITEMS. ITEM 60 (INCLUDE SCO a. ABUT. & INT. BENT CAPS & RISERS b. PILES, POST, SILLS, & BRACING c. BULKHEADS, WING'S, & TIE BACKS a. ABUT. & INT. BENT CAPS b. ABUT. & BENT COL'S BREASTWAL c. ABUT. & BENT CAPS & RISERS d. BACKWALLS, WING'S, RETAIN. WA e. ABUT. & BENT FOOTINGS & SILLS a. ABUT. & BENT FOOTINGS & SILLS a. ABUT. & BENT CAPS & RISERS	INSPECTION ITEM	INSPECTION ITEM	INSPECTION ITEM	DECK ITEMS

Bridge I&A Form 1(82)H

State of North Carolina Dept. of Transportation Division of Highways

FIELD INSPECTION REPORT

Bridge Inspecion & Analysis

Team Leader LEONARD G. FLETCHER

Assisted By TLF

Assisted By	TLF	
Item No.	Grade	
1	7	THE DECK HAS FAIRLY NEW BST SURFACE. IT IS CRACKING LONGITUDINALLY AT THE JOINTS AND A 6 INCH WIDE X 36 INCH LONG POTHOLE HAS RAVELED LOOSE NEAR THE CENTERLINE OF BENT 3.
2a	5	AT SPAN 1 THERE IS A MINOR DIAGONAL CRACK IN BAY 3 AT THE SOUTHWEST CORNER OF THE BRIDGE. ONE TRANSVERSE CRACK IS LEAKING EFFLORESCENCE AT APPROXIMATELY THE 2/3 POINT OF BAY 3. AT SPAN 2, THE CONCRETE CORED SLABS SHOW NO SIGNS OF DISTRESS. THERE IS SPOT EFFLORESCENCE AT RANDOM THROUGHOUT THE SLAB JOINTS. AT SPAN 3, THERE IS HEAVY LEAKAGE AT THE CENTERLINE OF BAY 3, 1/4 OF WAY INTO THE SPAN. SEVERAL LIGHT TRANSVERSE CRACKS IN BAY 1 AND BAY 2 WERE NOTED. AT SPAN 4 THERE ARE 5 TO 6 TRANSVERSE CRACKS LEAKING EFFLORESCENCE AT EACH BAY. OVERALL THE DECK APPEARS TO BE SOUND.
3a	7	THERE IS MINOR SCALING AND COARSE AGGREGATE EXPOSED ON THE RAILS AT SPANS 1, 3, AND 4. SEVERAL CHIPS AND SPALLS HAVE BEEN PATCHED. AT SPAN 2, THE RAILS ARE MUCH NEWER AND ARE GOOD.
4	7	SOME MINOR SCRAPES AND MINOR VOIDS ARE PRESENT. THE CONCRETE IS SCALING, EXPOSING COARSE AGGREGATE.
6d	7	THERE IS A 6 INCH X 3 FOOT SECTION OF MISSING ASPHALT AND ROADWAY AT BENT 3.
7	7	THERE IS A MINOR BUILDUP OF STONE AND DEBRIS ALONG BOTH CURBS.
10	6	AT SPANS 1 AND 4 THE GIRDERS ARE GOOD. SPAN 2 CORED SLABS ARE GOOD. SPAN 3 GIRDERS APPEAR TO HAVE BEEN SCRAPED BY TRAFFIC. THESE SCRAPES APPEAR TO HAVE BEEN PATCHED. GIRDER 3, SPAN 3 HAS A SURFACE CHIP 6-8 INCHES LONG AND 1/2 INCH DEEP 15 FEET AWAY FROM BENT 3.
15	7	THE BEARING ASSEMBLIES IN PRECAST GIRDER SPANS WERE GALVANIZED BUT ARE NOW COVERED WITH RUST ON THE INTERIOR BENTS.
39	7	THERE IS MINOR SETTLEMENT AND UNEVENESS OF JOINTS AND SOME MISALIGNMENT. SEVERAL TRANSVERSE CRACKS ARE MISALIGNED.
50	6	BOTH APPROACHES ARE UNEVEN AND SETTLED SLIGHTLY.
54	8	SLOW TRAFFIC DUE TO SECONDARY ROAD AND SIGHT DISTANCES CAUSES LITTLE VIBRATION.

BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 770169


County ROBESON

Date:

07/31/2006

These Repairs Should Be Made Within Twelve Months From Date Of This Inspection

Function Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
556	Bridge approaches, surfacing or pavement replacement or repair	Man-Hours	40	EAST APPROACH IS UNEVEN AND SETTLED.	
560	Maintenance and repairs to concrete bridge floors	Sq-ft	2900	CRACKS IN THE DECK.	




POTHOLE IN JOINT MEASURING 4 INCHES WIDE X 2 INCHES DEEP X 4 FOOT LONG AT INTERIOR BENT 3



TYPICAL HAIRLINE CRACK OVER INTERIOR BENT 2 JOINT



VEGETATION GROWING OUT OF CRACK IN SLOPE BANK



CRACKING IN SLOPE PROTECTION - SPAN 1



SPALL ON UNDERSIDE - BEAM 1, SPAN 3



EFFLORESCENCE LEAKAGE IN SPAN 3 - 1/4 POINT




CHIP ON SOUTHEAST WINGWALL

BRIDGE MAINTENANCE UNIT

DATA ON EXISTING STRUCTURE **RUN DATE** 04/30/2007 COUNTY: DIV: DIST: STRUCTURE NUMBER: LENGTH: ROBESON 770169 221 FEET FEATURE INTERSECTED: ROUTE CARRIED: SR1718 LOCATED: BRIDGE NAME: 0.3 MI. E. JCT. US301 FUNC. CLASS: SYST.ON: SYST.UNDER: ADT & YR: RAIL TYPE: LT 141 RT 141 09 NFA FA 280 2001 BUILT: BY: PROJ: FED.AID PROJ: **DESIGN LOAD:** SHC 8.13962 H 15 1959 PROJ: LANES: REHAB: BY: ALIGNMENT: SKEW: 0 DBM 4.8060006 TAN. 97 ON 2 UNDER 4 HT. CRN. TO BED: WATER DEPTH: **NAVIGATION:** VC HC 0 FT FT FT RC FLOOR/PPC GDRS.& PPC CORED SLABS SUPERSTRUCTURE: SUBSTRUCTURE: EBTS:RC CAPS/PRESTR.CONC.PILES;INT.BTS:RCP&BEAM SPANS: 1@55'3,2@55',1@55'3 BEAMS OR GIRDERS: SPN.ACD 4LNS PPC GDRS.SPN.B 9LNS.PPC CORED SLAB SECTIONS FLOOR: ENCROACHMENT: DECK (OUT TO OUT): RC&PPCS/2 26.5 FT AWS CLEAR ROADWAY: BETWEEN RAILS: SIDEWALK OR CURB: 24.0 FT 26.3 FT LT 1.1 FT RT 1.1 FT VERT.CL.OVER: VERT.CL.UNDER: HOR.CL.UNDER: 99 FT 99 IN 14 FT 08 IN 47.3 FT INV.RTG.: OPE.RTG.: CONTR.MEMBER: POSTED: SLAB PC HS-17 HS-38 SV 0 TTST 0 DATE SYSTEM: GREEN LINE ROUTE: Primary S.R. Route 5TH OPENING: 2ND OPENING: 3RD OPENING: 4TH OPENING: 16 FT 01 IN I-95NBL REMARKS:

Structure Data Worksheet

County: ROBESON Structure No: 770169 Date: 00/31/2006 Inspected By: LGF




Span No	Span Length	Bearing to Bearing	Comments	
1	55.25	SEE PLANS		
2	55.00	53.67		
3	55.00	SEE PLANS		
4	55.25	SEE PLANS		

Bridge Inspection Field Sketch Looking East Roadway 18.00ft Wide 2 Paved Lanes Left Shoulder 4ft Wide 4.00ft Unpaved Right Shoulder 4ft Wide 4.00ft Unpaved Left Guardrail Right Guardrail

Title APPROACH ROADWAY	YWDTH	Description APPROACH ROADWA	YWDTH
Bridge No:	Drawn By: MSB	Datelana	Eile Namet
Bridge No: 770169	Drawn By: IVISB	Date: 07/07/20	6 File Name: S02860000

Bridge Inspection Field Sketch



.58

7.00ft

Deck Thickness

PPC Girder

PPC Girder

Beam No 1 2

3


Top of Rail to Bottom of Bear	m 6.10	Right Overhang	
Beam Type	Spacing	Comments	
PPC Girder	7.00ft		
PPC Girder	7.00ft		

Left Overhang

Title TYPICAL SECTION		TYPIC, AND	AL SECTION FOR SE	PANS 1, 3
Bridge No: 770169	Drawn By: MSB		Date: 07/07/2006	File Name: S0286000048


Bridge Inspection Field Sketch







No of Slabs	Slab Height	Slab Width	Comments
9	1.50ft	3.00ft	


Title TYPICAL SECTION II		Descri _I	ption AL SECTION FOR SE	PAN 2
Bridge No: 770169	Drawn By: MSB		Date: 07/07/2006	File Name: S0286000050









LOOKING EAST




LOOKING WEST



LOOKING NORTH



LOOKING SOUTH




NORTH ELEVATION



SOUTH ELEVATION



BRIDGE PLAQUE



TYPICAL RAIL - SOUTH SHOWN



TYPICAL CURB - NORTH SHOWN




END BENT 2




TYPICAL BEARING AREA




INTERIOR BENT 3




UNDERSIDE - SPAN 4




UNDERSIDE - SPAN 3




TYPICAL SLOPE PROTECTION




INTERIOR DIAPHRAGM



UNDERSIDE - SPAN 2



TYPICAL UNDERSIDE - SPAN 1



END BENT 1