

28-JAN-2016 12:22 K:\TIPProjects-I\I5788\Structures\Finalplans\250157_plans.dgn tfang

+


CHECKED BY : _

REPAIR QUANTI	ΤΥ Τ.	ABLE			
UNDERSIDE OF DECK REPAIRS					
	ESTIMATE		ACTUAL		
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF	
UNDERSIDE OF DECK & OVERHANGS	1.0	0.3			
BENT DIAPHRAGMS	4.0	1.0			
RC DECK GIRDERS	4.5	1.2			
	ESTIMATE		ACTUAL		
EPOXY RESIN INJECTION	1.5 LF				

VALUES IN CHARTS REPRESENT ESTIMATED UNDERSIDE OF DECK REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN.OF 1" BEHIND REBAR AND MIN.1" CLEAR TO SAWCUT. SEE REPAIR DETAILS.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. FOR BENT DIAPHRAGM AND RC DECK GIRDER REPAIR DETAILS SEE SHEET S-24. REPAIR CONCRETE BENT DIAPHRAGMS AS DIRECTED BY THE ENGINEER.



1/28/2016

PROJECT NO. <u>I-5788</u> <u>CUMBERLAND</u> COUNTY BRIDGE NO. <u>157</u> SHEET 2 OF 5					
STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION					
SUPERSTRUCTURE					
REPAIR					
SPAN B					
NBL					
REVISIONS SHEET NO.					
NO. BY: DATE: NO. BY: DATE: S-26					
1 3 TOTAL SHEETS 72 4					
2 4 72					