



UNDERSIDE OF DECK REPAIRS

SHOTCRETE REPAIRS	ESTI	ESTIMATE		ACTUAL	
	AREA SF	VOLUME CF	AREA SF	VOLUM CF	
UNDERSIDE OF DECK & OVERHANGS					
BENT DIAPHRAGMS					
RC DECK GIRDERS	2.2	0.6			
	ESTIMATE		ACTUAL		
EPOXY RESIN INJECTION	0.0	0.0 LF			

VALUES IN CHARTS REPRESENT ESTIMATED UNDERSIDE OF DECK REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 1" CLEAR TO SAWCUT. SEE REPAIR DETAILS.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR BENT DIAPHRAGM AND RC DECK GIRDER REPAIR DETAILS SEE SHEET S-24.

REPAIR CONCRETE BENT DIAPHRAGMS AS DIRECTED BY THE ENGINEER.

PROJECT NO. I-5788

CUMBERLAND COUNTY

BRIDGE NO. 158

SHEET 1 OF 5

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUPERSTRUCTURE REPAIR SPAN A

SBL

REVISIONS

BY: DATE: NO. BY: DATE: S-37

3 TOTAL SHEETS 72



__ DATE : <u>10/2015</u> __ DATE : <u>11/2015</u>

T.H.FANG

T. FANG

DRAWN BY :

CHECKED BY : _