NOTES REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE. CAP COLUMN FOR CAP REPAIRS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET. CAP COLUMN EPOXY COATING -SPAN B FACE TOP OF BENT CAP NO REPAIRS NOTED FOR BENT 1 DURING INSPECTION BY STRUCTURES MANAGEMENT UNIT. THE CONTRACTOR AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK. └SPAN A FACE TOP OF CAP END VIEW END VIEW SPAN A FACE SPAN B FACE NORTH FACE SOUTH FACE -SPAN A FACE -DocuSigned by: John a. Yammaccone -7BC36E9CFE094EC SPAN B FACE SEAL 3 32492 UNDERSIDE OF CAP 3/21/2016

AS-BUILT REPAIR QUANTITY TABLE REPAIRS BENT 1 ESTIMATE ACTUAL AREA VOLUME AREA VOLUME SF CF SF CF SHOTCRETE REPAIRS 0.0 0.0 0.0 0.0 LN. FT LN. FT EPOXY RESIN INJECTION 0.0 0.0 VALUES IN CHARTS REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN.1" CLEAR TO SAWCUT. DAMAGED AREA

> PROJECT NO. I-5756 HAYWOOD COUNTY 232 BRIDGE NO.

SHEET 1 OF 2

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

BENT 1

REVISIONS SHEET NO DATE: NO. BY: DATE: S-117 DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS 122

DATE : __11/15

DATE : 12/15

W.O.KEITH

J. YANNACCONE

DRAWN BY :

CHECKED BY :