Strain Pole Attachments

NOTE:


- 1. Strap all signal cables to the side of the pole with $\sqrt[3]{4}^{\prime\prime}$ stainless steel straps when the distance between the spanwire attachment clamp and the weatherheads exceeds 3^{\prime} -0 $^{\prime\prime}$.
- 2. Provide minimum two spanwire pole clamps per pole.
- 3. It is prohibited to attach two span wires at one pole clamp.
- 4. For general requirements refer to NCDOT Standard Specifications for Roadway and Structures, January 2012.

PROJECT ID. NO. SHEET NO.


U-4910A Sig.M6

#0#

ס



Attachment of Cable to Intermediate Metal Pole



Metal Pole Grounding Detail For Strain Pole and Mast Arm

