

REPAIR QUANTITY TABLE QUANTITIES REPAIRS BENT 1 ESTIMATE ACTUAL AREA VOLUME AREA VOLUME SF CF SF CF SHOTCRETE REPAIRS CAP (VERTICAL FACE) 0 0 CAP (HORIZONTAL, CORNER) 0 COLUMN (HORIZONTAL FACE) 1.0 0.5 LN. FT EPOXY RESIN INJECTION CAP 0 COLUMN 0 EPOXY COATING TOP OF CAP 106.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

CONTRACTOR SHALL SAW CUT TO A MINIMUM DEPTH OF $^{1\!/}_{2}{}''$ BUT REINFORCING STEEL SHALL NOT BE DAMAGED.

FOR REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

- SHOTCRETE REPAIRS

ERI - EPOXY RESIN INJECTION

I-5765 PROJECT NO. DAVIE COUNTY 75 BRIDGE NO .:



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

SUBSTRUCTURE

BENT 1 (WBL)

12/9/2016

REVISIONS SHEET NO. NO. BY: DATE: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS 35