
TO WEAVERVILLE

+

+

TO MARS HILL



AS-BUILT REPAIR QU	IANT	ITY	ΤA	BLE	
UNDERSIDE OF DECK REPAIRS					
SHOTCRETE REPAIRS		MATE VOLUME		TUAL VOLUME	
UNDERSIDE OF DECK	SF 0.0	CF 0.0	SF	CF	
OVERHANG DIAPHRAGMS	0.0	0.0			
UNDERSIDE OF OVERHANG INTERIOR DIAPHRAGMS	133.3 4.3	83.9 * 2.6 *			
			• • •		
UNDERSIDE EPOXY RESIN INJECTION	ESTIMATE ACTUAL				
VALUES IN CHARTS REPRESENT ESTIMATED UNDERSIDE OF DECK					
VALUES IN CHARTS REPRESENT ESTIMATED UNDERSIDE OF DECK REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE,MINIMUM OF 1" BEHIND REBAR AND MINIMUM 2" CLEARANCE TO SAWCUT. SEE REPAIR DETAILS.					
SEE REPAIR DETAILS.					
UNDERSIDE REPAIR					
DIAPHRAGM REPA	DIAPHRAGM REPAIR				
ERI EPOXY RESIN INJECTION					
CATIONS AND ESTIMATED OUANTITIES ARE GIVEN WITH THE BEST ION AVAILABLE.IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS D. NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE					
D NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY					
SIDE OF DECK AND DIAPHRAGM REPAIRS, SEE ``OVERHANG, DIAPHRAGM AND IL REPAIR DETAILS'' SHEET.					
HAS BEEN INCREASED DUE TO THE POTENTIAL FOR FURTHER ITION SINCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT.					
TION SINCE THE FIELD INSPECTION DI STRUCTURES MANAGEMENT UNIT.					
PROJECT NO.		<u>I-58</u>	<u>39</u> 2		
BUNCO					
		429			
BRIDGE NO		J			
DocuSigned by: SHEET 1 OF 2					
DEPARTMENT		RANSPO	RTAT	ION	
ABC SOLUCIES BURGES					
SEAL 32492 μ ΡΙΔΝ	PLAN OF SPANS				
	SPANS A & B				
74.7 YANNA		2.	-		
-,					
	IONS NO. BY:	DA1		SHEET NO. S-42	
FINAL UNLESS ALL <b>1</b>	3		<u> </u>	TOTAL SHEETS	
SIGNATURES COMPLETED 🙎	4			68	

- D