

.

+

+

1/21

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR REPAIRS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP FACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE THE AREA OF THE CAP BENEATH THE MASONRY PLATES.

FOR EPOXY COATING, SEE SPECIAL PROVISION.

FOR LOCATION OF COLUMN SIDE VIEWS, SEE SHEET 1 OF 3.

DAMAGED AREA

----- EPOXY RESIN INJECTION

			MBE		2 UNTY
JOLUN AMARAMACCONE STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION 78CAEROCEEXAPECTING					
21/2017	BENT 2 COLUMN SIDE VIEWS				
	REVISIONS SHEET NO.				
DOCUMENT NOT CONSIDERED	NO. BY:		NO. BY:	DATE:	S-53
FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		3 4		TOTAL SHEETS 68