

SIDE VIEW SOUTH FACE


ELEVATION EAST FACE

+





PROPOSED REPAIR AREAS

SUBSTRUCTURE SPALL/DELAMINATION



ANTICIPATE CAP
UNDERSIDE REPAIRS







SUBSTRUCTURE CONC. REPAIR - BENT 85

REVISIONS					SHEET NO.	
NO.	BY:	DATE:	N0.	BY:	DATE:	S-104
1			3			TOTAL SHEETS
2			4			
	1	1	NO. BY: DATE:	NO. BY: DATE: NO.	NO. BY: DATE: NO. BY:	NO. BY: DATE: NO. BY: DATE:

DocuSigned by: Sanuel Cullum

19697095675A467

FESSIO

SEAL 043571

GIN EL L. CU