NO REPAIRS NOTED DURING INSPECTION BY STRUCTURES MANAGEMENT UNIT. THE CONTRACTOR AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK. ELEVATION ELEVATION END VIEW SOUTH SIDE EAST SIDE NORTH SIDE REPAIR QUANTITY TABLE - EPOXY COATING QUANTITIES REPAIRS BENT 40 ACTUAL ESTIMATE - SHOTCRETE REPAIR AREA AREA SF VOLUME VOLUME SHOTCRETE REPAIRS ERI - EPOXY RESIN INJECTION PROJECT NO._ CAP (VERTICAL FACE) 0.0 0.0 CAP (HORIZONTAL, CORNER) 0.0 0.0 CARTERET COLUMN 0.0 0.0 PLAN STRUT BRIDGE NO. 0.0 0.0 TOP OF FOOTING FOOTING 0.0 0.0 SHEET 41 OF 50 AREA AREA EPOXY COATING NOTES: FTG (VERTICAL FACE) DEPARTMENT OF TRANSPORTATION 0.0 REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE IF ADDITIONAL REPAIRS FTG (HORIZONTAL, CORNER) 334.4 NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. EPOXY RESIN INJECTION LN.FT LN.FT 21271 CAP SX YOMEE? BENT 40 0.0 COLUMN 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET. STRUT 0.0 | Greg Dickey FOOTING FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. 0.0 2/22/2017^{884546B8CE5B4B6...} REVISIONS FOR "EPOXY RESIN INJECTION", SEE SPECIAL PROVISIONS. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

END VIEW

WEST SIDE

B-5938

68

STATE OF NORTH CAROLINA

RALEIGH

BY:

COUNTY

SHEET NO.

S1-84

DATE:

FOR "EPOXY COATING", SEE SPECIAL PROVISIONS.

P.D.BRYANT / S.T.SANDOR

R.N. WEISZ

DRAWN BY :

CHECKED BY : ____

__ DATE : <u>9/2016</u>

DATE : 9/2016