

PLAN bottom of cap

DRAWN BY :	M.A.LEE	DATE : <u>8/2016</u>
CHECKED BY :	P.BRYANT	DATE : <u>8/2016</u>

END VIEW west side

+

+

## NOTES:


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.


FOR ``SHOTCRETE REPAIRS'', SEE SPECIAL PROVISIONS.

FOR "EPOXY RESIN INJECTION", SEE SPECIAL PROVISIONS.

FOR "EPOXY COATING", SEE SPECIAL PROVISIONS.









REPAIR QUANTITY TABLE							
QUANTITIES							
ESTIMATE		ACTUAL					
AREA SF	VOLUME CF	AREA SF	VOLUME CF				
26.3	13.2						
0	0						
EPOXY RESIN INJECTION			LN.FT				
САР							
	ESTI AREA SF 26.3 0	QUANT ESTIMATE AREA VOLUME SF CF 26.3 13.2 0 0	OUANTITIESESTIMATEACTAREA SFVOLUME CFAREA SF26.313.20000ONLN.FTImage: Colspan="2">Image: Colspan="2" Image: Colspan="2" Image				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

- SHOTCRETE REPAIR

ERI - EPOXY RESIN INJECTION

PROJECT NO. <u>B-5939</u> <u>CARTERET</u> COUNTY BRIDGE NO. <u>6</u> SHEET 54 OF 60								
STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH								
SEAL 21271 BR: CAROLINA SEAL 21271 DocuSigned by: Maga Niakau	SUBSTRUCTURES BENT 53							
Greg Dickey 884E46B8CE5B4B6	REVISIONS SHEET NO.							
	NO. BY:	DATE:	NO. BY:	DATE:	S2-124			
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL	1		3		TOTAL SHEETS			
SIGNATURES COMPLETED	2		4					