

+

+

REPAIR QL		I I I AE	3LE	
BENT 3	QUANTITIES			
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL, CORNER)	0.0	0.0		
EPOXY RESIN INJECTION		LN.FT.	LN.	FT.
САР		0.0		
EPOXY COATING	AREA SF	-		
TOP OF CAP	110.0			
ELEVATION (SPAN D SIDE)	JECT N	10	<u></u>	1 DUNTY
BRI	DGE NO)	469	
		STATE OF NORTH C	AROLINA	
TH CARO	EPARTME	NT OF TRA	ANSPORT	TION
CURCTDUCTUDE				
SUDSIRULIURE				
SEAL 030024		REPAI	R	
The C. Abiline	BENT 3			
- DocuSigned by:				
Aster Abraha		BENI	J	
Docusigned by: Ister Abraha DDA094AED5104FD 8/22/2017	R		5	SHEET NO.
Uster Ubralia DDA094AED5104FD 8/22/2017	R BY: DATE:	EVISIONS	DATE:	SHEET NO. S-9 TOTAL SHEETS