

AS-BUILT REPAIR QUANTITY TABLE						
BENT 7 REPAIRS	QUANTITIES					
	ESTIMATE		ACTUAL			
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	DEPTH FT	VOLUME CF	
CAP (VERTICAL FACE)	106.0	53.0				
CAP (HORIZONTAL, CORNER)	0	0				
COLUMN	0	0				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPÁIR DETAILS.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN REPAIR DETAILS" SHEET.

- SHOTCRETE REPAIR

- CONCRETE REPAIR

	PROJECT NO. <u>I-5889A</u> <u>BUNCOMBE</u> county BRIDGE NO. <u>352</u>				
THE CAROLINE	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH				
DocuSigned by:	BENT 7 Span g side				
Ei Bruch (h 11/16/2017 BA9F91762D7044A					
Road	REVISIONS SHEET NO.				
7607-3073 DOCUMENT NOT CONSIDERE	NO. BY: DATE: NO. BY: DATE: S-66				
FINAL UNLESS ALL SIGNATURES COMPLETED	1 3 TOTAL 2 4 208				
JIONATONES COMPLETED	任 208				