


## Strain Pole Attachments


## NOTE:

- 1. Strap all signal cables to the side of the pole with  $34^{\prime\prime}$  stainless steel straps when the distance between the spanwire attachment clamp and the weatherheads exceeds  $3^{\prime}$ - $0^{\prime\prime}$ .
- 2. Provide minimum two spanwire pole clamps per pole.
- 3. It is prohibited to attach two span wires at one pole clamp.
- 4. For general requirements refer to NCDOT Standard Specifications for Roadway and Structures, January 2012.




**\$** 


Stra



## Attachment of Cable to Intermediate Metal Pole



## Metal Pole Grounding Detail For Strain Pole and Mast Arm



S:\*ITS&SU\*ITS Signals\*Signal Design Section\*Eastern Region\*M Sheets\*2016\*2014 Sig.M6 Std. Fabrication Details—Strain P. jgalloway