

	SPAN C SPAN B
--	------------------

BENT 2 SPAN B FACE	QUAINTITIES			
DENT 2 STAN DIACE	ESTI	MATE	ΛΟΤΗΛΙ	
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA VOLUM SQ.FT. CU.FT	
САР	0.0	0.0		
COLUMN	0.0	0.0		
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME AREA CU.FT. SQ.FT.		VOLUME CU.FT.
САР	0.0	0.0		
COLUMN	0.0	0.0		
EPOXY RESIN INJECTIO	LIN.FT.	LIN.FT.		
САР	3.0			
COLUMN	0.0			
EPOXY COATING	SQ.FT.	SQ.FT.		
TOP OF BENT CAP		209.9		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE ``TYPICAL CAP AND COLUMN REPAIR DETAILS'' SHEET.


## NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.


CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

## SPAN B SPAN C







D	V	Ι	Ε	W

TH CAR

SEAL 031021

-DocuSigned by:

PROJECT NO	<u>158PR.40</u>
BUNCO	MBE COUNTY
BRIDGE NO.	100481

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE REPAIR BENT 2 SPAN B FACE

B04B5A4F2FAD484							
5/29/2019	REVISIONS				SHEET NO.		
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S1-12
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			18