SPAN A

SPAN B

BOTTOM OF CAP @ BENT 1

NOTES


REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR SUMMARY OF QUANTITIES TABLE.

FOR BENT REPAIRS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

EPOXY COATING SHALL BE APPLIED TO TOP FACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIR



CONCRETE REPAIR



__ EPOXY RESIN INJECTION (ERI)

PROJECT NO. 15BPR.45 ____ COUNTY

PENDER

BRIDGE NO. 700219

SHEET 2 OF 2

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> BENT 1 (SPAN B)

REVISIONS SHEET NO. S2-11 NO. BY: TOTAL SHEETS

END OF CAP COLUMN 4 COLUMN 3 COLUMN 2 COLUMN 1 ELEVATION @ BENT 1 (SPAN B)

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

5540 Centerview Drive, Suite 305 Raleigh, NC 27606 Tel. 919-854-0344 Fax. 919-854-0355 NC License No. F-0765

DRAWN BY: R.G. BEAUCHAMP DATE: 3/19
CHECKED BY: J. R. MCROY DATE: 3/19