Strain Pole Attachments

NOTE:


- 1. Strap all signal cables to the side of the pole with $\sqrt[3]{4}^{\prime\prime}$ stainless steel straps when the distance between the spanwire attachment clamp and the weatherheads exceeds 3^{\prime} - $0^{\prime\prime}$.
- 2. Provide minimum two spanwire pole clamps per pole.
- 3. It is prohibited to attach two span wires at one pole clamp.
- 4. For general requirements refer to NCDOT Standard Specifications for Roadway and Structures, January 2018.

SHEET NO. PROJECT ID. NO. I-5711 Sig.M6


\$

ס

\$



Attachment of Cable to Intermediate Metal Pole



Metal Pole Grounding Detail For Strain Pole and Mast Arm

