

AS-BUILT REPAIR QUANTITY TABLE QUANTITIES BENT 1 NORTHBOUND ESTIMATE ACTUAL VOLUME CU.FT. **VOLUME** SHOTCRETE REPAIRS SO.FT. SQ.FT. CU.FT. CAP 18.7 9.4 COLUMNS 3.7 1.9 VOLUME CU.FT. **VOLUME** CONCRETE REPAIRS CU. FT. SQ.FT. SQ.FT. CAP 2.5 1.3 EPOXY RESIN INJECTION LIN.FT. LIN.FT. CAP 0.0 0.0 COLUMNS EPOXY COATING SQ.FT. SQ.FT. TOP OF BENT CAP 0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIR SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR SEE SPECIAL PROVISIONS.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIR AREA




CONCRETE REPAIR AREA



EPOXY RESIN INJECTION (ERI)

PROJECT NO. I-5746C MECKLENBURG COUNTY BRIDGE NO. 590327

SHEET 2 OF 2



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

SHEET NO

S7-13

TOTAL SHEETS

274

REVISIONS DATE: NO. BY: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

8/23/2021

R.L. PUTEK

H.A. LOCKLEAR

DRAWN BY : _

CHECKED BY : _

DATE : <u>05/2021</u>

DATE : 07/2021