

AS-BUILT REPAIR QUANTITY TABLE QUANTITIES BENT 2 SOUTHBOUND ESTIMATE ACTUAL VOLUME CU.FT. **VOLUME** SHOTCRETE REPAIRS SQ.FT. SQ.FT. CU.FT. CAP 14.9 7.5 COLUMNS 7.6 3.8 VOLUME CONCRETE REPAIRS SO.FT. SQ.FT. CU.FT. CU.FT. CAP 0.0 0.0 EPOXY RESIN INJECTION LIN. FT. LIN.FT. CAP 8.5 COLUMNS 0.0 EPOXY COATING SQ.FT. SQ.FT. 212 TOP OF BENT CAP

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING. SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIR AREA

CONCRETE REPAIR AREA

EPOXY RESIN INJECTION (ERI)

PROJECT NO. I-5746CMECKLENBURG COUNTY BRIDGE NO. 590327

SHEET 2 OF 2

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION BENT 2 SOUTHBOUND SPAN C FACE

8/23/2021

SHEET NO **REVISIONS** NO. BY: DATE: S7-19 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS 274

23-AUG-2021 11:59 R:\Structures\FINAL PLANS\Bridge 327\407_037_I5746C_SMU_B2CSB_S7-19_590327.dgn

R.L. PUTEK

HEARBRT LOCKLEAR

DRAWN BY :

_ DATE : <u>05/2021</u>

_ DATE : <u>07/2021</u>